

# Preface

---

The manual may help you to quickly get familiar with the HNC-818 system (hereafter referred to as "system"), providing detailed information about the features, components, commands, usage, operation procedure, programming and beyond. Any updates or modification of the manual is not allowed without the authorization of Wuhan Huazhong Numerical Control Co., LTD (hereafter referred to as "Huazhong NC") under any circumstances. Huazhong NC will not be responsible for any loss caused by pirated copies.

The documentation focuses on the main operations of the system. Limited by space as well as product conceptualization and development, it's impossible for us to explain anything unnecessary or impossible. Hence, what are not described in the manual can be regarded as "IMPOSSIBLE" or "NOT ALLOWED".

The documentation is protected by copyright and contains proprietary and confidential information. No part of the contents of the documentation may be disclosed, used or reproduced in any form, or by any means, without the prior written consent of the copyright holder.

# Contents

<b>Preface .....</b>	<b>i</b>
<b>Contents .....</b>	<b>ii</b>
<b>I Product Overview .....</b>	<b>1</b>
1 Overview .....	2
2 Symbol Description .....	3
<b>II NC Functions .....</b>	<b>4</b>
1 Overview .....	5
1.1 CNC Machine Programming .....	6
1.2 Machine Coordinate System .....	7
1.3 Machine Origin .....	9
1.4 Reference Point of Machine .....	10
1.5 Workpiece Coordinate System and Workpiece Origin .....	11
1.6 Programming Origin .....	12
1.7 Absolute and Relative Coordinate Systems .....	13
2 Preparation (G-Code) .....	14
2.1 G-Codes (T) .....	15
2.2 G-Codes (M) .....	17
3 Program Structure .....	20
3.1 Command Format .....	21
3.2 Program Block Format .....	22
3.3 General Program Structure .....	23
3.4 Program File Name .....	24
3.5 Program File Properties .....	25
3.6 Sub-Programs .....	26
4 Auxiliary Functions .....	27
4.1 M Commands .....	28
4.2 S Commands .....	34
4.3 T Commands .....	35
5 Interpolation Functions .....	38
5.1 Linear Feed (G01) .....	39
5.2 Arc Feed (G02, G03) .....	42
5.3 Cylindrical Helical Interpolation (G02, G03) .....	47
5.4 Specify Imaginary Axis and Sine Interpolation (G07) .....	50
5.5 NURBS Spline Interpolation (NURBS) .....	51
5.6 Thread Cutting (G32) .....	54
5.7 HSPLINE Spline Interpolation (HSPLINE) .....	58

5.8 GOTO Function (G31).....	60
6 Feed Functions.....	63
6.1 Rapid Feed (G00) .....	64
6.2 Unidirectional Positioning (G60).....	65
6.3 Define Feed Speed Unit (G93, G94, G95).....	67
6.4 Exact Stop Verification (G09).....	69
6.5 Cutting Mode (G61/G64).....	70
6.6 Feed Hold (G04) .....	72
6.7 High-Speed High-Precision Mode Selection (M) (G05.1) .....	73
7 Reference Point.....	74
7.1 Return to Reference (G28, G29, G30).....	75
8 Coordinate System.....	78
8.1 Machine Coordinate System Programming (G53).....	80
8.2 Workpiece Coordinate System.....	82
8.3 Define Local Coordinate System (G52) .....	87
8.4 Select Coordinate Planes (G17, G18, G19) .....	89
9 Coordinate Values and Dimension Unit.....	90
9.1 Absolute Commands and Incremental Commands (G90, G91).....	91
9.2 Dimension Unit Selection (G20, G21).....	93
9.3 Polar Coordinate Programming (M) (G16, G15).....	94
9.4 Diameter and Radius Programming (T) (G36, G37) .....	98
10 Tool Compensation Functions .....	100
10.1 Tool Offset (T) .....	101
10.2 Tool Nose Radius Compensation (T) (G40, G41, G42).....	104
10.3 Introduction to Tool Radius Compensation (M) (G40, G41, G42).....	113
10.4 Description of Tool Radius Compensation (M) (G40, G41, G42).....	117
10.5 Tool Length Compensation (M) (G43, G44, G49) .....	126
11 Programming Simplification Functions.....	131
11.1 Mirroring Function (M) (G24, G25).....	132
11.2 Scaling Function (M) (G50, G51).....	136
11.3 Rotation Function (M) (G68, G69).....	139
11.4 Direct Programming based on Blueprint Dimensions (T) .....	142
12 Fixed Cycle.....	146
12.1 Drilling Fixed Cycle for Milling Machines (M).....	147
12.2 Simple Cycle for Turning Machines (T).....	239
12.3 Fixed Cycle for Drilling of Turning Machines (T) .....	255
12.4 Compound Cycle for Turning Machines (T) .....	261
12.5 Special Cases in Fixed Cycle .....	281
13 User Macro Program.....	282
13.1 Variables .....	283
13.2 Operation Instructions.....	290
13.3 Macro Statement.....	292
13.4 Calling Macro Programs.....	297
14 Spindle Functions .....	308

---

14.1 Constant Linear Speed Cutting Control (T) (G96, G97) .....	309
14.2 C/S Axis Switching Function (CTOS/STOC).....	312
14.3 Spindle Synchronization (G116, G117) .....	313
15 Programmable Data Input.....	315
15.1 Programmable Data Input (G10, G11).....	316
16 Axis Control Functions .....	320
16.1 Cycle Function of the Rotation Axis.....	321
16.2 Reference of Grating Ruler with Distance-Code .....	322
17 Other Functions .....	324
17.1 Stop Read -ahead (G08).....	325
17.2 Redefine Rotary Axis Angle Resolution (G115).....	326
17.3 Axis Release (G101) and Axis Obtaining (G102).....	327
17.4 Command Channel Loader (G1030) and Running (G103.1).....	329
17.5 Channel Synchronization (G104) .....	330
17.6 Alarms (G110) .....	332

# **I Product Overview**

# 1 Overview

---

---

This documentation describes the following CNC systems:

CNC System		Abbreviation
HNC-818	HNC-818A Turning Unit (with handheld unit)	HNC-818A-TU-H
	HNC-818A Turning Unit (without handheld unit)	HNC-818A-TU-X
	HNC-818B Turning Unit	HNC-818B-TU
	HNC-818A Milling Unit	HNC-818A-MU
	HNC-818B Milling Unit	HNC-818B-MU

## 2 Symbol Description

---

---

The symbols used in this documentation:

**M**: description valid only in the Milling Unit

**T**: description valid only in the Turning Unit

**IP\_**: combination of any axis, e.g. X\_ Y\_ Z\_ .... Coordinate axis values are in the position of "\_" in actual programming.

## **II NC Functions**



# 1 Overview

---

---

This chapter includes the following sections:

## **1.1 CNC Machine Programming**

## **1.2 Machine Coordinate System**

## **1.3 Machine Origin**

## **1.4 Reference Point of Machine**

## **1.5 Workpiece Coordinate System and Workpiece Origin**

## **1.6 Programming Origin**


## **1.7 Absolute and Relative Coordinate Systems**

## 1.1 CNC Machine Programming

CNC machines conduct workpiece machining based on programming. The programming has a direct impact on the quality of machining, productivity, and lifecycle of cutting tools. A good programmer should have the abilities to master and flexibly use the CNC machine programming.

Programming means that a programmer, by referring to the workpiece machining blueprint and craft, creates program codes and instructions for the workpiece cutting process, machining path, auxiliary operations during the machining such as tool change, cooling, clamp, and clockwise (CW) and counter clockwise (CCW) rotation of spindle, etc. Then the programmer inputs all the programs into the CNC system to run the CNC machine for the workpiece machining. The CNC programming indicates the process to create CNC codes and instructions based on the blueprint and craft, and input them to the CNC system.


The figure below shows the general programming methods and procedure:



## 1.2 Machine Coordinate System

Machine coordinate system is a geometric coordinate system and a fixed coordinate on the machine, which is established to determine the position of the workpiece on the machine, the special position and motion scope of the motion parts. In the machine coordinate system, the workpiece is believed stationary and the tool is in motion. This allows programmers to determine the machining process based on the blueprint without considering the movement of the workpiece and the tool.

Standard machine coordinate system adopts the right hand Cartesian coordinate system. The coordinate is named X, Y, Z which is often referred to as the basic coordinate system shown in the figure below. It follows the right-hand rule: stretching out the right hand thumb, forefinger and middle finger, and keeping them mutually perpendicular; then the thumb points in the positive direction of the X axis (+X), the index finger points in the positive direction of the Y axis (+Y), and the middle finger points in the positive direction of the Z axis (+Z).



The letters A, B, and C are used to define the circumferential feed coordinate which rotates around X, Y, and Z or the axis parallel to the X, Y, and Z. According to the right-hand screw rule, if the thumb points in the direction of +X, +Y, or +Z, the rotation direction of the remaining four fingers point in the direction of +A, +B and +C.

- Define the Z axis

The axis parallel to the spindle is the Z axis. For the machine without a spindle, Z axis is perpendicular to the workpiece clamping surface. The positive direction of Z (+Z) is the direction where the tool moves away from the workpiece.

- 
- Define the X axis


On the machine where the tool rotates, such as milling machine, drilling machine, or boring machine, if the Z axis is horizontal, the X axis is positive in the right direction when looking from the tool (spindle) to the workpiece; If the Z axis is vertical, X axis is positive in the right direction when looking from the spindle to the column. The above are based on the motion of tool relative to workpiece. These directions are relative directions of the tool to the motion workpiece.

On the machine where the tool rotates, such as turning machine or grinding machine, the X axis motion is in the radial direction of the workpiece and parallel to the cross carriage. The direction where the tool moves away from the workpiece rotation center is the positive direction of the X axis.

- Define the Y axis


After defining the positive directions of X and Z axis, you may define the positive direction of the Y axis based on the right-handed rectangular Cartesian coordinate system. That is, within the ZX plane, rotate from + Z to + X, and the right hand-screw should advance along the + Y direction.

This may differ based on the machine types. The figure below shows the coordinate system of a six-axis machining center:



## 1.3 Machine Origin

The Machine Origin is a fixed point on the machine, which is defined by the machine manufacturer. It is a benchmark of workpiece coordinate system, programming coordinate system and reference point. The Milling Machine Origin may differ for different machine manufacturers. Some are defined at the center of the machine work table, and some are defined at the end of the feed travel.




M: machine origin; R: reference point

The origin of the machine is called Machine Origin ( $X=0$ ,  $Y=0$ ,  $Z=0$ ).

## 1.4 Reference Point of Machine


The machine reference point is exactly defined by the machine manufacturer in each feed axis with limit switch. The coordinate values are input into the numerical control system, which are fixed by the mechanical block along each axis. You may return the tool or the work table to the reference point by pressing the **Reference** key on the control panel. Usually in the CNC milling machines and machining centers, the machine reference point is coincident with the machine origin. See the figure below:



## 1.5 Workpiece Coordinate System and Workpiece Origin

The workpiece coordinate system is used to define the position of the workpiece geometry elements (points, straight lines and arcs). The origin of the workpiece coordinate system is the workpiece zero. When you select the workpiece zero, it is recommended to define it in the position where the dimension of the blueprint can be easily converted into coordinate values. For the workpiece zero of milling machines, it is generally defined on one corner of the outer contour of the workpiece; the zero point in the cutting depth direction is mostly defined on the surface of the workpiece.


During processing, after the workpiece is installed on the machine with the clamber, measure the distance between the workpiece origin and the machine origin (defined by measuring the distance between certain base level/lines). This distance is called the workpiece origin offset (the absolute coordinate value of the machine origin in the workpiece coordinate system). See the figure below. Before machining, pre-input the offset value in the CNC system, then during machining, the workpiece origin offset value is automatically attached to the workpiece coordinate system, to ensure accurate axis movement on the CNC machine; therefore, programmers can directly create programs based on blueprint dimensions, without considering the installation position of the workpiece on the machine.



## 1.6 Programming Origin

Generally, for simple workpiece, the workpiece origin is the programming origin. For the workpiece with complex shapes, you need to create several programs or subprograms. To facilitate programming and reduce coordinate value calculation, the programming origin will not be necessarily the workpiece origin, but be defined in a position for easy programming.

The figure below shows the coordinate systems and relative points.






## 1.7 Absolute and Relative Coordinate Systems

There are two modes to describe the amount of movement in the CNC system: the absolute coordinate system and the relative coordinate system.

- The absolute coordinate system refers to the coordinate system where all coordinate points are measured based on a fixed origin.
- The relative coordinate system refers to the coordinate system where the end point coordinates of the motion path are measured based on the starting point.

As shown in the figure below, A, B are two coordinate points. In the absolute coordinate system, the coordinate value of the two points (A, B) are  $(x_A, y_A) = (40, 40)$  and  $(x_B, y_B) = (15, 20)$  respectively; but in the relative coordinate system with the origin of point A, the coordinate value of the point B is  $(x_B, y_B) = (-25, -20)$ .



## 2 Preparation (G-Code)

---

---

### Modal

There are two kinds of G-codes based on their validity:

- Non-Modal G-code: valid only when the G-code is specified, invalid when not specified.
- Modal G-code: saved in the CNC system when it is executed once, and valid until other codes of the same group is executed

### Group

G-codes are divided into several groups according to their functions. 00 group is non-modal G-code and other groups are modal G-code. Multiple G-codes from different groups can be specified in the same program block. If multiple G-codes from the same group are specified in the same block, only the last specified code is valid.

## 2.1 G-Codes (T)

### Attention

After the system is powered on, the G-code marked with the "[ ]" symbol indicates the initial modal of the same group, while the " 『 』 " symbol indicates the equivalent macro name of the G-code.

G Code	Group No.	Function
G00	01	Quick location
[G01]		Linear interpolation
G02		Clockwise (CW) circular interpolation/CW cylindrical helical interpolation
G03		Counter clockwise (CCW) circular interpolation/CCW cylindrical helical interpolation
G04	00	Pause
G07	00	Specify the imaginary axis
G08		Close look-ahead function
G09		Exact stop verification
G10	07	Programmable data input
[G11]		Cancel programmable data input
G17	02	XY plane selection
G18		ZX plane selection
[G19]		YZ plane selection
G20	08	Inch input
[G21]		Metric input
G28	00	Return to the reference point
G29		Return from the reference point
G30		Return to the reference point 2, 3, 4, and 5
G32	01	Thread cutting
[G36]	17	Diameter programming
G37		Radius programming
[G40]	09	Cancel tool radius compensation
G41		Left cutter compensation
G42		Right cutter compensation
G52	00	Local coordinate system settings
G53		Direct machine coordinate system programming
G54.x	11	Extended workpiece coordinate system selection
[G54]		Select workpiece coordinate system 1
G55		Select workpiece coordinate system 2
G56		Select workpiece coordinate system 3
G57		Select workpiece coordinate system 4
G58		Select workpiece coordinate system 5

G59	11	Select workpiece coordinate system 6
G60	00	Single-orientation
[G61]	12	Precise stop mode
G64		Cutting mode
G65	00	Macro non-modal calling
G71	06	Inner (outer) diameter roughing compound cycle
G72		End-face roughing compound cycle
G73		Closed contour compound cycle
G76		Thread cutting compound cycle
G80		Inner (outer) diameter cutting cycle
G81		End-face cutting cycle
G82		Thread cutting cycle
G74		End-face deep-hole drilling cycle
G75		Outer diameter grooving cycle
G83		Axial drilling cycle
G87		Radial drilling cycle
G84		Axially rigid tapping cycle
G88		Radial rigid tapping cycle
[G90]	13	Absolute programming mode
G91		Incremental programming mode
G92	00	Workpiece coordinate system settings
G93	14	Inverse-time feed
[G94]		Feed per minute
G95		Feed per revolution
[G97]	19	Disable constant linear velocity control
G96		Enable constant linear velocity control
G101	00	Axis release
G102		Axis acquisition
G103		Command channel loader
G103.1		Run the command channel loader
G104		Channel synchronization
G108 『STOC』		Change the spindle to the C-axis
G109 『CTOS』		Change the C-axis to spindle
G110		Alarm
G115		Redefine the rotary axis angular resolution

## 2.2 G-Codes (M)

### Attention

After the system is powered on, the G-code marked with the "[ ]" symbol indicates the initial modal of the same group, while the " 『 』 " symbol indicates the macro name of the G-code.

G Code	Group No.	Function
G00	01	Quick location
[G01]		Linear interpolation
G02		CW circular interpolation/ CW cylindrical helical interpolation
G03		CCW circular interpolation/ CCW cylindrical helical interpolation
G04	00	Pause
G05.1	27	High-speed high-precision mode
G07	00	Specifies the imaginary axis
G07.1		Cylindrical surface interpolation
G08		Close look-ahead function
G09		Exact stop verification
G10	07	Programmable data input
[G11]		Cancel programmable data input
G12	18	Enable polar coordinate interpolation
[G13]		Disable polar coordinate interpolation
[G15]	16	Disable polar coordinate programming
G16		Enable polar coordinate programming
[G17]	02	XY plane selection
G18		ZX plane selection
G19		YZ plane selection
G20	08	Inch input
[G21]		Metric input
G24	03	Enable Mirror function
[G25]		Disable Mirror function
G28	00	Return to the reference point
G29		Return from the reference point
G30		Return to the reference points 2, 3, 4, and 5
[G40]	09	Cancel tool radius compensation
G41		Left cutter compensation
G42		Right cutter compensation
G43	10	Positive tool length compensation
G44		Negative tool length compensation
[G49]		Cancel tool length compensation

[G50]	04	Disable the Zoom function
G51		Enable the Zoom function
G52	00	Local coordinate system setting
G53		Direct machine coordinate system programming
G54.x	11	Extended workpiece coordinate system selection
[G54]		Select workpiece coordinate system 1
G55		Select workpiece coordinate system 2
G56		Select workpiece coordinate system 3
G57		Select workpiece coordinate system 4
G58		Select workpiece coordinate system 5
G59		Select workpiece coordinate system 6
G60	00	Single-orientation
[G61]	12	Precise stop mode
G64		Cutting mode
G65	00	Macro non-modal calling
G68	05	Start rotation transformation
[G69]		Cancel rotation transformation
G73	06	Deep-hole drilling cycle
G74		Reverse-tapping cycle
G76		Fine-boring cycle
[G80]		Cancel fixed cycle
G81		Centre-drilling cycle
G82		Drilling cycle with pause
G83		Deep-hole drilling cycle
G84		Tapping cycle
G85		Boring cycle
G86		Boring cycle
G87		Anti-boring cycle
G88		Boring cycle (hand boring)
G89		Boring cycle
G181		Arc groove cycle (Type 1)
G182		Arc groove cycle (Type 2)
G183		Circumference groove milling cycle
G184		Rectangular groove cycle
G185		Circular groove cycle
G186		End-face milling cycle
G188		Rectangular boss cycle
G189		Circular boss cycle
[G90]	13	Absolute programming mode
G91		Incremental programming mode
G92	00	Define workpiece coordinate system


G93	14	Inverse-time feed
[G94]		Feed per minute
G95		Feed per revolution
[G98]	15	Fixed cycle returning to the starting point
G99		Fixed cycle returning to the reference point
G101	00	Axis release
G102		Axis acquisition
G103		Command channel loader
G103.1		Run the command channel loader
G104		Channel synchronization
G108 『STOC』		Change the spindle to the C-axis
G109 『CTOS』		Change the C-axis to spindle
G115		Redefine the rotary axis angular resolution
NURBS		NURBS spline interpolation
HSPLINE		HSPLINE spline interpolation

### 3 Program Structure

---

A program is a set of commands and data transferred to the CNC system.

A program consists of a number of program blocks which follow a certain structure, syntax and format rules. Each block consists of a number of commands. See the figure below:





## 3.1 Command Format

---


A command consists of address characters (command word) and digital numbers with characters (e.g. dimension word) or without characters (e.g. preparatory function character command: G-code). Example: G01 X100 Z-90

Different commands in the program block may have different meaning in different environments. For details, see relevant sections in this documentation.

## 3.2 Program Block Format

A program block specifies the commands executed by a numerical control device.

The block format specifies the syntax of the functional words of each program block. See the figure below:



---

## 3.3 General Program Structure

---

A program must include the start symbol and end symbol.

A program is executed based on the input order of the blocks, rather than the order of block numbers. However, when you write a program, it is recommended to write block numbers in the ascending order.

### Start symbol

The symbol "%" (or "O") must be followed by a number (e.g. % 3256). The program start symbol should be in a separate line, starting at the first line and first character of the program.

### Program end

M02: End the program

M30: End the program and return to the program head

### Comment symbol

The content inside "(" or behind a semicolon symbol (;) is the comment text. Identify ; and ; .

### Single-line command

During G-code programs writing, please be noted that some commands must be in a separate line. Examples: M30, M02, M99, M6T, CTOS, STOC, G16, G15, G05.1, G04

## 3.4 Program File Name

---

Many program files can be saved in the CNC device, and can be written and read in the disk.

### File Name

Oxxxxx; "xxxxx" indicates the file name.

The CNC system calls programs by calling the file name, for machining or editing.

### Naming Rules

the file:

- 26 letters, uppercase or lowercase
- Numbers

The created program file name can contain up to seven characters.

The CNC system may read program files, of which name contains more than seven characters (created externally).

The CNC system reserves the following file names, which cannot be specified for naming the program file.

- USERDEF.CYC
- MILLING.CYC
- TURNING.CYC

Use the following characters to name

## 3.5 Program File Properties

---

Access properties of program files can be set.

### **Editing forbidden**

The currently loaded program can be set to Read-only through interface operation. The file cannot be edited until its property is set to **Write** through interface operation.


In addition, you may also control the program accessibility through the key switch on the project panel. However, the key switch is valid for all programs in the Program Manager. When the key switch is turned off, all programs will become read-only until the switch is turned on.

For detailed description of the program file property control, see section 错误！未找到引用源。 in III Operation.

## 3.6 Sub-Programs

When a fixed machining operation is repeated in a program, you may set it as a sub-program and input it into the program to simplify the programming.

### Execution Process



### Call Sub-program

You may call a sub-program with M98 or G65. For the method of calling a sub-program with M98, see the description of M98 in section 4. For the method of calling a sub-program with G65, see section 13.

## **4    Auxiliary Functions**

---

---

This chapter includes the following sections:

### **4.1 M Commands**

### **4.2 S Commands**

### **4.3 T Commands**

## 4.1 M Commands

---

Auxiliary function commands consist of the address character "M" and digital numbers. It is used to control the motion of the programs, various auxiliary switch of the machine, the start and stop of the spindle, end of the program, etc.

Generally, one program block has only one valid M command. In this system, up to four M commands can be specified in one block (M commands in the same group cannot be specified in the same line).

The M commands (M00, M01, M02, M30, and M99) must be in a separate line. In other words, the program line which contains any of the M commands mentioned above can contain only one M command, and cannot have other commands such as G commands or T commands.

The relationship between the M commands and their functions depends on the specific settings of the machine manufacturer.

### Modal

The M functions include non-modal and modal functions:

- Non-modal M function (valid only in the current block)
- Modal M function (continuously valid)

### Modal Group

Modal M commands are grouped according to different functions. Once the defined modal M command has been executed, it remains valid until it is canceled by other modal M commands in the same group.

The Modal M function group contains a default function which is the initial function when the system is powered on.

### Pre- and Post- M functions

The M function can also be divided into pre-M function and post-M function:

- Pre-M function

Executed before the axis motion specified by the program block.

- Post-M function

Executed after the axis motion specified by the program block.



### 4.1.1 Default CNC Auxiliary Functions

#### M00

##### Pause Program

When the CNC system executes the M00 command, it will pause the execution of the current program. That facilitates the operator to carry out dimensional measurements of the tool and the workpiece, turn around the workpiece, manually change speed, etc.

When the system pauses the program, the feeding on the machine is stopped, and all existing modal information remains unchanged. If you want to continue the follow-up procedures, press the **Start** button on the control panel.

M00 indicates the non-modal post-M function.

#### M01

##### Optional Pause Program

If you activate the **Optional Pause** key on the control panel, the CNC system will pause the current program when it executes the M01 command, to facilitate the operator to carry out dimensional measurements of the tool and the workpiece, turn around the workpiece, manually change speed, etc. When the system pauses the program, the feeding on the machine is stopped, and all existing modal information remains unchanged. If you want to continue the follow-up procedures, press the **Start** button on the control panel.

If you do not activate the **Optional Pause** key on the control panel, the CNC system will not pause the current program when it executes the M01 command.

M01 indicates the non-modal post-M function.

#### M02

##### End program

M02 is created in the last program block of the main program.

When the CNC system executes the M02 command, all the spindle, feed, and coolant functions are stopped and the machining is ended.

After the program is ended by M02, you need to recall the program or press the **Restart** key under the auto machining sub menu, and press the **Start** button on the control panel if you want to re-execute the program.

M02 indicates the non-modal post-M function.

**M30****End program and return (valid only when it is in a separate line)**

The functions of M30 are similar to those of M02, with an additional control function of returning to the program header (%).

After the program is ended by M30, you need to repress the **Start** button on the control panel if you want to re-execute the program.

**M98/M99****Call sub-programs**

If the program contains a fixed sequence or frequently repeated pattern, the sequence or pattern can be stored as a sub-program in the memory to simplify the programming.

A sub-program can be called for a maximum of 10,000 times (L).

A sub-program can be called from a main program.

In addition, a called sub-program can call another sub-program.

Sub-program structure:

%xxxx; Sub-program number

.....; Sub-program content

M99; Sub-program returns

Call sub-program (M98)


M98 P□□□□ LΔΔΔ

□□□□: The number of the called sub-program (Arabic numerals)

ΔΔΔ: The times that the sub-program is called

**Call nested sub-programs**

A main program can call up to six levels of sub-programs. See the figure below:



**Execute M99 in a main program**

If M99 is executed in a main program, then the system returns to the header of the main program and re-execute the program.

**Use M commands to call sub-programs**

Using the M commands to call sub-programs may cause program errors. You may add G80 before M99 to ensure a proper program running. For details, see section 12.5.

### 4.1.2 Auxiliary Functions Defined by PLC

#### M3/4/5

##### Spindle Control

The M03 command starts and rotates the spindle in a clockwise direction (from the positive direction toward the negative direction of the Z axis) at the speed specified in the program.

The M04 command starts and rotates the spindle in a counter clockwise direction at the speed specified in the program.

The M05 command stops the spindle rotation.

The M03 and M04 are modal pre-M functions. M05 is a modal post-M function, which is the default function.

M03, M04, M05 can be canceled by each other.

#### M06 Tool Change

M06 is used to call a tool that will be installed on the spindle from the machining center. The tool will be automatically installed on the spindle when executing this command. Example: M06 T01 can be used to install the 01 tool on the spindle.

M06 indicates a non-modal post-M function.

For the machines with armless type ATC, the tool change process is as follows (e.g. to change the tool 15 on the spindle to tool 01, execute M06 T01.):

1. Move the spindle quickly to the fixed tool change position which has been defined by the commissioning personnel.
2. Directionally rotate the spindle.
3. Rotate the tool magazine to the position (the position of the tool 15 in Group 0).
4. The cylinder drives the tool magazine, and chucks the tool on the spindle.
5. The cylinder releases the tool on the spindle, and blows to clean the spindle.
6. The spindle moves upward, and moves away completely from the tool.
7. The tool magazine rotates to the tool position of tool 01(the tool number of Group 0 in the tool magazine changes to 01).

8. The spindle moves downward, and catches the tool.
9. The cylinder on the spindle clamps the tool.
10. The tool magazine returns to the original position.
11. Release the orientation of the spindle.

**Attention**

M06 must be defined in a separate line.

**M7/8/9****Coolant Control**

M07 and M08 are used to enable the coolant control.

M09 is used to disable the coolant control.

M07 and M08 are modal pre-M functions; M09 is a modal post-M function, which is the default function.

**M64****Workpiece Count**

M64 is used to calculate the cumulative count of completed workpiece.

**M19/M20****Spindle Orientation**

M19 is used for spindle orientation.

M20 is used to cancel the spindle orientation.

**M03/M04**

The spindle can be switched directly from the position mode to speed mode by executing the M03/M04 command, without executing G109.

## 4.2 S Commands

---

### **Directly Define Spindle Speed**

The S command is used to control the spindle rotation speed. The number that follows S indicates the spindle speed in revolution per minute (r/min).

The S command is a modal command, and the S function is valid only when the spindle speed is adjustable.

### **Define Spindle Speed with Code**

In the lathe with mechanical shifting, you may specify a value behind S to input a code signal to the machine, thereby controlling the spindle speed of the machine.

This approach needs to be processed in the ladder graph.

## 4.3 T Commands

---

### Milling System

T commands are used for tool selection. The value that follows T indicates the selected tool number. The relationship between T commands and the tool is defined by the machine manufacturer.

machining center to input a code signal or a strobe signal into the machine, thereby controlling the rotation of the tool magazine to the selected tool, and then wait until the completion of the tool change with the M06 command. For armless type ATC, the M06 and T commands must be written in the same block. During tool change, the tool number (e.g. 15) of Group 0 must be the position of the tool clamped on the spindle in the tool magazine. When you change the tool to another, you need to firstly return the tool to the corresponding tool position in the tool magazine (that is No. 15). Then there should be no tool in the position of No.15, otherwise a collision may occur. The tools in the tool magazine are automatically managed by the system, and cannot be modified. After the machine starts, tool position(e.g. No. 15) facing to the spindle must be the same as tool number of Group 0 in the tool magazine, and there should be no tool in the corresponding tool position (e.g. No. 15).

Therefore, when installing tools to the tool magazine, it is recommended to firstly install the tool on the spindle, then in the MDI mode, run the M and T commands (e.g. M06 T01) to install the tool through the spindle.

Execute a T command on the

### Turning System

T commands are used for tool selection and tool change. The four/six/eight digits that follow T indicates the selected tool number and tool compensation number.

For TXX XX (4 digits), the first two digits indicate the tool number, and the last two digits indicate the tool compensation number.

For TXXX XXX (6 digits), the first three digits indicate the tool number, and the last three digits indicate the tool compensation number.

For TXXXX XXXS (8 digits), the first four digits indicate the tool number, and the last four digits indicate the tool compensation number.

The relationship between the tool and T commands is specified by the machine manufacturer. Please refer to the user manual of the machine provided by the manufacturer.

You may set parameters to define the number (four by default) of digits which follow T code.

- When **P000061** is set to **2**, T code is followed by four digits.
- When **P000061** is set to **3**, T code is followed by six digits.

The same tool may correspond to multiple tool compensations (e.g. T0101, T0102, T0103), and multiple tools may correspond to the same tool compensation (e.g. T0101, T0201, T0301).

Execute the T command to rotate the tool turret and select the defined tool, and at the same time import the tool compensation value (the geometry compensation value of the tool indicates the offset compensation plus the wear compensation) in the tool compensation register. The tool will not move when the T command is executed without being followed by motion commands.

When a program block contains T commands and tool motion commands simultaneously, the T commands are firstly executed, and then the tool motion commands are performed.

*%0012*

*N01 T0101*

*N02 M03 S460*

*N03 G00 X45 Z0*

*N04 G01 X10 F100*

*N05 G00 X80 Z30*

*N06 T0202*

*N07 G00 X40 Z5*

*N08 G01 Z-20 F100*

*N09 G00 X80 Z30*

*M10 M30*

For details about the tool compensation, see the relevant tool compensation section in this documentation.





## 5 Interpolation Functions

---

---

This chapter includes the following sections:

### **5.1 Linear Feed**

### **5.2 Arc Feed**

### **5.3 Cylindrical Helical Interpolation**

### **5.4 Specify Imaginary Axis**

### **5.5 NURBS Spline Interpolation**

### **5.6 Thread Cutting**

### **5.7 HSPLINE Spline Interpolation**

### **5.8 Jump Function**

## 5.1 Linear Feed (G01)

G01 enables a linear feed of the tool from the starting point to the end.

### Format

G01 IP\_ F\_

### Description

Parameter	Description
IP	Under G90command, it indicates the coordinate value of the end point in the workpiece coordinate system. Under G91command, it indicates the relative displacement of the end point to the starting point.
F	Feed speed

G01 enables a linear feed of the tool from the current position to the end point defined by the program block at the speed specified by **F** and in linkage approach.

G01 is a modal code, which can be canceled by G00, G02, G03 or G34.

The feed speed specified by **F** is constantly valid and does not need to be specified in every program block.

The speed along each axis is as follows:

G91 G01 X $\alpha$  Y $\beta$  Z $\gamma$  Ff;

X axis: F $\alpha$  =  $\alpha \times f/L$ ;

Y axis: F $\beta$  =  $\beta \times f/L$ ;

Z axis: F $\gamma$  =  $\gamma \times f/L$ ;

$$L = \sqrt{\alpha^2 + \beta^2 + \gamma^2}$$

### Speed of Rotation Axis

For rotation axis, its feed speed is defined by the linear speed.

During linear interpolation, when the linear axis is  $\alpha$  (e.g. X, unit: mm) and the rotation axis is  $\beta$  (e.g. C, unit: deg), the tangential speed in the  $\alpha/\beta$  Cartesian coordinate system is defined by **F** (mm/min). The speed on the  $\beta$  axis is obtained based on the time calculated from the formula above and then converted to deg/min.

Example: G91 G01 X20.0 C40.0 F300.0;

Assuming the metric input of the C axis 40.0deg is 40 mm


Then the time required should be:

$$\frac{\sqrt{20^2 + 40^2}}{300} \approx 0.14907 \text{ min}$$


The speed on the C axis is:

$$\frac{40 \text{ deg}}{0.14907 \text{ min}} \approx 268.3 \text{ deg/min}$$

### Linear Interpolation




### Rotation Interpolation



**Attention**

After the five-axis RTCP function is enabled, **F** specifies the movement speed of the tool center point in the workpiece coordinate system. During the five-axis machining, due to the join of the rotation axis, the movement speed of the tool center point may not match the actual machine movement speed; therefore, the split-axis speed may exceed the specified maximum speed limit. In this case, the CNC system will reduce the machining speed to ensure the split-axis speed within the defined range.

Use G01 for programming: Linear feed from the point A to B (a straight line from A to B)

**Example**

## 5.2 Arc Feed (G02, G03)

Run the tool to the end along the specified arc direction at a specified plane (G17, G18, G19).

### Format

$$G17 \begin{Bmatrix} G02 \\ G03 \end{Bmatrix} X\_Y \begin{Bmatrix} I\_J\_ \\ R\_ \end{Bmatrix} F\_ \quad \text{Arc interpolation in the XY plane}$$

$$G18 \begin{Bmatrix} G02 \\ G03 \end{Bmatrix} X\_Z \begin{Bmatrix} I\_K\_ \\ R\_ \end{Bmatrix} F\_ \quad \text{Arc interpolation in the ZX plane}$$


$$G19 \begin{Bmatrix} G02 \\ G03 \end{Bmatrix} Y\_Z \begin{Bmatrix} J\_K\_ \\ R\_ \end{Bmatrix} F\_ \quad \text{Arc interpolation in the YZ plane}$$

### Parameter Description

Parameter	Description
G17	Specify arc interpolation at the XY plane
G18	Specify arc interpolation at the ZX plane
G19	Specify arc interpolation at the YZ plane
G02	CW arc interpolation
G03	CCW arc interpolation
X	The amount of movement along the X-axis with arc interpolation or the X-axis coordinate value of the arc end
Y	The amount of movement along the Y-axis with arc interpolation or the Y-axis coordinate value of the arc end
Z	The amount of movement along the Z-axis with arc interpolation or the Z-axis coordinate value of the arc end
R	Arc radius (with signal, "+": inferior arc; "-": excellent arc)
I	The distance from the arc start point along the X-axis to the center of the arc (with signal)
J	The distance from the arc start point along the Y-axis to the center of the arc (with signal)
K	The distance from the arc start point along the Z-axis to the center of the arc (with signal)
F	Feed speed, valid in the modal mode

## Arc Interpolation Direction


Definition of clockwise (CW) and counter clockwise (CCW) direction in each plane: in the Cartesian coordinate system, looking to the XY plane from the positive direction of Z-axis to the negative direction to define the CW and CCW direction of the XY plane; similarly, looking to the ZX plane from the positive direction of the Y-axis to the negative direction to define the CW and CCW direction of the ZX plane; looking to the YZ plane from the positive direction of the X-axis to the negative direction to define the CW and CCW direction of the YZ plane. See the figure below:



## Arc End

Use the position command (X, Y, Z) to specify the arc end.

In the absolute value (G90) mode, the position command (X, Y, Z) specifies the absolute position of the arc end point; in the incremental value (G91) mode, the position command (X, Y, Z) specified the distance from the arc start point to the end point. See the figure below:



## UVW Programming

In addition to the position command (X, Y, Z), you may use the UVW command to specify the arc end.

For the turning CNC system (T Series), when the channel parameter **Enable Programming with UVW** (040033) is set to **1**, you may use UVW instead of XYZ to represent the movement amount (increment) of G02/G03 along the XYZ axis, or use XYZ and UVW for one programming.

Note: Only when the UVW axes are not specified as the motion axis, can UVW be used to specify the arc end.


## Distance from the Start Point to the Arc Center

Use the command (I, J, K) to specify the position of the arc center.

The parameters (I, J, K) indicate the vector components from the start point to the arc center, and it is always incremental value for both G90 and G91.

You need to specify the positive ("+") or negative symbol ("-") for the parameters (I, J, K) based on the direction.

See the figure below:





## Circular Programming


If the position commands (X, Y, Z) are all left blank during programming, the start point overlaps the end point. In this case, the command (I, J, K) specifies a full circle. If **R** is used to specify the arc, it becomes an arc of zero degree. A system alarm will be reported.

### Arc radius

In addition to the command (I, J, K) mentioned above, you may specify the arc center by using the arc radius. The arc is divided into two types:

1. Central angle less than 180 degrees
2. Central angle larger than 180 degrees

Therefore, you need know which arc to be programmed. The two types can be defined by the positive or negative symbols ("+" or "-") of the arc radius (R). See the figure below:




### Attention

- 
- **Parameters related to arc interpolation**  
If the radius difference between the arc start point and end point is greater than the value specified by **CIR INTERPOLATION C-TOL(mm) (000010)**, or (*radius difference between the arc start point and end point*) / *actual radius* is greater than the value specified by **Arc ARC PROG POINT RADIUS TOL(mm) (000011)**, the system will alarm.
- **I/J/K and R are specified simultaneously**  
If "I, J, K" and "R" are simultaneously specified in a non-full circular arc interpolation command, the arc defined by **R** is valid.
- **Specify axis outside the defined plane**  
If the axis is specified outside the defined plane, an alarm will be reported.
-

## Semicircle Programming

When the arc is a semicircle or the central angle is close to 180 degrees, you must use I, J, K to specify the arc center, because a calculation error may be generated due to the rounding errors if you use **R** to specify the arc center.

## Example



As shown in the figure above, the tool path programming is as follows:

### 1. Absolute programming

```
G92 X200.0 Y40.0 Z0;
```

```
G90 G03 X140.0 Y100.0 R60.0 F300.;
```

```
G02 X120.0 Y60.0 R50.0;
```

**Or**

```
G92 X200.0 Y40.0 Z0;
```

```
G90 G03 X140.0 Y100.0 I-60.0 F300.;
```

```
G02 X120.0 Y60.0 I-50.0;
```

### 2. Incremental programming

```
G91 G03 X-60.0 Y60.0 R60.0 F3000.;
```

```
G02 X-20.0 Y-40.0 R50.0;
```

**Or**

```
G91 G03 X-60.0 Y60.0 I-60.0 F300.;
```

```
G02 X-20.0 Y-40.0 I-50.0
```

## 5.3 Cylindrical Helical Interpolation (G02, G03)

In addition to arc interpolation, the G02 and G03 commands can also be used to define helical interpolation by specifying the movement distance of the third axis.

### Format

$$\begin{aligned}
 &G17 \left\{ \begin{matrix} G02 \\ G03 \end{matrix} \right\} X\_Y\_Z \left\{ \begin{matrix} I\_J\_ \\ L\_ \end{matrix} \right\} F\_ \quad \textbf{XY Plane Helical Interpolation} \\
 &G18 \left\{ \begin{matrix} G02 \\ G03 \end{matrix} \right\} X\_Z\_Y \left\{ \begin{matrix} I\_K\_ \\ L\_ \end{matrix} \right\} F\_ \quad \textbf{ZX Plane Helical Interpolation} \\
 &G19 \left\{ \begin{matrix} G02 \\ G03 \end{matrix} \right\} Y\_Z\_X \left\{ \begin{matrix} J\_K\_ \\ L\_ \end{matrix} \right\} F\_ \quad \textbf{YZ Plane Helical Interpolation}
 \end{aligned}$$

### Parameter Description

G17	Specify arc interpolation at the XY plane
G18	Specify arc interpolation at the ZX plane
G19	Specify arc interpolation at the YZ plane
G02	CW arc interpolation
G03	CCW arc interpolation
X	The amount of movement along the X-axis with arc interpolation or the X-axis coordinate value of the arc end
Y	The amount of movement along the Y-axis with arc interpolation or the Y-axis coordinate value of the arc end
Z	The Z-axis coordinate value in absolute programming, or the the Z-axis increment of the end point relative the start point(even if L command is programmed)
R	Arc radius (with signal: "+": inferior arc; "-": excellent arc)
I	The distance from the arc start point along the X-axis to the center of the arc (with signal). The value of height variation for a spiral circle at YZ plane in conic interpolation.
J	The distance from the arc start point along the Y-axis to the center of the arc (with signal)

Parameter	Description
-----------	-------------

K	The distance from the arc start point along the Z-axis to the center of the arc (with signal).
F	Feed speed, valid in the modal mode
L	Helical rotation number (positive number without a decimal point)

### Rotation Direction


For the rotation direction of helical interpolation, refer to the arc direction projected on a two-dimensional plane.

### Circular Programming

If the position commands (X, Y, Z) are all left blank during programming, the start point overlaps the end point. In this case, the command (I, J, K) specifies a full circle. If **R** is used to specify the arc, it becomes an arc of zero degree. A system alarm will be reported.

### Example

The figure below shows the helical machining:



#### 1. Absolute programming

*X30 Y0 Z0*

*G90 G03 X0 Y0 Z50 I-15 J0 K0 L10 F3500*

*M30*

**2. Incremental programming**

*G91 G03 X-30 Y0 Z50 I-15 J0 K0 L10 F3500*

*X30 Y0 Z0*

*M30*

## 5.4 Specify Imaginary Axis and Sine Interpolation (G07)

### Format

G07 IP\_

Parameter	Description
IP	Specify axis: <ul style="list-style-type: none"> <li>0: imaginary axis</li> <li>1: real axis</li> </ul>

### Description

If an axis is specified as an imaginary axis, this axis is only used for interpolation calculation without any motion. For example, if the G07 X0 command specifies the X axis as the imaginary axis, then the X axis will not move until the G07 X1 command is executed.

### Sine Interpolation


G07 can be used for a sine interpolation. For example, before the helical interpolation, if an axis used for arc interpolation is specified as the imaginary axis, then the helical interpolation becomes the sine interpolation.

### Attention

If you want to cancel the imaginary axis specification, you only specify the imaginary axis as a real axis, e.g. executing G07 X1.

### Example

Use G03 for programming the sine curve as below:



## 5.5 NURBS Spline Interpolation (NURBS)

You may conduct NURBS spline interpolation by specifying three parameters (IP, W, K) of the NURBS curve.

### Single Spline NURBS Format

**NURBS P\_K\_IP\_W\_F\_;**

Parameter	Description
P	Order of NURBS curve; Only cubic spline interpolation is supported, where the value of <b>P</b> is <b>4</b> .
K	Node
IP	Control point coordinate
W	Weight
F	Feed speed

### Cancel Interpolation

NURBS indicates modal of Group 01. You may cancel the NURBS interpolation modal by specifying G01 or G00.

### Curve order

**P** is used to specify the order of the NURBS curve:

P=4, indicates cubic NURBS curve;

P is modal address word, which will be valid until it is changed or other modal commands in group 01 are specified.

### Node

During NURBS interpolation, you must specify the first control point as the start point and the last control point as the end point.

In addition, use the following format to specify the node of the first program block:

- Single-spline:

NURBS P4 K:0,0,0,0,1: X1 Y0 Z0

- Dual-spline:

NURBSB P4 K:0,0,0,0,0.5: Q:10,0,0,38.28,0,28.28: W1F60

**Weight**

Weight indicates the weight value of the control point specified in the same program block. If it is not specified, the default value is **1.0**.

**Compensation**

In the NURBS curve interpolation mode, you cannot use tool radius compensation.


**Description**

Single-spline NURBS interpolation is generally used for three-axis small line interpolation.

Dual- spline NURBS interpolation is generally used for five-axis small line interpolation.

**Example of Single-spline interpolation**

The figure below shows the single-spline NURBS interpolation for a full-circle (R=50mm):



```
%0001
```

```
G54
```

```
G90G17F500G64
```

```
G01x0y0z0
```

```
NURBS P4 K:0.0,0.0,0.0,0.0,0.5: X0.0Y0.0Z0.0 W1.0
```

```
K0.5 X0.0000 Y100.0 W0.3333
```

```
K0.5 X100.0 Y100.0 W0.3333
```



<i>K1.0</i>	<i>X100.0</i>	<i>Y0.0</i>	<i>W1.0</i>	<i>K1.0</i>	<i>X0.0</i>	<i>Y-100</i>	<i>W0.3333</i>
<i>K1.0</i>	<i>X100</i>	<i>Y-100.0</i>		<i>K1.0</i>	<i>X0.0</i>	<i>Y0.0</i>	<i>W1.0</i>
	<i>W0.3333</i>			<i>M30</i>			

## 5.6 Thread Cutting (G32)


The feed operation coincides with the spindle rotation, which different kinds of threads can be processed, such as variable pitch screw, multi-thread, etc.

### Format

**G32 X\_Z\_F\_P\_R\_E\_**

Parameter	Description
X Z	Thread end point coordinate (G90). Relative distance of the thread end point away from the start point (G91).
F	Metric thread pitch (along the long axis).
P	Angle of the thread start point
R	Specify the retreat of tailstock along the Z axis in the incremental mode. If the tool withdrawal groove is not required, the parameter signal cannot be specified.
E	Specify the retreat of tailstock along the X axis in the incremental mode. If the tool withdrawal groove is not required, the parameter signal cannot be specified.


### Constant Pitch



### Multi-Thread

You may process multi-threads by specifying the thread start angle **P**. For example, you may set **P** to 180 degrees to process double threads.

See the figure below:



### Retreat of tailstock

tailstock by specifying the **R** (retreat along the Z axis) and **E** (retreat along the X axis) parameters, of which values are specified in the incremental mode for both absolute and incremental programming. The positive value indicates the retreat along the positive direction of the Z/X axis, while the negative value indicates the retreat in the negative direction of the Z/X axis. If no **R** or **E** value is specified, there will be no retreat function.

According to the thread standard, **R** is generally specified as double pitch, while **E** is specified as the height of the thread.


Note: If the retreat of tailstock is specified, the thread cutting direction must be coordinated with the **R/E** direction to avoid damage to the thread. For example, if the thread cutting is towards the negative direction of the Z axis, then the value of **R** must be negative; otherwise, there may be damage to the processed thread.

You may define the retreat of  
**Attention**

1. Do not change the feed rate or spindle override during thread cutting.
2. It is dangerous to stop the feed of the thread cutting tool without stopping the spindle as it may suddenly increase the cutting depth; therefore, the function of feed hold is invalid during thread cutting. The feed hold is valid only during the non-thread machining.
3. When thread cutting is conducted in the single block mode, the tool will stop at the beginning of the first block where no threading cutting is specified.
4. During thread cutting, the work mode cannot be changed from the auto mode into manual, incremental or reference mode.

**Example**

The figure below shows the cylindrical thread programming. Thread lead: 1.5 mm; each cut depth (diameter value): 0.8 mm, 0.6 mm, 0.4 mm, 0.16 mm.



%3316

N1 T0101 (Set coordinate system, and select No. 1 tool)

N2 G00 X50 Z120 (Move to the start point position)

N3 M03 S300 (Rotate the spindle at 300 r/min)

N4 G00 X29.2 Z101.5 (Move to the start point, acceleration stage: 1.5 mm, cut depth: 0.8 mm)

N5 G32 Z19 F1.5 (Thread cutting to the end point, deceleration stage: 1 mm)

N6 G00 X40 (Quick retreat along the X axis)

N7 Z101.5 (Quick retreat to the start point along the Z axis)

N8 X28.6 (Fast forward to the start point along the X axis, cut depth: 0.6 mm)

N9 G32 Z19 F1.5 (Cut thread to the end point)

N10 G00 X40 (Quick retreat along the X axis)

N11 Z101.5 (Quick retreat to the start point along the Z axis)

N12 X28.2 (Fast forward to the start point along the X axis, cut depth: 0.4 mm)

N13 G32 Z19 F1.5 (Cut thread to the end point)

*N14 G00 X40* (Quick retreat along the X axis)

*N15 Z101.5* (Quick retreat to the start point along the Z axis)

*N16 U-11.96* (Fast forward to the start point along the X axis, cut depth: 0.16 mm)

*N17 G32 W-82.5 F1.5* (Cut thread to the end point)

*N18 G00 X40* (Quick retreat along the X axis)

*N19 X50 Z120* (Back to the tool setting position)

*N20 M05* (Stop the spindle)

*N21 M30* (End the main program and reset)

## 5.7 HSPLINE Spline Interpolation (HSPLINE)

HSPLINE is the abbreviation of Hermite SPLINE. The Hermite interpolation function can also improve the machining results of small lines, making the surface fairing. Different from the NURBS curves, the Hermite curve passes through the control point. The CNC system may conduct spline interpolation by specifying the control point and vectors of the Hermite curve.

### Format

**HSPLINE P\_X\_Y\_Z\_I\_J\_K\_F\_**

Parameter	Description
X Y Z	Control point coordinates. Note: The coordinate position must be the same as the end point position of the previous line.
I J K	Vector of the control point
F	Hermite curve order

### Cancel Interpolation

HSPLINE indicates modal of Group 01. You may cancel the HSPLINE interpolation modal by specifying G01 or G00.

### Curve order


**P** is used to specify the order of the HSPLINE curve: P must be set to **3**.

### Compensation

Tool radius compensation cannot be used for HSPLINE interpolation.

### Example

Use cubic Hermite spline interpolation for the curve as below:



*%0001*

*G54G0X0Y0Z0*

*G90G17 F1000G64*

*X0.005y-0.987z0.04*

*HSPLINE P3 X0.005 Y-0.987 Z0.040 I1.000 J-0.026 K-0.002; Q1*

*X0.748 Y-0.727 Z0.027 I0.756 J0.655 K-0.016; Q2*

*X1.049 Y-1.097 Z0.023 I0.967 J0.256 K-0.011; Q3*

*X1.249 Y-0.727 Z0.053 I0.497 J0.866 K0.050; Q4*

*M30*

## 5.8 GOTO Function (G31)

---

G31 is followed by axes, the motion path of which is similar to the G01 linear interpolation. When G31 command is executed, if an external GOTO signal is input, the execution will be interrupted and the system proceeds to execute the next block instead.

You may use the GOTO function if the processing end point is not specified in the program, but specified with the signal from the machine, e.g. grinding. The GOTO function can also be used to measure the dimension of the workpiece.

### Format

G31 L\_IP\_; The number behind L indicates the trigger point number, which must be the same as that in PLC.

G31: non-modal G-code

### Description

The coordinate values when the GOTO signal is connected can be used in user macro-program because they are stored in the axis macro variables of user macro programs. The axis macro variables start from **60000**, and each axis uses 100 macro variables. For example, if the X axis number is **0**, the X-axis variables start from **60000** to **60099**; if the Y axis number is **1**, the Y-axis macro variables starts from **60100** to **60199**; similarly, the Z axis macro variables start from **60200** to **60299**. Macro variables related to measurement are defined as follows:

#60010-60011: The command position of the axis 0 on the machine when receiving measurement signals

#60012-60013: The real position of the axis 0 on the machine when receiving measurement signals

#60014-60015: The position of the No.2 encoder on the axis 0 when receiving measurement signals


#60016: The speed on the axis 0 when receiving measurement signals

#60017: The current of the axis 0 when receiving measurement signals

### Example

If there is a X7.6 signal, then go to the next block.






1. The program block after G31 is incremental command.

*G31L1G91X100.0F100;*


*Y50.0;*



2. The program block after G31 is absolute command to one axis.

*G31L1G90X200.0F100;*


*Y100.0;*



3. The program block after G31 is absolute command to two axes,

*G31L1G90X200.0F100;*

*X300.0Y100.0;*



## **6 Feed Functions**

---

---

This chapter includes the following sections:

### **6.1 Rapid Feed**

### **6.2 Unidirectional Positioning**

### **6.3 Define Feed Speed Unit**

### **6.4 Exact stop verification**

### **6.5 Cutting Mode**

### **6.6 Feed Hold**

### **6.7 High-Speed High-Precision Mode Selection**

## 6.1 Rapid Feed (G00)

In the G00 mode, the tool moves at the rapid feed speed to the specified position.

### Format

G00 IP\_

Parameter	Description
IP	In the absolute value mode (G90): the coordinate value of the end point in the workpiece coordinate system. In the incremental value mode (G91): the relative movement amount of the end point away from the start point.

### Description


The rapid motion speed of each axis in the G00 command is defined by the axis parameter **Rapid Traverse Feed Rate (100034 axis 0)**. You cannot specify it with the **F** command.

G00 is generally used for quick positioning before processing or fast tool retreat after machining. In the positioning mode initiated by G00, the tool speeds up to the specified speed from the start point of the block and slows down when close to the target position. After reaching the end point, the CNC system will execute the next block.

The rapid traverse speed can be adjusted with the override ratio button on the control plane.

G00 is modal code, of which functions can be canceled by G01, G02, or G03.

## 6.2 Unidirectional Positioning (G60)



### Format

#### G60 IP\_

Parameter	Description
IP	In the absolute value mode (G90): the end point position in unidirectional positioning. In the incremental value mode (G90): the distance from the current position to the end point.

### Description

In order to eliminate the influence of backlash, you may control the axis to conduct positioning in one direction.

As shown in the figure, conduct positioning in a common mode when the motion direction is the same as the positioning direction; when the motion direction is different from the positioning direction, move the tool in the motion direction, then move one offset in the positioning direction. Then the tool reaches the end point.

### Offset Value

When running G60, you also need to specify the offset value and the offset direction. The positive and negative values of the following parameters indicate the offset directions of G60.

Axis	Parameter Index	Description
1 <sup>st</sup> axis	Parm100030	G60 offset vector of the first axis.
2 <sup>nd</sup> axis	Parm101030	G60 offset vector of the second axis.
3 <sup>rd</sup> axis	Parm102030	G60 offset vector of the third axis.

**Attention**

1. Conduct unidirectional positioning even if the tool movement is zero.
2. The specified overshoot in unidirectional orientation must be greater than the backlash of the corresponding shaft; otherwise you cannot completely eliminate the backlash during unidirectional orientation.

**Example**

(Set **100030** to **10**, G60 *end point - parameter value of 10X030 = G60 center point*)

*%0008*

*G54*

*G00X20*

*G60X0*; move to X-10, and then move to 0

*M30*

## 6.3 Define Feed Speed Unit (G93, G94, G95)

During workpiece machining, the feed speed of linear interpolation (G01) and circular interpolation (G02, G03) are defined by the value after **F**. The feed speed unit is defined by G93, G94, and G95.

### 1. M: three commands

- Feed per minute (G94)

After **F**, specify the tool feed per minute.

- Feed per revolution (G95)

After **F**, specify the tool feed per revolution around the spindle.

- Inverse-time feed (G93)

After **F**, specify **FRN**

### 2. T: two commands

- Feed per minute (G94)

After **F**, specify the tool feed per minute.

- Feed per revolution (G95)

After **F**, specify the tool feed per revolution around the spindle.

### Format

**G93**; Specify FRN feed

**G94**; Specify feed per minute

**G95**; Specify feed per revolution

### G94

#### Feed per minute

In the G94 mode (feed per minute), **F** specifies the tool movement amount per minute. Unit: mm/min (G21) or in/min (G20)

### G95

**Feed per revolution**

G95 specifies the tool movement amount per revolution around the spindle as the feed rate F. Unit: mm/r (G21) or in/r (G20)

Only when the spindle is configured with an encoder, can G95 be specified.

**G93****FRN feed**

FRN feed is achieved by specifying the time which is taken to execute the current program block.

**Attention**

1. G93, G94, and G95 are modal functions, which can be canceled by each other. G94 is the default modal.
2. In the FRN feed mode, if the calculated speed exceeds the maximum cutting speed, the actual speed is limited to the maximum cutting feed speed.
3. G93 must be programmed in a separate line.

**Example**

*%0008*

*G54X0Y0Z0; the F value in each mode below is **1000**.*

*G94*

*G01X50F1000*

*M3S500*

*G95*

*G01Y50F2*

*G93*

*G01Z50F20; movement distance x **F** = final feed speed*

*M30*



## 6.4 Exact Stop Verification (G09)

---

Control the tool stop exactly at the end point of the program block.

### Format

**G09;** specified in a separate line

### Description


Stop exactly at the end point of the program block including G09 before proceeding to execute another program block. The function is used for machining sharp corners.

G09 is non-modal command, which is valid only in the defined program block.

The difference between G09 and G61 is that G09 is valid in program blocks but G61 is valid in the modal mode.

## 6.5 Cutting Mode (G61/G64)

The cutting mode is used to control feed speed.



### Description

#### 1. G61: exact stop mode

In each block after G61, the programmed axis must exactly stop at the end point of the block, and then proceed to the next block.

#### 2. G64: continuous cutting mode

In each block after G64, the programmed axis executes the next block right after it begins to slow down (not reaching the programmed end point). However, in the block including position commands (G00, G60) or exact stop verification command (G09), or in the block excluding motion command, the position verification will be executed only when the feed speed slows down to zero.

### Attention


1. The programming contour of G61 is consistent with the actual contour.
2. The difference between G61 and G09 is that G61 is modal command.
3. The programming contour of G64 is inconsistent with the actual contour. Its difference depends on the value of **F** and the angle between the two paths. The greater the value of **F** is, the greater the difference is.
4. G61 and G64 are modal commands, which can be canceled by each

other.


5. After running small line programs and changing from the automatic mode to the single block mode, the G64 command will execute the splines in the look-ahead buffer, and then execute program blocks in single block mode; therefore, a number of program blocks may be continuously executed in a single block. Small lines program includes programs generated by CAM and programs generated by macro operation.

### Example

- 1: Create a program for the machining as shown in the figure below: The programming contour must be consistent with the actual contour.



- 2: Create a program for the machining as shown in the figure below: no stops between program blocks.



## 6.6 Feed Hold (G04)

---

During automatic running, you may use G04 to pause the tool feed. The system will automatically execute the ongoing program blocks after the specified time is expired.

### Format

**G04 P\_;** Feed hold

**G04 X\_;**

X: Unit: second

P: Unit: millisecond

### Attention

1. The minimum feed hold time is specified as an interpolation cycle (Parm000001). If the specified time is less than an interpolation cycle, it will be executed as an interpolation cycle.
2. The value after **X** cannot be greater than **2000**; otherwise, the system will not execute the program.

## 6.7 High-Speed High-Precision Mode Selection (M) (G05.1)

The command is used to switch among different machining modes to meet different requirements.

### Format

**G05.1 Q\_;** Specify machining mode

.....

**G05.1 Q0;** Default mode

Parameter	Description
Q_	Select a machining mode 0, 1, 2 and 3, which can be switched by G05.1Q_.

### Description

Command	Description
G05.1Q0	Default mode; focuses on the balance between efficiency and precision
G05.1Q1	High-precision mode; focuses on the machined surface and dimensional accuracy.
G05.1Q2	High-speed and high-precision mode; focuses on processing smoothness and the balance between the efficiency and precision.
G05.1Q3	High-speed mode; focuses on the processing efficiency, improves the processing speed for free curve.

### Attention

G05.1Q\_ must be specified in a separate line.

## 7 Reference Point

---

---

Reference point is a fixed position on the CNC machine, based on which, the workpiece coordinate system can be established, or the tool change and other fixed operations can be conducted.

The chapter includes the section below:

### 7.1 Return to Reference Point

## 7.1 Return to Reference (G28, G29, G30)


Reference point is a fixed point on the machine. There are a total of five reference points: the first, the second, the third, the fourth and the fifth reference points. You may use the reference command to easily move the tool to the reference points. The reference points can be used as the tool change position.

Take the axis 0 as an example. You may set five reference points in the machine coordinate system by setting the reference point position parameters (100017, 100021, 100022, 100023, and 100024).

### Execution procedure

When you execute the command of returning to the reference point, the tool automatically passes through the intermediate point to reach the reference point rapidly. At the same time, the specified intermediate point is saved in the CNC system, and the tool automatically passes through the intermediate point and moves along the specified axis to the end point.

The figure below shows the process that a tool returns to the reference point:



### Automatically home to reference point

**G28 IP\_;** Return to the first reference point

**G30 P2 IP\_;** Return to the second reference point (P2 can be omitted )

**G30 P3 IP\_;** Return to the third reference point

**G30 P4 IP\_;** Return to the fourth reference point

**G30 P5 IP\_;** Return to the fifth reference point

Parameter	Description
IP	In the absolute value mode (G90), specify the absolute position of the intermediate point; in the relative value mode (G91), specify the distance from the intermediate point to the start point. You do not need to calculate the specific movement amount from the intermediate point to the reference point.

The coordinate value specified by **IP** is the value in the workpiece coordinate system. Only the axis specified with the

intermediate point can move when the command of automatic returning to reference is executed.

### G29 IP\_;

The coordinate value specified by **IP** is the value in the workpiece coordinate system.

### Return from reference point

The intermediate point is that of G28, G30 specified previously.

The table below describes the running mode for the relative value (G91):


Execute program	Workpiece coordinate system x, y, z
G54X0Y0Z0	0,0,0
G91G28X10Y10Z10	10,10,10----->0,0,0
X100	100,0,0
Y100	100,100,0
Z100	100,100,100
G29X10Y10Z10	10,10,10----->20,20,20
	Move to the intermediate point of G28, and then execute G91

Parameter	Description
IP	In the absolute value mode (G90), specify the end point; in the relative value mode (G91), the intermediate point of G29 must be that of G28 specified previously. To execute G29, you may execute G91 based on the intermediate point of G28.



**Attention**

G29 can be executed only after G28 or G30 has been executed; otherwise, the execution may be abnormal as there is no intermediate point.

**Example**

*%I234*

*G54*

*G00 X200Y300*

*G28 G90 X1000.0 Y500.0*; program from point A to B. Move through the intermediate point B, and to the reference point R.

*T6*;

*M06*; change tool at the reference point


*G29 X1300.0 Y200.0*; program from point B to C. Move from the reference point R, through the intermediate point B, and to the end point specified by C

*M30*


## 8 Coordinate System

reach a predefined position, which is defined based on the coordinate values within a coordinate system. The coordinate value is specified by program axis value, so as to process workpiece according to the specific program.

- Milling machine (use X40.0 Y50.0 Z25.0 to define the tool position)



- Turning machine (use X50.0 Z40.0 to define the tool position)



This CNC system provides the following coordinate systems:

- Machine coordinate system
- Workpiece coordinate system
- Local coordinate system

During the machining, the tool may

-

This chapter includes the following sections:

**8.1 Machine Coordinate System Programming**

**8.2 Define Workpiece Coordinate System**

**8.3 Define Local Coordinate System**

**8.4 Select Coordinate System Plane**

## 8.1 Machine Coordinate System Programming (G53)

There is a fixed mechanical point on the machine, which can be used as a datum point of the machine. It is called as the machine origin, of which position is defined by Zero Block or Grating Zero point. This point is used as the origin to establish the coordinate system which is called the machine system.

After power on, you may establish the machine coordinate system by manually returning to the reference point. Once the machine coordinate system is established, it remains unchanged before cutting off the power supply.

### Format


**G53 IP\_;**

Parameter	Description
IP	Target position in the machine coordinate system

### Define Machine Coordinate System

Before calling G53, the machine coordinate system must be established by returning to the reference point.

The reference point does not coincide with the origin of the machine coordinate system. The figure below shows the relationship between them:



### Attention

1. G53 is a non-modal command, which must be specified at the current line when conducting the machine coordinate programming.

2. The target position specified by G53 cannot be relative programming. You must use absolute command for programming.
3. The compensation functions such as tool radius compensation, tool length compensation, and cutter radius compensation are cleared when the G53 command is specified.
4. Before specifying the G53 command, you must set the machine coordinate system; therefore it is necessary to manually return to the reference point or return to the reference point with the G28 command after power on. You may skip this operation when using the absolute position encoder.

## 8.2 Workpiece Coordinate System

The coordinate system used for workpiece machining is called as a workpiece coordinate system.

The workpiece coordinate system is predefined in the CNC system (Define workpiece coordinate system).

You may create programs in the defined workpiece coordinate system and machine the workpiece (Select workpiece coordinate system).

You may move the origin of the defined workpiece coordinate system to change the workpiece coordinate system (Change workpiece coordinate system).

### 8.2.1 Define Workpiece Coordinate System (G92)

workpiece coordinate system:

1. Use G92 to define the workpiece coordinate system.
2. Define the workpiece coordinate system through the selection of G code.

Use the workpiece coordinate system on the HMI interface to define six standard workpiece coordinate systems (G54-59) and 60 extended workpiece coordinate systems (G54.X) (for milling machining center), and then use the corresponding program commands to define the workpiece coordinate.

3. For turning machines, in the absolute tool offset compensation mode, you may define the origin of the workpiece coordinate system via T commands (see section 10.1)

Under the absolute commands, the workpiece coordinate system must be established by using any of the methods above.

There are three methods to define a

#### Format

**G92 IP\_;**

Parameter	Description
IP	The orientation distance from the origin of the coordinate system to the tool start point.

**Set Workpiece Coordinate System**

The G92 command can be used to set the relative position of the tool start point to the coordinate origin. Thereby defining the workpiece coordinate system. Once the workpiece coordinate system is defined, the command value in absolute programming is the coordinate value in the workpiece coordinate system.

**Attention**


1. The execution of this program block is only to set the workpiece coordinate system, but the tool will not move.
2. G92 is a non-modal command.
3. In the tool length compensation mode of milling machines, the coordinate system set G92 command is the specified coordinate system before conducting the compensation. However, the G code cannot be executed in the program blocks where the tool length compensation vector changes. For example, it is cannot be executed in the following blocks:
  - Program blocks where the G43/G44 is specified.
  - Program blocks where H code is specified in G43/G44 modes
  - Program blocks where G49 is specified in G43/G44 modes
  - Program blocks where the compensation vector is canceled by G28/G53 in G43/G44 modes and the vector is restored

In addition, when setting the workpiece coordinate system with G92, the programs before it will be stopped and the tool length compensation defined by MDI cannot be changed.

**Example**

Use G92 to set the workpiece coordinate system as shown below:

```
G92 X30.0 Y30.0 Z20.0
```





### 8.2.2 Select Workpiece Coordinate System (G54-G59)

You may select the following workpiece coordinate systems that have been defined:

1. In the workpiece coordinate system defined by G92, the absolute command defined is a position in this coordinate system.
2. Select among 6 standard workpiece coordinate systems of G54 to G59.
3. For milling machines and machining centers, select among 60 extended workpiece coordinate systems of G54.X.
4. For turning machines, in the absolute tool offset mode, select a workpiece coordinate system with T commands. For details, see section 10.1.

#### Example

*%I234*

*G54*

*G90 G00 X100 Y100 Z50*; Locate X=100 Y=100 Z=50 in the G54 coordinate system

*M30*

### 8.2.3 Change Workpiece Coordinate System (G10)

You may change the workpiece coordinate system defined in the following modes by changing an external workpiece origin offset or workpiece origin offset:

1. Workpiece coordinate systems defined by G54-G59
  - Set the Coordinate system on the HMI interface.(see relevant section of Operation manual)
  - Select the G code to define the workpiece coordinate systems
  - Change the coordinate system origin with G10 command(for details, see section 15)
2. Workpiece coordinate systems defined by G54.X for milling machines

- - Set the Coordinate system on the HMI interface.(see relevant section of Operation manual)
  - Select the G code to define the workpiece coordinate systems
  - Change the coordinate system origin with G10 command(for details, see section 15)
  -
3. Workpiece coordinate systems defined with absolute tool offset for turning machines
    - Set the Coordinate system on the HMI interface.(see relevant section of Operation manual)
    - Select the G code to define the workpiece coordinate systems

### 8.2.4 Select Extended Workpiece Coordinate System (G54.x)

In addition to the six standard workpiece coordinate systems, you may select extended workpiece coordinate systems for milling machines as required.

A total of 60 extended workpiece coordinate systems for milling machines are available.

#### Format

**G54.n, G54.1Pn, G54Pn:** Select No. *n* workpiece coordinate system

Parameter	Description
n	Number of Extended workpiece coordinate system, ranging from <b>1</b> to <b>60</b> .

#### Example

*%1234*

*G54.18; or G54.1P18, G54P18*

*G90 G00 X100 Y100 Z50;* locate the position where X=100 Y=100 Z=50 in the 18<sup>th</sup> coordinate system

*M30*

### 8.3 Define Local Coordinate System (G52)

During workpiece coordinate system programming, you may create a sub workpiece coordinate system, which is called local coordinate system.

#### Format

**G52 IP\_;** Define the local coordinate system

.....

**G52 IP 0;** Cancel the local coordinate system

Parameter	Description
IP	Define the origin of the local coordinate system

#### Description

The **G52 IP\_;** command can be used to create the local coordinate systems in all workpiece coordinate systems. The origin of the local coordinate system becomes the position defined by IP\_ in the corresponding workpiece coordinate system.

Once the local coordinate system is defined, the axial movement command to be specified will be the coordinate value in the local coordinate system.

If you want to cancel the local coordinate system or specify coordinate value in the workpiece coordinate system, you may make the origin of the local coordinate system coincide with the origin of the workpiece coordinate system.

#### Example

*%1234*

*G55;* select G55, assuming that the value of G55 in the machine coordinate system is (10, 20)

*G1 X10Y10F1000;* move to the point (20, 30) in the machine coordinate system

*G52 X30Y30;* set local coordinate system based on G55 in the workpiece coordinate system, with the origin of (30, 30)

*G1 X0Y0;* move to the origin of the local coordinate system (the current position in the machine coordinate system is (40, 50))

*G52 X0Y0;* cancel the local coordinate system, and restore the G55

workpiece coordinate system

*G1 X10Y10*; move to the machine coordinate system (20, 30)

*M30*

### Attention

If the local coordinate system is not canceled and the workpiece coordinate system changes, the local coordinate system is still valid.

### Example

*%I234*

*G54*; select G54, assuming that the value of G54 in the machine coordinate system is (10, 10, 10)

*G0X0Y0Z0*; move to the point (10, 10, 10) in the machine coordinate system

*G52X20Y20Z20*; set local coordinate system based on G54 in the workpiece coordinate system, with the origin of (20, 20, 20)

*G0X0Y0Z0*; move to the point (30, 30, 30) in the machine coordinate system

*G55*; select G55, assuming that the value of G55 in the machine coordinate system is (12, 12, 12)

*G0X0Y0Z0*; move to the point (32, 32, 32) in the machine coordinate system; the local coordinate system is still valid.

*G52X0Y0Z0*; cancel the local coordinate system and restore the G55 coordinate system

*G0X0Y0Z0*; move to the point (12, 12, 12) in the machine coordinate system; the local coordinate system is still valid.

*M30*

## 8.4 Select Coordinate Planes (G17, G18, G19)

The coordinate plane selection command G17/G18/G19 is used to select machining planes during circular interpolation, cutter radius compensation (M), rotation transformation (M), etc.

### Description

G code	Plane
G17	XY plane
G18	ZX plane
G19	YZ plane

### Attention

G17, G18, and G19 are modal functions, which can be canceled by each other.

The motion command has nothing to do with the plane selection. For example, the Z axis moves even the command *G17 G01 Z10* is executed.

## **9 Coordinate Values and Dimension Unit**

---

---

This chapter includes the following sections:

### **9.1 Absolute Commands and Incremental Commands**

### **9.2 Dimension Unit Selection**

### **9.3 Polar Coordinate Programming (M)**

### **9.4 Diameter and Radius Programming (T)**

## 9.1 Absolute Commands and Incremental Commands (G90, G91)

There are two methods to specify tool movement: absolute commands and incremental commands:

- Absolute commands are used to create programs for the tool movement end point coordinates.
- Incremental command is used to create programs for the amount of tool movement.

### Format

- Milling Machines
  - Absolute command G90 IP<sub>z</sub>;
  - Incremental command G91 IP<sub>z</sub>;
- Turning Machines (two formats):
  - First: Absolute command G90 IP<sub>z</sub>;  
Incremental command G91 IP<sub>z</sub>;
  - Second: UVW incremental programming


When UVW is not defined as a coordinate axis and the channel parameter **Enable Programming with UVW** (040033) is set to **1**, you may use UVW to present the incremental value of XYZ.

### Description

It can simplify programming by selecting a proper programming mode. When the blueprint dimension is based on a fixed point, it is recommended to use the absolute programming. When the blueprint dimension is based on the distance between contour vertexes, it is recommended to use the incremental programming.

**Example**

## 1. Milling machines




## 2. Turning machines

The tool moves from P to Q (X axis indicates the diameter value commands).

Absolute command: G90X400Z50

Incremental command: G91X200Z-400 or U200W-400





## 9.2 Dimension Unit Selection (G20, G21)

You may select dimension unit with G20/G21.

### Format

G20	Inch input mode
G21	Metric input mode

### Description

G Code	Linear Axis	Rotation Axis
Inch input (G20)	inch	Degree (deg)
Metric input (G21)	Millimeter (mm)	Degree (deg)

### Attention

1. G20 and G21 are modal functions, which can be canceled by each other. G21 is the default value after power on.
2. The unit of the data input for G codes has nothing to do with the unit of the data displayed on the HMI interface. G20/21 is used to select the unit of the data input for G codes, but cannot change the data unit displayed on the HMI interface. The NC parameter **SIZE METRIC/INCH (000025)** is used to set the coordinate data unit displayed on the interface.

### Example

*%0007*

*G54*

*G01 x10y10z10*

*G20*

*x2y2z2*

*M30*

## 9.3 Polar Coordinate Programming (M) (G16, G15)

For G code programming, it is more convenient and faster to create programs by entering the coordinate values of the end point at the polar coordinate system of the radius and angle.

From the positive direction of the first axis in the specified polar coordinate plane, the angle in the CCW direction is positive, and the angle in the CW direction is negative.

The absolute command and incremental command (G90, G91) can be used to specify radius and angle.

### Format

Define the plane of the polar coordinate system	G17	XY plane: The X axis specifies the polar radius while the Y axis specifies the polar angle.
	G18	ZX plane: The Z axis specifies the polar radius while the X axis specifies the polar angle.
	G19	YZ plane: The Y axis specifies the polar radius while the Z axis specifies the polar angle
Define the origin of the polar coordinate system	G90	Specify the workpiece coordinate system origin as the origin of the polar coordinate system, and measure radius from this point.
	G91	Specify the current point as the origin of the polar coordinate system, and measure radius from this point.
G16		Start of the polar coordinate programming command
G15		End of the polar coordinate programming command

### Set origin of polar coordinate system

There are two methods to set the origin of the polar coordinate system:


1. Specify the workpiece coordinate system zero point as the origin of the polar coordinate system

**Specify the radius with absolute value.**

**Specify the workpiece coordinate system origin as the origin of the polar coordinate system.**

**When using the local coordinate system (G52), the origin of the**


**local coordinate system is the origin of the polar coordinate system.**



- Specify the actual position as the origin of the polar coordinate system

**Specify the radius with incremental value.**

**Specify the actual position as the origin of the polar coordinate system.**



### Attention

- The axis command with the following commands will not be regarded as polar coordinate command:
  - Pause *G04*
  - Programmable data input *G10*
  - Local coordinate system *G52*
  - Change workpiece coordinate system *G92*
  - Machine coordinate system selection *G53*

- Coordinate rotation *G68*
- Scaling *G51*

2. In the polar coordinate system, any degrees of angle/convex corner R cannot be specified.
3. In the polar coordinate system, you cannot use fixed cycle G commands.
4. For polar coordinate programming, when specifying the radius with absolute values, set the workpiece coordinate system origin as the polar coordinate system origin; when specifying the radius with incremental values, set the actual position as the polar coordinate system origin. However, if only angle is specified in the command, set the workpiece coordinate system origin as the polar coordinate system origin both in absolute mode and incremental mode.

### Examples

1. Use absolute commands to specify the radius and angle

*%1000;*

*G54*

*G00 X0Y0Z0*

*G17 G90 G16;*

*G01 X100.0 Y30.0F1500*

*Y150.0;*

*Y270.0;*

*G15*

*M30*

2. Use absolute command to specify the radius and incremental command to specify the angle

*%1000*

*G54*

*G00 X0Y0Z0*

*G17 G90 G16;*

*G01 X100.0 Y30.0F1500*

*G91Y120.0;*

*Y120.0;*

*G15*

*M30*

## 9.4 Diameter and Radius Programming (T) (G36, G37)

### Format

**G36;** Diameter programming

**G37;** Radius programming


### Description

The shape of the workpiece to be processed in a turning machine is usually a rotating piece, and its X axis dimension can be specified in two ways: diameter and radius modes. G36, the default value, indicates the diameter programming.

### Attention

1. The Z-axis command input has nothing to do with the diameter or radius programming.
2. When G02 or G03 is specified, the parameter values of R, I, K are radius values.
3. In single fixed rotation, the parameter R used as the tool feed along the X axis indicates the radius value.
4. For turning machines or machining center, the default mode is the diameter programming (G36).
5. Specify the axial feed rate based on the change of radius.

### Example



Diameter programming	Radius programming
%3341 N1 G92 X180 Z254 N2 G36 G01 X20 W-44 N3 U30 Z50 N4 G00 X180 Z254 N5 M30	%3342 N1 G92 X90 Z254 N2 G37 G01 X10 W-44 N3 U15 Z50 N4 G00 X90 Z254 N5 M30

## **10 Tool Compensation Functions**

---

---

This chapter includes the following sections:

### **10.1 Tool Offset (T)**

### **10.2 Tool Nose Radius Compensation (T)**

### **10.3 Introduction to Tool Radius Compensation (M)**

### **10.4 Detailed Description of Tool Radius Compensation (M)**

### **10.5 Tool Length Compensation (M)**



## 10.1 Tool Offset (T)


The programming path is the motion path of the tool nose. However, in real machining, the geometry dimensions and installation positions of different tools are different; therefore, the relative position of the tool nose to the center of the turret is different. You need to measure and set the tool nose position, so that the system may conduct tool offset compensation during the machining. When programming, you do not need to take into account the tool nose position difference caused by tool shape and installation position.

Tool dimension error may be caused by tool wear after a period of usage; therefore the compensation is required. The compensation and tool offset compensation are stored in the same register address number. The tool wear compensation of a tool is only valid for the tool (including the standard tool).

### 10.1.1 T Command for Tool Offset

The tool compensation is specified by T commands, and the four digits after T express selected tool number and tool offset compensation (for details, see section 4.3).

The description of T command is as follows:



The tool offset number is the address number of the tool offset compensation register which stores the tool offset compensation values and tool wear compensation value of X axis and Z axis.

T plus compensation number starts the offset compensation feature. The offset number **00** expresses the offset is **0**. In this case, the offset feature

is canceled.

The tool geometry offset number and tool number may be the same or different. In other words, multiple tool offset numbers (value) may correspond to one tool.


### Example

*N1 G00X100Z140*

*N2 T0313* (select No. 3 tool and the tool offset of No. 13 tool)

*N3 X200Z150*


As shown in the figure below, if there is compensation value for the tool path (relative to the programming path) in the X, Z axis (the vector of the compensation in the X, Z direction is referred to as compensation vector), the position of the end point in the program segment plus or minus compensation amount (compensation vector) is the end position specified by the T command.



### 10.1.2 Tool Offset Compensation and Tool Wear Compensation

The programming path of the turning machine is actually the movement path of the tool nose. But in the actual situation, the geometry dimension and installation position of different tools are different, and the relative position of the tool nose to the center of the turret is different. Hence, you need to measure and define the tool nose position of each tool, so that the system may conduct tool offset compensation during the processing. This way, you do not need to take account of the tool nose position difference caused by the difference of tool shape and installation position in programming.


### Absolute Compensation Mode



The absolute tool offset indicates the orientation distance from the tool nose of each tool on the turret to the workpiece zero when the machine returns to the machine zero. When executing tool offset compensation, the processing coordinate system of each tool is defined based on the distance. This way, when the turret is at the machine zero, even the tool dimension and the distance from the tool position to the workpiece zero are different, the defined coordinate system of each tool is coincide with the workpiece coordinate system (programmed).


### Example

As shown in the figure below, set tool offset wear compensation, and then cancel the tool offset wear compensation:



## 10.2 Tool Nose Radius Compensation (T) (G40, G41, G42)

The CNC program is generally created based on the dimension of the workpiece for a point that is on the cutting tools (cutter location point), which is generally the imaginary tool nose (point A) under ideal conditions or the center point of the tool nose circle (O). But in the actual processing, the tool nose may not be a point but an arc because of the processing craft or other requirements. During cutting, the cutting point changes on the arc. This way, there may be deviation between the actual cutting position and the cutter location point, and thereby causing excessive or less cutting. The processing error, caused because that the tool nose is not an ideal point but one arc, can be eliminated by the nose radius compensation function.



### Attention


Radius compensation does not support interruption command such as G31.

### 10.2.1 Imaginary Tool Nose

As shown in the figure below, the imaginary tool nose point (A) does not exist. It is more difficult to set the radius center of actual tool nose at the start point than to set the imaginary tool nose at the start point. Hence, the imaginary is necessary.

When using the imaginary tool nose, you do not need to consider the radius of tool nose during programming.

When the tool is set at the start point, the position is as below:




### Description

The tool nose arc radius compensation function can be used to add or cancel radius compensation, which is specified with the G41/G42/G40 and tool nose radius compensation number specified by T.

### Format

G Code	Workpiece Position	Tool Path
G40	Canceling tool nose radius compensation	Move along the tool path
G41	Left tool compensation	Compensation at the left side of the tool movement direction
G42	Right tool compensation	Compensation at the right side of the tool movement direction


See the figure below:




### 10.2.2 Define Tool Nose Direction

The direction number of cutting tool nose defines the relationship between the cutter location point and tool nose center. There are ten directions ranging from 0 to 9. See the figure below:

#### Back tool turret



#### Front tool turret



**Attention**

1. G40, G41, and G42 are modal codes, which can be canceled by each other.
2. G41/G42 is not followed by any parameters, and its compensation number (indicating the tool nose radius compensation corresponding to the tool) is specified by T commands. The tool nose arc compensation number corresponds to the tool offset compensation number.
3. The command used to establish or cancel the tool radius compensation can be only G00 or G01, but cannot be G02 or G03.


**Tool Offset Transition**

The program block changing from G40 to G41 or G42 is called the program of tool offset transition.

**G40\_;**

**G41\_;** (starting cutting)

The tool offset transition movement is performed in this program block. In the start point of the next program block after it, the tool nose center is located in the vertical line of the programming path.


**Cancel Offset**

The program block changing from G41 or G42 to G40 is called the offset cancelation program.

**G41\_;**


**G40\_;** (offset cancelation program)

In the program block prior to the offset cancelation program, the tool nose center moves to the position vertical to the programming path. The tool is located at the end point of the offset cancelation program. See the figure below:



### Example

Create a program for the workpiece machining as shown in the figure below (considering the tool radius compensation):



%3323

N1 T0101 (change to the No. 1 tool and set the coordinate system)

N2 M03 S400 (CW rotate spindle at 400r/min)

N3 G00 X40 Z5 (move to the program start point)

N4 G00 X0 (the tool moves to the workpiece center)

N5 G01 G42 Z0 F60 (add tool radius compensation, and move to the workpiece position)

N6 G03 U24 W-24 R15 (process the R15 arc segment)

N7 G02 X26 Z-31 R5 (process the R5 arc segment)

N8 G01 Z-40 (process the Φ26 external circle)

N9 G00 X30 (exit the processed surface)

N10 G40 X40 Z5 (cancel the radius compensation, and return to



the program start point)



*N11 M30* (stop spindle, end the main program and reset)

### 10.2.3 Usage of Tool Radius Compensation


**Tool nose radius compensation of inner/outer diameter cutting cycle (G80) or end-face cutting cycle (G81)**


1. Movement path in the direction of the imaginary tool

The tool movement path direction is generally parallel to the programming path. The figure below shows the paths with tool nose radius compensation in nine tool nose directions:



2. Offset direction





### Tool nose radius compensation of cutting cycle


When you specify the following cutting cycle, the tool offset will be a tool nose radius compensation vector, without intersection calculation during the cycle.


Note: The establishment and cancelation of radius compensation must be between the P/Q segments of the combined cycle.

- G71 Inner (outer) diameter rough-turning compound cycle
- G72 End-face rough-turning compound cycle
- G73 Closed turning compound cycle

### Tool nose radius compensation of chamfer

The figure below shows the compensation motion:



**Tool nose radius compensation of corner arc**

## 10.3 Introduction to Tool Radius Compensation (M) (G40, G41, G42)

### Attention

Radius compensation does not support interruption command such as G31.

In the program block between G41/G42 and G40, G0 automatically changes to G01.

### 10.3.1 Tool Radius Compensation for Milling Machines

During programming, only the tool center path is generally programmed (the tool radius is assumed as 0). However, in the actual machining, you need to conduct offset for the tool center path because the tool radius is not zero (The offset distance equals to the tool radius and the offset direction may be left or right based on the actual programming). In this case, tool radius compensation function is required.

### Format

**G17 (or G18/G19) G41 (or G42) G00 (or G01) IP\_ D\_;**

### Attention

1. Tool radius compensation does not support radius change.
2. Tool radius compensation does not support the status change of G41/G42.

### Establish Tool Compensation

G17/G18/G19: Define the compensation plane, XY, YZ, ZX plane respectively

G41/G42: Tool radius compensation is valid. G41: left compensation. G42: Right compensation.

D: Define the tool radius compensation number.

### Cancel Tool Radius Compensation

**G40 IP\_;**

G40: Cancel tool radius compensation (G40, G41, G42 are modal codes, which can be canceled by each other.)


IP\_: The command value of axis movement

The tool radius compensation function is defined by G41 or G42.

G41: Conduct left offset along the tool movement (see a)

#### Offset Direction

G42: Conduct right offset along the tool movement (see b)



### 10.3.2 Establish or Cancel Tool Compensation

Establish or cancel radius compensation through G00 or G01.

If the arc interpolation commands (G02, G03) are used to establish or cancel the tool compensation, an alarm will be reported.

### 10.3.3 Define Tool Radius Compensation Amount

You may use the D codes to set the tool radius compensation amount by defining the number of tool radius compensation amount.

The D code is valid until another D code is defined.

#### Attention

The change of tool radius compensation amount is generally conducted during tool change when the tool compensation is canceled.


### 10.3.4 Plane Selection and Vector

The offset calculation is based on the plane defined by G17, G18, and G19. The plane for offset calculation is called the offset plane.

The coordinate value on the axis outside the offset plane is not affected by the offset, and can be used as originally. In the simultaneous 3-axis control, the tool moves in the offset mode based on the shape projected on the offset plane.

### Example

Change the offset plane in the offset cancelation mode. An alarm will be reported and the tool stops if the offset plane is changed in the offset mode.



%0504

N01 G92 X0 Y0

N02 G0 X-40 Y-26.66

N03 G90 G41 G0 X0 Y0 D3

N04 G1 X-20 Y30 F2000

N05 G1 X43.135529 Y156.271057

N06 G2 X175.554 Y73.70 R80

N07 G1 X20 Y-30

N08 G1 X0 Y0

N09 G40 G0 X-40 Y-26.66

N10 M30







## 10.4 Description of Tool Radius Compensation (M) (G40, G41, G42)

### 10.4.1 Tool Movement during Tool Start

The figure below shows the tool movement when the mode is changed from the offset cancelation into the offset mode:



**Tool movement around the inner corner**

( $\alpha \geq 180$  degrees)




### Tool movement around the outer corner


( $90 \text{ degrees} \leq \alpha < 180 \text{ degrees}$ )



### Tool movement around the outer corner

( $\alpha < 90 \text{ degrees}$ )









### 10.4.2 Tool Movement in Offset

Tool movement around the inner corner


( $\alpha \geq 180$  degrees)








### Tool movement around the outer corner




(90 degrees  $\leq \alpha < 180$  degrees)






### Tool movement around the outer corner

( $\alpha < 90$  degrees)







### 10.4.3 Tool Movement during Offset Cancellation



In the program block including offset cancellation, tool movement around the inner corner

( $\alpha \geq 180$  degrees)



**In the program block including offset cancelation, tool movement around the outer obtuse angle**



**(90 degrees  $\leq \alpha < 180$  degrees)**






**In the program block including  
offset cancelation, tool movement  
around the outer acute angle**

**( $\alpha < 90$  degrees)**



## 10.5 Tool Length Compensation (M) (G43, G44, G49)

between the tool length specified in programming and the actual tool length. You may save this difference in the CNC's tool offset register, and then use the tool length compensation codes to conduct the compensation for the difference, in order to simplify the operation and programming. This way, even tools with different length are used for machining, you may conduct normal machining without modifying the program if you know the difference between the programmed tool length and the actual length.



Generally, there may be a difference

### Attention

The length compensation does not support interruption codes such as G31.

### Abstract

There are three kinds of tool length compensation based on the type of the axis allowed tool length compensation.

1. Tool length compensation A

Tool length compensation along Z axis direction

2. Tool length compensation B

Tool length compensation vertical to the selected plane

3. Tool length compensation C

Tool length compensation along specified axis direction

**Format**

Type	Format
Tool length compensation A	G43/G44 Z_H_
Tool length compensation B	G17 G43/G44 Z_H_ G18 G43/G44 Y_H_ G19 G43/G44 X_H_
Tool length compensation C	G43/G44 X_H_ G43/G44 Y_H_ G43/G44 Z_H_ .....
Cancel tool length compensation	G49 IP_

**Description**

Tool length compensation is defined by G43 and G44.

G43: Tool length compensation in the positive direction (plus the tool length compensation value to the theoretical position in the tool axis direction)

G44: Tool length compensation in the negative direction (minus the tool length compensation value to the theoretical position in the tool axis direction)

G17: Select XY plane

G18: Select ZX plane

G19: Select YZ plane

H: The number of tool length compensation amount in the tool compensation table

**Attention**

1. The direction of tool length compensation is always vertical to the plane defined by G17/G18/G19.
2. When the offset number is changed, the new offset value will not be added to the old offset value. Example:

H1: Tool length compensation amount 20.0; H2: Tool length compensation amount 30.0

G90 G43 Z100 H01; Z reaches 120

G90 G43 Z100 H02; Z reaches 130


3. G43, G44, G49 are modal codes which can be canceled by each other.
4. The axis movement is invalid if no tool length compensation after G49.



**Example 1**

Take into account the tool length compensation, and create a program for the workpiece as shown in the figure below.

Requirements: establish a workpiece coordinate system and conduct machining in the direction shown by the arrow in the figure below:



H1 = -4.0 (tool length compensation value)

%3325

G92 X0 Y0 Z0

G91 G00 X120 Y80 M03 S600

①

G43 Z-32 H01

②

G01 Z-21 F300

③

G04 P2000

④

G00 Z21

⑤

X30 Y-50

⑥

<i>G01 Z-41</i>	⑦
<i>G00 Z41</i>	⑧
<i>X50 Y30</i>	⑨
<i>G01 Z-25</i>	⑩
<i>G04 P2000</i>	⑪
<i>G00 G49 Z57</i>	⑫
<i>X-200Y-60</i>	⑬
<i>M05</i>	
<i>M30</i>	

## **11 Programming Simplification Functions**

---

---

This chapter includes the following sections:

### **11.1 Mirroring Function (M) (G24/G25)**

### **11.2 Scaling Function (M) (G50/G51)**

### **11.3 Rotation Function (M) (G68/G69)**

### **11.4 Direct Programming Based on Blueprint Dimension (T)**

## 11.1 Mirroring Function (M) (G24, G25)

When the workpiece is symmetric around an axis, you may use the mirroring functions and subprograms to create a program only for one part of the workpiece, and other symmetrical parts can be produced. This is called mirroring.

### Format

**G24 IP\_;** Create mirror

.....

**G25 IP0;** Cancel mirror

Parameter	Description
IP	The position of the mirror axis.

### Attention


1. you may establish the symmetrical mirror of the  $\beta$  axis by specifying G24  $\alpha_.$

After establishing the mirror of the  $\beta$  axis, you may cancel the mirror of the  $\beta$  axis by specifying G25  $\alpha 0$ . If you establish a point-symmetrical mirror by specifying G24 X0Y0, the symmetrical mirror of the Y axis can be canceled by specifying G25 X0, and then only the X axis mirror is specified.

The character " $\alpha$ " represents the first axis in the selected plane while " $\beta$ " represents the second axis in the selected plane.

2. G24 and G25 program blocks are specified in separate lines.
3. G24 is a modal function. You may use G25 to cancel the mirroring function after it is ended.
4. When no axis is after G25, all mirroring functions are canceled.



**Description**

1. The mirroring path 1 and the programming path is axisymmetric, with the symmetry axis  $\alpha=50$ .
2. The mirroring path 2 and the programming path is point-symmetric, with the symmetry point (50, 60).
3. The mirroring path 3 and the programming path is axisymmetric, with the symmetry axis  $\beta=60$ .

**Axisymmetric mirror**

(G17/G18/G19) G24  $\alpha\_/\beta\_;$

..... ;

**G25;**

G17/G18/G19: Selects the mirror plane which should contain the programming tool path.

G24  $\alpha\_/\beta\_;$  Specifies the symmetry axis of the mirror. You can only and must specify either  $\alpha\_$  or  $\beta\_$ . The character " $\alpha$ " represents the first axis in the selected plane, and " $\beta$ " represents the second axis in the selected plane. If an axis that is not in the selected plane is specified, an alarm will be reported.

.....: Programming command of tool path.

G25 $\alpha 0/\beta 0$ : Cancels the mirroring function. Only the command G25 or the command with G25 followed by the random value of "a" and "b" can cancel the mirroring function.

**Point-symmetric mirror**

(G17/G18/G19) G24  $\alpha\_ \beta\_;$

..... ;

**G25;**

G17/G18/G19: Selects the mirror plane which should contain the programming tool path.


G24  $\alpha\_ \beta\_$ : Specifies the symmetry point of the mirror. When  $\alpha\_$  or  $\beta\_$  is blank, the point is the actual tool position by default. If an axis that is not in the selected plane is specified, an alarm will be reported.

.....: Programming command of tool path.

G25 $\alpha 0 \beta 0$ : Cancels the mirroring function. Only the command G25 or the command with G25 followed by the random value of "a" and "b" can cancel the mirroring function.

### Example

Use the mirroring function to create a program for the machining of the contour as shown in the figure below: The distance from the start point of the tool to the workpiece surface is 100 mm, and the cutting depth is 5 mm.



%3331 Main program

G92 X0 Y0 Z100

G91 G17 M03 S600

M98 P100; Conduct machining for ①

G24 X0; Y axis mirroring, with mirroring position X=0

M98 P100; Conduct machining for ②

G24 Y0; X&Y axis mirroring, with mirroring position (0, 0)

M98 P100; Conduct machining for ③

G25 X0; X axis mirroring remains valid, and cancel the Y axis mirroring

M98 P100; Conduct machining for ④

*G25 x0 Y0; Cancel mirroring*

*M30*

*%100; sub program (program for ①):*

*N100 G41 G00 X10 Y4 D01*

*N120 G43 Z10 H01*

*N130 G01 G90 Z-3 F300*

*N140 G91 Y26*

*N150 X10*

*N160 G03 X10 Y-10 I10 J0*

*N170 G01 Y-10*

*N180 X-25*

*N185 G00 Z10*

*N190 G90 G49 G00 Z100*

*N200 G40 X0 Y0*

*N210 M99*

## 11.2 Scaling Function (M) (G50, G51)

The scaling function can be used to zoom in or zoom out the programming path by a given scaling factor.

### Uniform scaling

**G51 IP\_ P\_;** Start scaling

.....

**G50;** Cancel scaling

Parameter	Description
IP	Specify the center point coordinates for the scaling. If the center point is not specified, the current point will be specified by default. The command always specifies the absolute position of the scaling center in the workpiece coordinate system.
P	Specifies the scaling factor for each axis. All axes are scaled according to the scaling factor.

### Tool Compensation


In the case of tool compensation, scaling is conducted before the tool radius compensation or tool length compensation. The scaling will not change the tool radius compensation value or tool length compensation value.

### Attention

1. Specify G51 block in a separate line.
2. Use G50 to cancel the scaling after the scaling is completed.
3. In the G51 block, either in the incremental (G91) or absolute mode (G90), the center coordinates of the scaling IP\_ refers to the absolute position in the workpiece coordinate system.

**Example**

Use the scaling function to create a program for the machining of the contour as shown in the figure below: The apexes of the triangle ABC are A (10, 30), B (90, 30), C (50, 110); the triangle A'B'C' is the shape after scaling, with the scaling center D (50, 50) and the scaling factor 0.5; the distance from the start point of the tool to the surface of the workpiece is 50 mm.



%3332; Main program

G92 X0 Y0 Z60

G17 M03 S600 F300

G43 G00 Z14 H01

X110 Y0

#51=0

M98 P100; Machining for the triangle ABC

#51=6

G51 X50 Y50 P0.5; Scaling center (50, 50), scaling factor 0.5

M98 P100; Machining for the triangle A'B'C'

G50; Cancel the scaling

G49 Z60

G00 X0 Y0

M05 M30

*%100; Sub program (program for the triangle ABC)*

*N100 G41 G00 Y30 D01*

*N120 Z[#51]*

*N150 G01 X10*

*N160 X50 Y110*

*N170 G91 X40 Y-80*

*N180 G90 Z[#51]*

*N200 G40 G00 X110 Y0*

*N210 M99*

## 11.3 Rotation Function (M) (G68, G69)

The rotation function can be used to rotate the programming path around the rotation center with the specified angle. If the workpiece consists of multiple parts with the same shape, you may create sub programs and then use the rotation command to call the subprograms.

It can simplify the programming and save storage space.

### Format

**G17/G18/G19;** Select a rotation plane

**G68 IP\_ P\_;** Establish rotation

.....

**G69;** Cancel rotation

Parameter	Description
IP	Specifies the rotation center coordinate. If nothing is specified as the rotation center, the current point of the tool will be specified by default. Either in the incremental or absolute mode, the specified value refers to the absolute position in the workpiece coordinate system.
P	Rotation angle (unit: degree)

### Rotation angle

The rotation angle **P** ranges from **-360** to **360** degrees, positive in the counterclockwise direction and negative in the clockwise direction. Either specified by G90 or G91, P is always the absolute value of the angle which is based on the positive direction of the first axis in the specified plane.

### Tool compensation

Conduct tool radius compensation, tool length compensation, tool offset, and other compensation after the coordinate system rotation. If rotation and scaling are both required, rotation should be programmed prior to the scaling function; otherwise a message prompting you "SWITCHING NESTING ORDER ERROR." will be displayed.


### Attention

1. The G code (G28, G29, G30, etc.) related to reference or the command used for changing the coordinate system (G52, G54-G59, G54.X, G92, etc.) cannot be specified in the rotation mode. To specify such commands, please firstly cancel the coordinate rotation command.

2. If you Specify G68 and G69 in the tool radius compensation mode, the rotation plane must be consistent with the tool radius compensation plane.
3. Use G69 to cancel the rotation function after it is completed.
4. Specify the G68 program block in a separate line.

### Example

Use the rotation function to create a program for the machining of the contour as shown in the figure below: the distance from the tool start point to the workpiece surface is 50 mm, and the cutting depth is 5 mm.



%3333; Main program

N10 G92 X0 Y0 Z50

N15 G90 G17 M03 S600

N20 G43 Z-5 H02

N25 M98 P200; Machining for ①

N30 G68 X0 Y0 P45; Rotate 45 degrees

N40 M98 P200; Machining for ②

N60 G68 X0 Y0 P90; Rotate 90 degrees

N70 M98 P200; Machining for ③

N20 G49 Z50

N80 G69 M05 M30; Cancel rotation

%200; Programming for subprogram ①

G41 G01 X20 Y-5 D02 F300

N105 Y0



*N110 G02 X40 I10*

*N120 X30 I-5*

*N130 G03 X20 I-5*

*N140 G00 Y-6*

*N145 G40 X0 Y0*

*N150 M99*

## 11.4 Direct Programming based on Blueprint Dimensions (T)

Straight angles, chamfering values, corner arc transition values and other dimensional values on machining blueprint can be directly entered for programming. In addition, chamfer or transition arc can be inserted between the straight lines of any dip angle. This program mode is called direct programming based on blueprint dimensions.

**This programming mode is used only for G01 command of turning series G01.**

### Command format

The programming mode consists of eight command modes. The meaning of each character is as below:


X\_/Z\_: Linear destination address word

A\_: The angle between the direction of linear movement and the positive direction of Z-axis, negative in the clockwise direction and positive in the counterclockwise direction. Unit: degree.

C\_: Chamfer side length.


R\_: Rounding radius.

1. Specify a straight line




Note: You can only specify the amount of displacement in one direction for the target position. For example: Z50a45 or X100a45.


## 2. Specify straight lines continuously




## 3. Rounding




## 4. Chamfer




## 5. Continuous rounding



## 6. Continuous chamfer



## 7. Rounding and then chamfer

**Attention**

To avoid the conflicts between the address word in this function and the axis name, make sure to set the channel parameter **Parm040035** [ANGLE PROGRAMMING ENABLED] (channel 0) when using this function.

## **12 Fixed Cycle**

---

During CNC machining, some machining cycle has been stylized. Some typical machining operations such as drilling, boring, milling, turning, etc., are pre-created via the macro program and are saved in the system. Call the programs through G codes to simplify the programming. This chapter includes the following sections:

### **12.1 Drilling Fixed Cycle for Milling Machines**

### **12.2 Simple Cycle for Turning Machines**

### **12.3 Drilling Fixed Cycle for Turning Machines**

### **12.4 Combined Cycle for Turning Machines**

### **12.5 Exceptions in Fixed Cycle**

## 12.1 Drilling Fixed Cycle for Milling Machines (M)

Commands of drilling fixed cycle for milling machines

G Code	Drilling (-Z Direction)	Action at the Hole Bottom	Tool Exist (+Z Direction)
G70	Cutting feed	Pause	Rapid tool exit
G71	Cutting feed	Pause	Rapid tool exit
G73	Intermittent cutting feed	Pause	Rapid tool exit
G74	Cutting feed	Pause—Spindle clockwise rotation	Cutting back
G76	Cutting feed	Spindle orientation	Rapid tool exit
G78	Cutting feed	Pause	Rapid tool exit
G79	Cutting feed	Pause	Rapid tool exit
G81	Cutting feed	—	Rapid tool exit
G82	Cutting feed	Pause	Rapid tool exit
G83	Cutting feed	Pause	Rapid tool exit
G84	Cutting feed	Pause—Spindle counter clockwise rotation	Cutting back
G85	Cutting feed	—	Cutting back
G86	Cutting feed	Pause—Spindle stop	Rapid tool exit
G87	Cutting feed	Spindle clockwise rotation	Rapid tool exit
G88	Cutting feed	Pause—Spindle stop	Manually
G89	Cutting feed	Pause	Cutting back
G80	—	—	—

### Drilling actions

Generally there are six actions for the drilling cycle in order:

Action 1: X&Y axis positioning


Action 2: Rapidly move to the R plane

Action 3: Execute drilling

Action 4: Operations at the hole bottom

Action 5: Exit the tool to the R plane

Action 6: Rapidly exit the tool to the initial Z plane



**Locate plane**

**G17 plane (X, Y axis)**

**Drilling axis**


**Z axis**

**Drilling data**

G73, G74, G76 and the codes from G81 to G89 are modal G codes, which are valid before they are canceled. The parameters defined in these drilling cycle commands are modal data, which indicates that the parameters are valid before they are canceled.

**Return to the reference plane G99**


The G99 command can be used to return to the reference point plane specified by the R parameter after the fixed cycle is ended.






**Return to the start plane G98**

The G98 command can be used to return to the start plane where the fixed cycle is commanded after the fixed cycle is ended. G98 is the initial modal G code of Group 15.

**Cancel the fixed cycle**

**G80 or the G codes of Group 01 can be used to cancel the fixed cycle.**


**Symbol description****Attention**

1. When the fixed cycle program lines without X, Y, Z axis movement command are executed, the tool will not move, but the cycle parameter modal value of the current lines will be saved.
2. Specifying the G code of Group 1 or G80 will cancel the current fixed cycle G code modal, and also clear the cycle parameter modal value.
3. If you need to execute the fixed cycle repeatedly by specifying **L**, an alarm will be reported when **L** is set to **0**.

4. When the G53 command is specified in a fixed cycle block, its positioning data (X, Y) is still the original workpiece coordinate system data, but not the coordinate system data specified by G53.

**Example:**

Use  $\Phi 10$  drilling bit to drill the holes shown in the figure below:

**Program example**

```
%5647
```

```
G54
```

```
G90 X0 Y0 Z80
```

```
M3 S1000;
```

*G90 G99 G81 X300 Y-250 Z-150 R-120 F120;* Position, drill hole 1, return to the point of R

*Y-550;* Position, drill hole 2, return to the point of R

*Y-750;* Position, drill hole 3, return to the point of R

*X1000;* Position, drill hole 4, return to the point of R

*Y-550;* Position, drill hole 5, return to the point of R

*G98 Y-750;* Position, drill hole 6, return the initial plane

*G80 G28 G91 X0 Y0 Z0;* Cancel the fixed cycle and return to the reference point


```
M5;
```

```
M30
```

### 12.1.1 Circumference Drilling Cycle (G70)

### Description

In the circumference with the radius **I** and the center being the coordinate (**X**, **Y**). Divide the circle into **N** equal parts based on the angle **J** and the X axis. Conduct drilling for **N** holes. Execute fixed cycle of **G81** and **G83** based on the value of **Q**, **K** for each hole. The movement between holes is performed through **G00**. **G70** is a modal code, and the command word following it is non-modal.



## Format

**(G98 / G99) G70 X\_ Y\_ Z\_ R\_ I\_ J\_ N\_[Q\_K\_P]\_ F\_ L\_**

Parameter	Description
X Y	The circle center coordinate.
Z	Hole bottom coordinate.
R	The coordinate value of the reference point R for absolute programming, or the incremental value of the reference point R to the initial point B for incremental programming.
I	Circle radius.
J	The initial angle for drilling hole, positive in the counter clockwise direction.
N	The number of holes. The positive value for the counter clockwise drilling and negative value for the clockwise drilling.
Q	Feed depth for each time, orientation distance.
K	When conducting feeding again after a tool exit, the distance away from the previous machining plane while the rapid feed is changed to the cutting feed.
P	The duration that the tool remains at the hole bottom. Unit: millisecond An error is reported when the value of <b>Q</b> is greater than <b>0</b> or <b>K</b> is less than <b>0</b> ; An error is reported when the tool feed distance <b>Q</b> is less than the tool exit distance <b>K</b> . When <b>Q</b> or <b>K</b> is <b>0</b> or is not defined, <b>G81</b> center drilling cycle is executed for each hole, and <b>P</b> is invalid. When the values of <b>Q</b> and <b>K</b> are correct, <b>G83</b> deep hole machining cycle is executed for each hole.
F	Define cutting feed speed.
L	The repeat count (Generally used for multi-hole machining, and therefore X or Y is incremental value. It is optional when L=1.).

On the X, Y plane, drill four holes in the counter clockwise direction on the four axes(+X, -X, +Y, -Y). This operation is executed twice, and G81 is executed for drilling at the hole bottom.

#### Example 1

*G98 G70 X10 Y10 Z0 R20 I10 J0 N4 F200 L2*

#### Example 2

On the X, Y plane, drill four holes in the clockwise direction with thangle of 45 degrees. This operation is

executed once, and G81 is executed for drilling at the hole bottom.

*G99 G70 X10 Y10 Z10 R50 I10 J45 N-4 F200*

On the X, Y plane, drill four holes in the clockwise direction, with the angle of -45 degrees. This operation is executed once, and G81 is executed for drilling at the hole bottom.

### Example 3

*G99 G70 X10 Y10 Z10 R50 I10 J-45 N-4 F200*

### Example 4

On the X, Y plane, drill four holes in the clockwise direction with the angle of -45 degrees. This operation is executed once. The value of **Q** is invalid, and G81 is executed for drilling at the hole bottom.

*G99 G70 X10 Y10 Z10 R50 I10 J-45 N-4 Q-10 F200*

### Example 5

On the X, Y plane, drill four holes in the clockwise direction with the angle of -45 degrees. This operation is executed once, and G81 is executed for drilling at the hole bottom.

### Example 6


*G99 G70 X10Y10Z10R50 I10J-45N-4 Q0 F200*

*G99 G70 X10Y10Z10R50 I10J-45N-4 K0 F200*

*G99 G70 X10Y10Z10R50 I10J-45N-4 Q0K0 F200*

On the X, Y plane, drill four holes in the clockwise direction with the angle of -45 degrees. This operation is executed once, and G83 is executed for deep hole cycle.

*G99 G70 X10Y10Z10R50 I10J-45N-4 Q-10 K5 F200*



Use  $\Phi 10$  drilling bit for the machining of the holes as shown in the figure.

### 12.1.2 Arc Drilling Cycle (G71)

#### Decription

**I** and the center being the coordinate **(X, Y)**. Divide the circle into **N** equal parts based on the angle **J** and the X axis. Conduct drilling for **N** holes per **O** degrees, starting from the point where the angle from the A axis is **J**. Execute fixed cycle of **G81** or **G83** based on the value of **Q**, **K** for each hole. The movement between holes is performed through **G00**. **G71** is a modal code, and the command following it is non-modal.

In the circumference with the radius

#### Foramt

(G98/G99) G71 X\_Y\_Z\_R\_I\_J\_O\_N[Q\_K\_P]\_F\_L\_

Parameter	Description
X Y	The center coordinate for the arc.
Z	Hole bottom coordinate.
R	The coordinate value of the reference point R for absolute programming, or the incremental value of the reference point R to the initial point B for incremental programming.
I	Arc radius.
J	The initial drilling hole angle, positive in the counter clockwise direction
O	The angle between each hole. The positive value for the counter clockwise drilling and negative value for the clockwise drilling.
N	The number of holes, including the start hole.
Q	Feed depth for each time, orientation distance.
K	When conducting feeding again after a tool exit, the distance away from the previous machining plane while the rapid feed is changed to the cutting feed.
P	The duration that the tool remains at the hole bottom. Unit: millisecond An error is reported when <b>Q</b> is greater than <b>0</b> or <b>K</b> is less than <b>0</b> ; An error is reported when the tool feed distance <b>Q</b> is less than the tool exit distance <b>K</b> . When <b>Q</b> or <b>K</b> is <b>0</b> or is not defined, execute <b>G81</b> center drilling cycle for each hole, and <b>P</b> is invalid. When the values of <b>Q</b> and <b>K</b> are correct, <b>G83</b> deep hole machining cycle is executed for each hole and <b>P</b> is valid.
F	Define cutting feed speed.


L	The repeat count (Generally used for multi-hole machining, therefore X or Y is incremental value. L is optional.)
---	---

The total arc angle ( $N \times O$ ) cannot be greater than or equal to 360 degrees, otherwise the command will not be executed.

### Attention

Use  $\Phi 10$  drilling bit for the drilling of the holes as shown in the figure:

### Example



*%3359*

*N10 G55 G00 X0 Y0 Z80*

*N20 G98G71G90X40Y0G90R25Z0I40J55O28N4P2000Q-10K5F100*

*N30 G90 G00 X0 Y0 Z80*

*N40 M30*




### 12.1.3 High-Speed Deep-Hole Drilling Cycle (G73)

#### Example

The fixed cycle is used for the intermittent feed along Z axis, which is prone to chip-breaking, chip-removal, coolant adding, and small amount of tool exit. It is applicable for high-speed deep-hole drilling.

The figure below shows the operation action sequence of G73. The dotted line represents rapid positioning, **q** represents each feed depth, and **k** represents each tool exit value.



#### Format

(G98/G99) G73 X\_Y\_Z\_R\_Q\_P\_K\_F\_L\_;

Parameter	Description
X Y	The coordinate value of the hole center in the XY plane for absolute programming (G90), or the incremental value of the hole center to the start point in the XY plane for incremental programming (G91).
Z	The coordinate value of the hole bottom point Z for absolute programming (G90), or the incremental value of the hole bottom point Z to the reference point R for incremental programming (G91).
R	The coordinate value of the reference point R for absolute programming (G90), or the incremental value of the reference point R to the initial point B for incremental programming (G91).
Q	Drilling depth for each time (incremental value, negative).
P	The duration that the tool remains at the hole bottom. Unit: millisecond.

K	Each upward tool exit amount (incremental value, positive).
F	Drilling feed speed
L	Cycle count (for repetitive drilling)

### Operation procedure


1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece.
3. Drill downward at the speed of F, with depth  $q$ .
4. Move upward rapidly, with distance  $k$ .
5. Repeat step 3 and 4 for multiple times.
6. Drill to the point Z at the hole bottom.
7. Remain 9 seconds at the hole bottom (spindle remains rotation)
8. Exit upward rapidly to the point R (G99) or B (G98).

### Attention

1. If the motion amount of Z, K, and Q are zero, this command is not executed.
2.  $|Q| > |K|$ ;

### Example

Drilling the hole as shown in the figure below:



```
%3337
```

```
N10 G92 X0 Y0 Z80
```

```
N15 M03 S700
```

*N20 G00 Y25*

*N30 G98 G73 G91 X20 G90 R40 P2000 Q-10 K2 Z-3 L2 F80*

*N40 G00 X0 Y0 Z80*


*N45 M30*

### 12.1.4 Reverse Tapping Cycle (G74)

#### Description

The spindle motor and servo motors are running in the position control mode. The tapping is conducted by the interpolation between the tapping axis and spindle. The spindle feeds the distance of one thread lead along the tapping axis per rotation. The feeding does not change even during acceleration or deceleration.

The action defined by G74 is as shown in the figure below. Move rapidly to the point "R" after positioning along X and Y axis. The spindle rotates in the counter clockwise (CCW) direction, and tapping is conducted from the point R to Z. After the tapping is completed, the spindle stops and the system starts the mode of pause. Then the spindle rotates in the clockwise (CW) direction, the tool exits back to the point R, and the spindle stops. The tool will finally move rapidly to the initial position in the G98 mode.



In the rigid tapping mode, the servo spindle motor controls the tapping.

#### Format

**(G98/G99)G74 X\_Y\_Z\_Q\_R\_P\_F\_L\_H\_J\_;**

Parameter	Description	Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).	R	The absolute position of the point R for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
Z	The absolute position of the hole bottom for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).	P	The duration that the tool remains at the hole bottom. Unit: millisecond.
		F	Define thread lead.
		H	H1: segment tapping, exits to the R plane each time.
Q	The amount of each feed during segment tapping. Leave it blank in the H2 mode.	H2	directly drills to the hole bottom.
		L	Repeat count (It is optional when L=1.)
		J	J1: A axis tapping; J2: B axis tapping; J3 C: axis tapping

**F (feed speed) during tapping**

(F) specified in the programming is invalid. The feed speed along the tapping axis is derived from:  $speed\ feed = spindle\ speed \times thread\ lead$

During rigid tapping, the feed speed

**Tapping mode**

C axis tapping: take the servo spindle as the C axis, and conduct tapping by interpolation, to achieve high-speed high-precision tapping.

**Attention**


1. The tapping axis must be the Z axis.
2. The point Z must be lower than the plane of point R; otherwise, an alarm will be reported.

3. The G74 command data is saved as modal data.
4. When the motion amount of Z is zero, the cycle is not executed.
5. During reverse tapping, the operations on feed rate adjustment, spindle rate adjustment, and feed hold is invalid.
6. Before specifying reverse tapping with G74, change the control mode of the spindle servo motor from speed control to the position control by using the **STOC** command. After tapping, you may use the **CTOS** command to change back to the speed control mode and take the servo spindle as a common spindle.
7. Before specifying reverse tapping with G74, use the corresponding M command to rotate the spindle in the counter

clockwise direction.

8. After executing the rigid tapping with G74, the programmer must restore the original feed speed; otherwise, the feed speed will be the rigid tapping speed (s\*pitch).

Use M10 x 1 for anti-tapping



%3339

G92 X0 Y0 Z80 F200

M04 S300

STOC

G98G74X50Y40R40P10000G90Z-5F1

CTOS

### Example


*G0 X0 Y0 Z80*

*M30*

### 12.1.5 Fine-Boring Cycle (G76)

#### Description

During finish boring, after the spindle stops orientation at the hole bottom, it moves away from the tool nose, then the tool quickly exits. The value of movement away from the tool nose is specified by (I, J), which can only be positive. The value of (I, J) is modal, and the movement direction is determined during tool installation.



#### Format

(G98/G99) G76 X\_ Y\_ Z\_ R\_ I\_ J\_ P\_ F\_ L\_;

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91). UW programming is not supported.
Z	The absolute position of the hole bottom along Z axis for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R along Z axis for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
I	Offset value along X axis, positive only.
J	Offset value along Y axis, positive only.
P	The duration that the tool remains at the hole bottom. Unit: millisecond.
F	Cutting feed speed.
L	Repeat count (It is optional when L=1.)




**Operation procedure**

1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece.
3. Conduct boring downward at the speed of F, to the point Z at the hole bottom.
4. Remain at the hole bottom for P seconds (The spindle remains rotation).
5. The spindle conducts orientation and stops rotation.
6. The boring tool rapidly moves away from the tool nose with the distance specified by I or J.
7. Exit upward rapidly to the point R (G99) or B (G98).
8. Move rapidly in the positive direction of the tool nose with the distance specified by I or J, and the tool moves back to the point R or B over the hole center.
9. The spindle restores the clockwise rotation.

**Attention**

1. The boring axis must be the Z axis.
2. The point Z must be lower than the plane of point R; otherwise, an alarm will be reported.
3. The G76 command data is saved as modal data.
4. Before using the command of G76, use the corresponding M command to rotate the spindle.

**Example**



*N10 G54*

*N12 M03 S600*

*N15 G00 X0 Y0 Z80*

*N20 G98G76X20Y15R40P2000I5Z-4F100*

*N25 X40Y30*

*N30 G00 G90 X0 Y0 Z80*

*N40 M30*

### 12.1.6 Angular Linear Drilling Cycle (G78)

#### Description

Divide the oblique line which rotates **J** degrees around axis **X** into **N** holes with the interval distance of **I**. Starting from the point defined by **X**, **Y**, conduct the drilling cycle for each hole. Execute **G81** and **G83** fixed cycle based on the value of **Q**, **K** for each hole. The movement between holes is conducted through **G00**. **G78** is a modal code, and the command following it is non-modal.


#### Format

(G98/G99) G78 X\_ Y\_ Z\_ R\_ I\_ J\_ N\_ [Q\_ K\_ P]\_ F\_ L\_

Parameter	Description
X Y	The coordinate of the first hole.
Z	The coordinate of the hole bottom.
R	The absolute position of the reference point R for absolute programming (G90), or the distance from the reference point R to the initial point B for incremental programming (G91).
I	The distance between two successive hole centers.
J	The start angle formed by the oblique line and the positive X axis, which is positive in the counter clockwise direction.
N	The number of holes including the start hole.
Q	Feed depth for each time, orientation distance.
K	When conducting feeding again after a tool exit, the distance away from the previous machining plane while the rapid feed is changed to the cutting feed.
P	The duration that the tool remains at the hole bottom. Unit: millisecond An error is reported when <b>Q</b> is greater than 0 or <b>K</b> is less than 0; An error is reported when the tool feed distance <b>Q</b> is less than the tool exit distance <b>K</b> . When <b>Q</b> or <b>K</b> is 0 or is not defined, execute <b>G81</b> center drilling cycle for each hole, and <b>P</b> is invalid. When the values of <b>Q</b> and <b>K</b> are corrective, execute <b>G83</b> deep hole machining cycle for each hole, and <b>P</b> is valid.
F	Define cutting feed speed.
L	The repeat count (Generally used for multi-hole machining, and therefore X or Y is incremental value. (It is optional when L=1.)

**Example**

Use  $\Phi 10$  drilling bit to drill the holes as shown in the figure:



*%3360*

*N10 G55 G00 X0 Y0 Z80*

*N20 G98G78G90X20Y10G90R15Z0I20J30N3P2000Q-10K5F100*

*N30 G90 G00 X0 Y0 Z80*

*N40 M30*

### 12.1.7 Chessboard Drilling Cycle (Drilling along X Axis First) (G79)

#### Description

Starting from the point defined by **X**, **Y**, conduct drilling for **N** holes in the direction parallel to the X-axis with the interval distance of **I**. Then conduct drilling in the direction of the X axis with an interval specified by **J** along the Y axis. This operation is repeated for **O** times. Execute **G81** and **G83** fixed cycle based on the value of **Q**, **K** for each hole. The movement between holes is performed through **G00**. **G79** is a modal code, and the command following it is non-modal.

#### Format


(G98/G99) G79 X\_ Y\_ Z\_ R\_ I\_ N\_ J\_ O\_[Q\_K\_P]\_ F\_ L\_

Parameter	Description
X Y	The coordinate of the first hole.
Z	The coordinate of the hole bottom.
R	The coordinate value of the reference point R for absolute programming (G90), or the incremental value of the reference point R to the initial point B for incremental programming (G91).
I	The distance between two successive hole centers in the X axis direction. The positive value indicates the drilling along the positive X axis direction while the negative value indicates the drilling along the negative X axis direction.
N	The number of holes including the start hole in the X axis direction.
J	The distance between two successive hole centers in the Y axis direction. The positive value indicates the drilling along the positive Y axis direction while the negative value indicates the drilling along the negative Y axis direction.
O	The number of holes including the start hole in the Y axis direction.
Q	Feed depth for each time, orientation distance.
K	When conducting feeding again after a tool exit, the distance away from the previous machining plane while the rapid feed is changed to the cutting feed.

P	<p>The duration that the tool remains at the hole bottom. Unit: millisecond</p> <p>An error is reported when <b>Q</b> is greater than <b>0</b> or <b>K</b> is less than <b>0</b>; An error is reported when the tool feed distance <b>Q</b> is less than the tool exit distance <b>K</b>. When <b>Q</b> or <b>K</b> is <b>0</b> or is not defined, execute <b>G81</b> center drilling cycle for each hole, and <b>P</b> is invalid. When the values of <b>Q</b> and <b>K</b> are correct, execute <b>G83</b> deep hole machining cycle for each hole, and <b>P</b> is valid.</p>
F	Define cutting feed speed.
L	The repeat count (Generally used for multi-hole machining, therefore X or Y is incremental value. It is optional when L=1.)

### Example

Use  $\Phi 10$  drilling bit for the drilling of the holes as shown in the figure:



%3361

N10 G55 G00 X0 Y0 Z80

N20 G98G79G90X20Y20G90R25Z0I15N3J15O3P2000Q-10K5F100

N30 G90 G00 X0 Y0 Z80


N40 M30

### 12.1.8 Drilling Cycle (Center Drilling) (G81)

#### Description

The cycle is used for normal drilling. The cutting feed is executed to the hole bottom, and then the tool rapidly exits from the hole bottom.

The movement specified by G81 is as shown in the figure below, where the dotted line indicates rapid positioning:



#### Format

(G98/G99) G81 X\_ Y\_ Z\_ R\_ F\_ L\_ ;

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom along Z axis for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R along Z axis for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
F	Cutting feed speed.
L	The repeat count (Generally used for multi-hole machining, and therefore X or Y is incremental value. It is optional when L=1.)

**Operation procedure**


1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece.
3. Conduct drilling downward at the speed of F, to the point Z at the hole bottom.
4. The spindle remains the rotation and moves upward rapidly to the point R (G99) or B (G98).

**Attention**

1. If the movement amount of Z is zero, the command is not executed.
2. The drilling axis must be the Z axis.
3. The G81 command data is saved as modal data.
4. Before using the command of G81, use the corresponding M command to rotate the spindle.

**Example**

Conduct drilling of the holes as shown in the figure below:



```
%3343
```

```
N10 G92 X0 Y0 Z80
```

```
N15 M03 S600
```

```
N20 G98 G81 G91 X20 Y15 G90 R20 Z-3 L2 F200
```

```
N30 G00 X0 Y0 Z80
```


```
N40 M30
```



### 12.1.9 Drilling Cycle with Pause (G82)

#### Description

This instruction is mainly used for processing sink holes, blind holes, to improve the hole depth precision. Except for the pause at the hole bottom, other operations are similar as that of G81. The figure below shows the operation of G82:



#### Format

(G98/G99) G82 X\_Y\_Z\_R\_P\_F\_L\_;

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom along Z axis for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
P	The duration that the tool remains at the hole bottom. Unit: millisecond
F	Cutting feed speed.
L	The repeat count (Generally used for multi-hole machining to simplify programming. It is optional when L=1.)

**Operation procedure**


1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece.
3. Conduct drilling downward at the speed of F, to the point Z at the hole bottom.
4. Delay P milliseconds with the rotation of the spindle.
5. Move upward rapidly to the point R (G99) or B (G98).

**Attention**

1. The drilling axis must be the Z axis.
2. If the movement amount of Z is zero, the command is not executed.
3. The G82 command data is saved as modal data.
4. Before using the command of G82, use the corresponding M command to rotate the spindle.

**Example**

Conduct drilling of the hole as shown in the figure below:



```
%3345
```

```
N10 G92 X0 Y0 Z80
```

```
N15 M03 S600
```

```
N20 G98 G82 G90 X25 Y30 R40 P2000 Z25 F200
```


```
N30 G00 X0 Y0 Z80
```

*N40 M30*

### 12.1.10 Deep-Hole Drilling Cycle (G83)

#### Description

The fixed cycle is used for the intermittent feed along Z axis, which enables a rapid tool exit to the reference point R with larger retract amount after each drilling. It facilitates the chip-removal and coolant adding. The figure below shows the operation specified by G83:



#### Format

(G98/G99) G83 X\_Y\_Z\_R\_Q\_K\_F\_L\_P\_;

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
Q	The each downward drilling depth (incremental value, negative).
K	The distance away from the upper surface of drilled hole (incremental value, positive). <b>K</b> cannot be greater than <b>Q</b> .
F	Cutting feed speed.
L	The repeat count (Generally used for multi-hole machining to simplify programming. It is optional when L=1.)
P	The duration that the tool remains at the hole bottom. Unit: millisecond

**Operation procedure**


1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece.
3. Drill downward at the speed of F, with depth  $q$ .
4. Move upward rapidly to the point R.
5. Move downward rapidly to the upper surface of the drilled hole, the distance is specified with K.
6. Drill downward at the speed of F, with depth  $(q + k)$ .
7. Repeat the step 4, 5, and 6, and then drills to the hole bottom Z point.
8. Delay P milliseconds at the hole bottom (spindle remains rotation).
9. Exit upward rapidly to the point R (G99) or B (G98).

**Attention**

1. The drilling axis must be the Z axis.
2. If the movement amount of Z, Q, and K are zero, the command is not executed.
3. The G83 command data is saved as modal data.
4. Before using the command of G83, use the corresponding M command to rotate the spindle.

**Example**


Conduct drilling of the hole as shown in the figure below:



### 12.1.11 Tapping Cycle (G84)

#### Description

on the same principle. In the G84 mode, the tool taps to the hole bottom with the spindle rotation in the clockwise direction and then goes back with the spindle rotation in the counter clockwise direction. See the figure below:



The command G84 and G74 works

#### Format

**G84 X\_Y\_Z\_R\_Q\_P\_F\_L\_H\_J\_;**

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
Q	The amount of each feed during segment tapping. Leave it blank in the H2 mode.
P	The duration that the tool remains at the hole bottom. Unit: millisecond.
F	Define thread lead.

L	The repeat count (Generally used for multi-hole machining, and therefore X or Y is incremental value. It is optional when L=1.)
J	J1: A axis tapping; J2: B axis tapping; J3 C: axis tapping

**F (feed speed) during tapping**

During rigid tapping, the value of feed speed (F) specified in the programming is invalid. The feed speed along the tapping axis is derived from:

$$\text{feed speed} = \text{spindle speed} \times \text{thread lead}$$

**Tapping mode**

C axis tapping: take the servo spindle as the C axis, and conduct tapping by interpolation, to achieve high-speed high-precision tapping

**Attention**

1. The tapping axis must be the Z axis.
2. The point Z must be lower than the plane of point R; otherwise, an alarm will be reported.
3. The G84 command data is saved as modal data.
4. When the motion amount of Z is zero, the cycle is not executed.
5. During forward tapping, the operations on feed rate adjustment, spindle rate adjustment, and feed hold is invalid during tapping.
6. Before executing the tapping command G84, change the control mode of the spindle servo motor from speed control to the position control by using the **STOC** command. After tapping, you may use the **CTOS** command to change back to the speed control mode and use the servo spindle as a common spindle.
7. Before using the command of G84, use the corresponding M command to rotate the spindle in the clockwise direction.
8. After calling the rigid tapping G84, the programmer must restore the original feed speed; otherwise, the feed speed will be the rigid tapping speed (s\*pitch).
9. The rotation or zoom command is not supported during rigid tapping (The limitation is for all fixed cycles).



**Example**

*%3349*

*N10 G92 X0 Y0 Z80*

*N15 M03 S300*

*G108*

*N20 G98G84X0Y0Z-15R10P2000F1*

*G109*


*N30 G90 G0 X0 Y0 Z80*

*N40 M30*

### 12.1.12 Boring Cycle (G85)

#### Description

The command is used to bore the holes which have low requirement for precision. The operation specified by G85 is as shown below:



#### Format

(G98/G99) G85 X\_ Y\_ Z\_ R\_ F\_ L\_;

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91). UW programming is not supported.
Z	The absolute position of the hole bottom for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
F	Cutting feed speed.
L	The repeat count (Generally used for multi-hole machining to simplify programming. It is optional when L=1.)

#### Operation procedure

1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece.


3. Conduct boring downward at the speed of F.
4. Move to the point Z at the hole bottom.
5. Exit upward rapidly to the point R (the spindle remains rotation).
6. Exit upward rapidly to the point B in the G98 mode.

### Attention

1. The boring axis must be the Z axis.
2. The point Z must be lower than the plane of point R; otherwise, an alarm will be reported.
3. If the motion amount of Z, Q, and K are zero, the cycle is not executed.
4. The G85 command data is saved as modal data.
5. Before using the command of G85, use the corresponding M command to rotate the spindle.

### Example

Conduct boring of the holes as shown in the figure below:



```
%3351
```

```
N10 G92 X0 Y0 Z80
```

```
N15 M03 S600
```

```
N20 G98 G85 G91 X20 Y15 G90 R20 Z-3 L2 F100
```

*N30 G90 G00 X0 Y0 Z80*

*N40 M30*

### 12.1.13 Boring Cycle (G86)

#### Description

The operation specified by G86 is similar as G81. In the G86 mode, the spindle stops at the hole bottom and the tool exits rapidly. The command is used to bore the holes which have low requirement for precision.

#### Format

(G98/G99) G86 X\_ Y\_ Z\_ R\_ F\_ L\_;

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91)
R	The absolute position of the point R for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
F	Cutting feed speed.
L	The repeat count (Generally used for multi-hole machining to simplify programming. It is optional when L=1.)

#### Operation procedure

1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece.
3. Conduct boring downward at the speed of F.
4. Reach the hole bottom of point Z.
5. The spindle stops rotation.
6. Exit upward rapidly to the point R (G99) or B (G98).
7. The spindle restores clockwise rotation.


#### Attention

1. If the movement amount of Z is zero, the command is not executed.
2. The G86 command data is saved as modal data.

3. The boring axis must be the Z axis.
4. The point Z must be lower than the plane of point R; otherwise, an alarm will be reported.

### Example

Conduct boring of the hole as shown in the figure below:



%3353; Reaming with a reamer

*N10 G92 X0 Y0 Z80*

*N15 G98 G86 G90 X20 Y15 R20 Z-2 F200*

*N20 X40 Y30*


*N30 G90 G00 X0 Y0 Z80*

*N40 M30*

### 12.1.14 Anti-Boring Cycle(G87)

#### Description

The instruction is generally used to bore holes which are smaller at the upper part and larger at the lower part. The hole bottom point Z is generally above the reference point R, which is different from other instructions.



#### Format

(G98/G99) G87X\_Y\_Z\_R\_I\_J\_P\_F\_L\_;

Parameter	Description
X Y	The absolute position the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom along Z axis for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91)
R	The absolute position of the point R along Z axis for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
I	Offset value along X axis.
J	Offset value along Y axis.
P	The duration that the tool remains at the hole bottom. Unit: millisecond.
F	Cutting feed speed.
L	The repeat count (Generally used for multi-hole

	machining, and therefore X or Y is incremental value. It is optional when L=1.)
--	--




**Operation procedure**

1. The tool moves rapidly to the point B over the hole center.
2. The spindle conducts orientation and stops rotation.
3. The boring tool rapidly moves away from the tool nose with the distance specified by I or J.
4. Move rapidly to the point R.
5. Move rapidly in the positive direction of the tool nose with the distance specified by I or J, and the tool moves back to the hole center specified by X, Y.
6. The spindle rotates in the clockwise direction.
7. Conduct boring upward at the speed of F, to the point Z at the hole bottom.
8. Remain at the hole bottom for P milliseconds (The spindle remains rotation).
9. The spindle conducts orientation and stops rotation.
10. The boring tool rapidly moves away from the tool nose with the distance specified by I or J.
11. Exit upward rapidly to the point B (G98).
12. Move rapidly in the positive direction of the tool nose with the distance specified by I or J, and the tool moves back to the hole center point B.
13. The spindle restores the clockwise rotation.

**Attention**

1. The boring axis must be the Z axis.
2. If the movement amount of Z is zero, the command is not executed.
3. The point Z must be higher than the plane of point R; otherwise, an alarm will be reported.
4. The G87 command data is saved as modal data.
5. Only G98 can be used for G87.
6. Before using the command of G87, use the corresponding M command to rotate the spindle.

**Example**

*%3355*

*N10 G92 X0 Y0 Z80*

*N15 M03 S600*

*N20 G00 Y15 F200*

*N25 G98*

*G87 G91*

*X20 I5 R-83 P2000 Z23 L2*


*N30 G90 G00 X0 Y0 Z80 M05*

*N40 M30*

### 12.1.15 Boring Cycle (Manual Boring) (G88)

#### Description

Before boring, this instruction memories the initial point B or reference point R. When the boring tool automatically processes to the hole bottom, the machine stops. You may manually change the operation mode to "Manual", and move the tool upward to the point B or R, and avoid the workpiece. Then the operation mode is changed back to the automatic operation mode. Start the program again, and the tool returns back to the point B or R. This instruction is generally used for precise boring with milling machines, without calling the spindle exact stop function.



#### Format

**G98 (G99) G88 X\_ Y\_ Z\_ R\_ P\_ F\_ L\_**


Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom along axis Z for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R along Z axis for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
P	The duration that the tool remains at the hole bottom. Unit: millisecond.
F	Boring feed speed.
L	The repeat count (Generally used for multi-hole machining, and therefore X or Y is incremental value.)

**Operation procedure**

1. The tool moves rapidly to the point B over the hole center.
2. Move rapidly to the point R, close to the workpiece surface.
3. Conduct boring downward at the speed of F, to the point Z at the hole bottom.
4. Remain at the hole bottom for P seconds (The spindle remains rotation).
5. The spindle stops rotation.
6. Manually move the tool until it is over the point R (G99) or B (G98).
7. Press **Start** in the auto operation mode, the tool rapidly moves to the point R (G99) or B (G98).
8. The spindle restores the clockwise rotation.

**Attention**

1. The boring axis must be the Z axis.
2. If the movement amount of Z is zero, the command is not executed.
3. The point Z must be lower than the plane of point R; otherwise, an alarm will be reported.
4. The G88 command data is saved as modal data.
5. If G99 is used, manually move the tool to the place over the point of R.
6. If G98 is used, manually move the tool to the place over the point of B.
7. Before using the command of G88, use the corresponding M command to rotate the spindle.

**Example**

%3357; Drilling with a single-margin boring tool

N10 G54

N12 M03 S600

N15 G00 X0 Y0 Z80

N20 G98G88G91X20Y15R-42P2000Z-40L2F100

N30 G00 G90 X0 Y0 Z80


N40 M30

### 12.1.16 Boring Cycle (G89)

#### Description

This operation specified by the command G89 is almost the same as that of G86. In the G89 mode, the spindle pauses at the hole bottom. Before specifying G89, use auxiliary function the M command to rotate the spindle. When the G89 command and M command are specified in the same block, the system executes the M command while the first positioning movement is performing, and then conducts the next boring. If the repeat count L is specified, the system executes the M command only for the first boring hole.

The operation specified by G89 is as shown below:



This cycle is used for boring.

#### Format

(G98/G99) G89 X\_Y\_Z\_R\_P\_F\_L;

Parameter	Description
X Y	The absolute position of the hole for absolute programming (G90), or the distance from the current tool position to the hole for incremental programming (G91).
Z	The absolute position of the hole bottom for absolute programming (G90), or the distance from the hole bottom to the point R for incremental programming (G91).
R	The absolute position of the point R for absolute programming (G90), or the distance from the point R to the initial plane for incremental programming (G91).
P	The duration that the tool remains at the hole bottom. Unit: millisecond.
F	Cutting feed speed.

L	The repeat count (Generally used for multi-hole machining, and therefore X or Y is an incremental value.)
---	---

**Attention**

1. The boring axis must be the Z axis.
2. The point Z must be lower than the plane of point R; otherwise, an alarm will be reported.
3. The G89 command data is saved as modal data.
4. G89 is similar as G86, but with a pause at the hole bottom.
5. If the movement amount of Z is zero, this command is not executed.
6. Before using the command of G89, use the corresponding M command to rotate the spindle.

**Example**

*M3 S1000*; The spindle starts rotation.

*G90 G99 G89 X300 Y-250 Z-150 R-120 P1000 F120*; Conduct positioning, and conduct boring for hole 1, return to the point R and then pauses at the hole bottom for one second

*Y-550*; Conduct positioning, and conduct boring for hole 2; return to the point R

*Y-750*; Conduct positioning, and conduct boring for hole 3; return to the point R

*X1000*; Conduct positioning, and conduct boring for hole 4; return to the point R

*Y-550*; Conduct positioning, and conduct boring for hole 5; return to the point R

*G98 Y-750*; Conduct positioning, and conduct boring for hole 5; return to the initial plane

*G80 G28 G91 X0 Y0 Z0*; Cancel boring and return to the reference point

*M5*; The spindle stops rotation.



### 12.1.17 Cancel Fixed Cycle (G80)

**Description**

This command is used to cancel the fixed cycle for drilling.

**Format**

**G80**


**Attention**

1. Cancel all fixed cycles for the drilling and then restore the normal operation.
2. Cancel the R and Z planes.
3. Other drilling parameters are also canceled.

## 12.1.18 Arc Groove Cycle (Type 1) (G181)

### Description

This command is used to process the grooves arranged according to an arc. The groove width is defined by the tool diameter.




### Format

(G98/G99) G181 R\_Z\_N\_K\_X\_Y\_I\_A\_B\_F\_Q\_V\_

Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the groove bottom for absolute programming, or the incremental value from the groove bottom to the reference point R for incremental programming.
N	The number of grooves (It is optional when N=1)
K	The length of the groove.
X	The center of the arc formed by the grooves. The first axis coordinate of the current plane for absolute programming, and the incremental value relative to the start point for incremental programming.
Y	The center of the arc formed by the grooves. The second axis coordinate of the current plane for absolute programming, and the incremental value relative to the start point for incremental programming.
I	The radius of the arc formed by the grooves.
A	Start angle (-180 to 180 degrees, positive in the CCW direction and negative in the CW direction. It is optional when A=0)

B	Incremental angle (It is optional when $B=360/N$ . A positive B value indicates the milling in the CCW direction; a negative B value indicates the milling in the CW direction).
F	Milling speed.
Q	The maximum feed depth each time (It is optional when $Q = \text{groove depth}$ , cutting to the bottom for a time).
V	Tool radius.


### Parameter graph



### Operation procedure

1. Select a random start point from which the tool may move to each groove without any collision.
2. Go to the reference position R over the near-end of the first groove from the start point. The near-end indicates the end near to the center of the arc groove. The groove specified by the start angle **A** will be processed firstly.
3. Feed downward at the milling feed rate to the defined depth, and then conduct milling back and forth until the bottom is machined. Conduct deep feed at the groove end.
4. On the application axis (generally Z axis), exit the tool to the reference point R. Select the shortest path to rapidly move to the end of the next groove, and conduct milling back and forth until the bottom is machined.
5. After completing the last groove, exit the tool to the initial point B or the reference point R based on the current modal G98 or G99,

and then the cycle ends.




### Attention

1. The groove number  $N$  must be a non-negative integer. If not, the negative symbol (-) will be ignored, and the number will be rounded.
2. The maximum feed depth is specified by the value of  $Q$ . If the groove depth is not divisible by  $Q$ , the final cut depth will be less than  $Q$ .
3. The milling direction for each groove is related to the symbol of  $B$ . If the value of  $B$  is positive, the system starts the milling from the first groove to the last in the CCW direction; if the value of  $B$  is negative, the system starts the milling in the CW direction. If  $B$  is not specified, the system will automatically derive  $B$  from  $B=360/N$ , and conduct milling in the CCW direction.
4. The value of  $K$ ,  $I$ , and  $Q$  should be non-negative values. If not, the system will ignore the negative symbol.
5. Rotate the spindle before executing the cycle. For alarm information, see section 12.1.26.

**Example**

grooves as shown in the figure below: Groove length 30 mm; groove depth 23 mm; feed depth 6 mm



%0526

N10 G54 X0 Y0 Z5

N20 G17 G90

N30 T10

N40 M06

N50 M03 S600

N60 G181 R0 Z-23 N4 K30 X40 Y45 I20 A45 B90 F100 Q6 V5

N70 M30


Conduct milling for four rectangle

### 12.1.19 Arc Groove Cycle (Type 2) (G182)

#### Description

The instruction is used to process grooves which are arranged in an annular array. The longitudinal shaft of these grooves turn up radially. The instruction is different from G181, as the groove width can be specified by a parameter, but not be defined by the tool diameter.

This cycle can be specified for rough and finish machining.




#### Format

(G98/G99)G182 R\_Z\_N\_K\_W\_X\_Y\_I\_A\_B\_F\_Q\_E\_O\_H\_U\_P\_C\_D\_V\_

Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the groove bottom for absolute programming, or the incremental value from the groove bottom to the reference point R for incremental programming.
N	The number of grooves (It is optional when N=1)
K	The length of the groove.
W	The groove width (It is optional when W= <i>tool diameter</i> ).
X	The center of the arc formed by the grooves. The first axis coordinate of the current plane for absolute programming, and the incremental value relative to the start point for incremental programming.

**Parameter graph**

Y	The center of the arc formed by the grooves. The second axis coordinate of the current plane for absolute programming, and the incremental value relative to the start point for incremental programming.
I	The radius of the arc formed by the grooves.
A	Start angle ( <b>-180</b> to <b>180</b> degrees, positive in the CCW direction and negative in the CW direction. It is optional when A=0)
B	Incremental angle (It is optional when B=360/N. A positive B value indicates the milling in the CCW direction; a negative B value indicates the milling in the CW direction.
F	Milling speed for rough machining.
Q	The maximum feed depth for rough machining each time(It is optical when Q=groove depth -the depth of groove bottom left for finish machining).
E	The finish allowance at the edge of the groove(It is optional when E=0).
O	The finish allowance in the groove bottom(It is optional when O=0).
H	The maximum feed depth for finish machining(It is optional when H=Q).
U	Feed speed for finish machining(It is optional when U=F).
P	Spindle speed for finish machining(It is optional when P=spindle speed before the cycle or default spindle speed).
C	The direction for milling each groove (It is optional when C=3) 0: milling in the same direction with the spindle rotation; 1: milling in the reversed direction with the spindle rotation; 2: milling in G02 direction; 3: milling in G03 direction
D	1: rough machining 2: finish machining (It is optional when D=1).
V	Tool radius.



### Milling direction

Before entering the cycle mode, you need to use the command to enable spindle rotation. The system will calculate the reasonable milling direction based on the spindle rotation direction (M03/M04) and the command . See the table below:

Milling direction (Parameter C)	Execute M03/M04 before the cycle	
	M03 spindle CW	M04 spindle CCW
0: same direction	G03	G02
1: reversed direction	G02	G03
2: in G02 direction	G02	G02
3: in G03 direction	G03	G03
Left blank	G03	G03

### Operation procedure

1. Select the start point , a random start point from which the tool may move to each groove without any collision.
2. Go to the reference point R over the first groove. The groove specified by the start angle A will be processed firstly.
3. **Rough machining (D=1):**

Starting at the groove end, the tool conducts milling from the middle part to the margin and from the groove surface to the finish allowance in the milling direction specified by C. Each time the tool feeds at the same point of the groove end until it reaches finish allowance in the groove bottom.

#### Finish machining (D=2):

Conduct finish machining for the groove wall and then the groove bottom. Conduct milling from the middle part to the defined groove margin in the milling direction specified by the parameter C, and then back to the the same start position, conduct milling downward to the groove bottom



4. After completing a groove, exits the tool to the reference point R. Rapidly move to the near-end of the next groove, and repeat step 3 until completing the last groove.
5. Exits the tool to the initial point B or the reference point R with G98 or G99, and then the cycle ends.


**Attention**

1. The tool radius cannot exceed the specified groove width **W**; otherwise, an alarm will be reported.
2. The groove number **N** must be a non-negative integer. If not, the system will ignore the negative symbol, and conduct rounding for the non-integer.
3. **Q** and **H** both specify the maximum feed depth. If the groove depth is not divisible by **Q** or **H**, the final cut depth will be less than **Q** or **H**.
4. The milling direction for each groove is specified by the parameter **C**. The milling direction between grooves is specified by the parameter **B**. If the value of **B** is positive, the system starts the milling from the first groove to the last in the CCW direction; if the value of **B** is negative, the system starts the milling in the CW direction. If **B** is not specified, the system will automatically derives **B** from  $B=360/N$ , and conduct milling in the CCW direction.
5. The values of parameter **K**, **W**, **I**, **E**, **O**, **H** and **Q** should be non-negative values. If the value is negative, the system will ignore the negative symbol.
6. Rotate the spindle Before executing the cycle. The finish allowance (**E**) specified for the groove margin cannot exceed half of the groove width ( $W/2$ ), and the finish allowance (**O**) specified for the groove bottom cannot exceed the groove depth; otherwise, an alarm will be reported. For more alarm information, see section 12.1.26.

**Example**

Conduct milling for four grooves as shown in the figure below:

Groove length 30 mm; groove width 15 mm; groove depth 23 mm; finish allowance 0.5 mm; milling direction G02; feed depth for rough machining 6 mm; tool radius: 5 mm



*%0527*

*N10 G54 G17 G90*

*N20 T10*

*N30 M06*

*N40 M03 S600*


*N50 G182R5Z-23N4K30X40Y45W15I20A45B90F100Q6E0.5O0.5C2 V5*

*N60 M30*

### 12.1.20 Circumference Groove Milling Cycle (G183)

#### Description

This cycle is used to process circumference grooves distributed in a circle shape. You may specify roughing, finishing or comprehensive machining.




#### Format

(G98/G99)G183R\_Z\_N\_K\_W\_X\_Y\_I\_A\_B\_F\_Q\_E\_O\_H\_U\_P\_C\_D\_V\_

Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the groove bottom for absolute programming, or the incremental value from the groove bottom to the reference point R for incremental programming.
N	The number of grooves (It is optional when N=1 ).
K	The angle of groove length (0 to 360 degrees. Unit: degree).
W	The width of the groove (It is optional when W= <i>tool diameter</i> ).
X	The center of the circle rounded by the grooves. The first axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.

Y	The center of the circle rounded by the grooves. The second axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
I	The radius of the circle rounded by the grooves.
A	Start angle ( <b>-180</b> to <b>180</b> degrees, positive in the CCW direction and negative in the CW direction. It is optional when A=0.)
B	Incremental angle (It is optional when B=360/N ; a positive B value indicates the milling in the CCW direction while a negative B value indicates the milling in the CW direction.
F	Milling speed during rough machining.
Q	The maximum feed depth for each time during rough machining (It is optional when Q= <i>groove depth- finishing allowance of the groove bottom</i> ).
E	The finishing allowance of the groove margin (It is optional when E=0).
O	The finishing allowance in the groove bottom (It is optional when O=0).
U	The feed rate for finish machining (It is optional when U=F).
P	The spindle speed for finish machining (It is optional when P= <i>the spindle speed before cycle</i> ).
C	The direction for milling each groove (It is optional when C=3) 0: milling in the same direction with the spindle rotation; 1: milling in the reversed direction with the spindle rotation; 2: milling in G02 direction; 3: milling in G03 direction
D	Machining type (It is optional when D=1) 1: rough machining; 2: finish machining
V	Tool radius.

### Parameter graph




### Milling direction

Before entering the cycle mode, you need to use the command to enable spindle rotation. The system will calculate the reasonable milling direction (M03/M04) based on the spindle rotation and the command . See the table below:

Milling Direction (Parameter C)	Execute M03/M04 before the cycle	
	M03 spindle CW	M04 spindle CCW
0: same direction	G03	G02
1: reversed direction	G02	G03
2: in G02 direction	G02	G02
3: in G03 direction	G03	G03
Left blank	G03	G03

### Operation procedure

1. During the cycle, use G00 to move to the reference plane R.
2. Conduct milling for the current groove from middle part to the edge. The operation procedure is similar as that of G182.
3. After completing a groove, exit the tool to the reference plane and move to the next groove.
4. After completing all grooves, exit the tool with the G98 or G99 command, and then the cycle ends.




### Example

Conduct milling for three grooves shown in the figure below:

Circle center: (X60, Y60); radius on the XY plane: 42 mm; groove width: 15 mm; groove length angle: 70 degrees; groove depth: 23 mm; start angle: 0 degree; incremental angle: 120 degrees; finishing allowance on the groove contour: 0.5 mm; feed depth: 6 mm; tool radius 5 mm

The spindle speed and feed rate for rough and finish machining are the same. The finish machining is completed with one cut.

See the figure below:



%0528

N10 G54 G17 G90

N20 T10

N30 M06

N40 M03 S600

*N50 G00 X60 Y60 Z5*


*N60 G183R2Z-23N3K70W15X60Y60I42A70B120F100Q6E0.5O0.5V5*

*N70 M30*

### 12.1.21 Rectangular Groove Cycle (G184)

#### Description

This cycle is used for the rough and finish machining of rectangular grooves with rounded corners.



#### Format


(G98/G99)G184R\_Z\_K\_W\_X\_Y\_I\_A\_F\_Q\_E\_O\_H\_U\_P\_C\_D\_V\_

Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the groove bottom for absolute programming, or the incremental value from the groove bottom to the reference point R for incremental programming.
K	The length of the groove.
W	The width of the groove.
X	The center of the groove. The first axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
Y	The center of the groove. The second axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
I	The arc radius of the rounded corner (It can be left blank or specified to 0 when $I=W/2$ ).



A	The angle formed by the long side of the rectangle groove and the first positive axis (It is optional when A=0.).
F	Milling speed during rough machining.
Q	The maximum feed depth for each time during rough machining (It is optional when Q= <i>groove depth-finishing allowance of the groove bottom</i> ).
E	The finishing allowance of the groove margin (It is optional when E=0).
O	The finishing allowance of the groove bottom (It is optional when O=0).
H	The maximum feed rate for finish machining (It is optional when U=Q ).
U	The feed rate for finish machining (It is optional when U=F ).
P	The spindle speed for finish machining (It is optional when P= <i>the spindle speed before cycle or the default spindle speed</i> ).
C	The direction for milling each groove (It is optional when C=3) 0: milling in the same direction with the spindle rotation; 1: milling in the reversed direction with the spindle rotation; 2: milling in G02 direction; 3: milling in G03 direction
D	Machining type (It is optional when D=1) <ul style="list-style-type: none"> <li>1: rough machining</li> <li>2: finish machining</li> </ul>
V	The tool radius.

### Parameter graph



### Milling direction

Before entering the cycle mode, you need to use the command to enable spindle rotation. The system will calculate the reasonable milling direction based on the spindle rotation direction (M03/M04) and the command. See the table below:

Milling Direction (Parameter C)	Execute M03/M04 before the cycle	
	M03 spindle CW	M04 spindle CCW
0: same direction	G03	G02
1: reversed direction	G02	G03
2: in G02 direction	G02	G02
3: in G03 direction	G03	G03
Left blank	G03	G03

### Operation Procedure

1. Select a random start point from which the tool may move to each groove without any collision.

#### 2. Rough machining (D=1):

Go to the center of the long side of the groove with G00(reserve the finishing allowance for the groove margin). The tool feeds downward with the depth specified by **Q**, and then conducts milling from the margin to the center for the upper part of the groove in the milling direction specified by **C**. Then backing to the same start position, the tool conducts milling from the groove surface to the groove bottom (reserve the finishing allowance).

#### Finish machining (D=2):

Go to the center of the long side of the groove with G00

(reserve the finishing allowance for the groove margin). The tool feeds downward with the depth specified by **H**, and then conducts milling from the center to the defined margin for the groove surface in the milling direction specified by **C**. After that, the tool goes back to the same point, moves to the surface for milling the finishing allowance, from the surface to the bottom in the direction specified by **C**.

3. After machining, exit the tool to the initial plane or the reference plane based on the current modal G98 or G99, and then the cycle ends.

### Attention


1. This cycle requires milling tool with face tooth.
2. The maximum feed depth for rough and finish machining is specified by the parameter **Q** or **H** respectively. If the groove depth is not divisible by **Q** or **H**, the final cut depth will be less than **Q** or **H**.
3. The values of N, K, W, I, E, O, Q and H should be non-negatives. If the specified value is a negative value, the system will ignore the negative symbol.
4. For the information about alarms, see section 12.1.26.
5. If the specified groove width is greater than the groove length, the system will automatically exchange them and rotate to the expected position.
6. The parameter C specifies the milling direction, like G182.
7. You need to use the command to enable spindle rotation before entering the cycle mode.

### Example

Conduct milling for the groove as shown in the figure below. Dimension of the groove:

Length: 60 mm; width: 40 mm; radius of the rounded arc: 8 mm; depth: 17.5 mm; angle between the groove and the X axis: 0 degree; finishing allowance on the groove margin: 0.75 mm; finishing allowance on the groove bottom: 0.2 mm; groove center: X60Y40; feed depth: 4 mm; tool radius 5 mm

Only rough machining is required.



*%0526*

*N10 G54 G90 G17*

*N20 T20*

*N30 M06*

*N40 M04 S600*

*N50 G00 X60 Y40 Z5*


*N60 G98G184R5Z-17.5K60W40X60Y40I8F120Q4E0.75O0.2D1V5*

*N70 M30*

### 12.1.22 Circular Groove Cycle (G185)

#### Description

This cycle is used for rough or finish machining for circular grooves.




#### Format

(G98/G99)G185R\_Z\_X\_Y\_I\_F\_Q\_E\_O\_H\_U\_P\_C\_D\_V\_

Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the groove bottom for absolute programming, or the incremental value from the groove bottom to the reference point R for incremental programming.
X	The center of the groove. The first axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
Y	The center of the groove. The second axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
I	The radius of the circular groove.
F	Milling speed during rough machining.
Q	The maximum feed depth for each time during rough machining (It is optional when Q= <i>groove depth-finishing allowance of the groove bottom</i> ).

E	The finishing allowance of the groove margin (It is optional when E=0).
O	The finishing allowance of the groove bottom (It is optional when O=0 ).
H	The maximum feed rate for finish machining (It is optional when H=Q).
U	The feed rate for finish machining (It is optional when U=F ).
P	The spindle speed for finish machining (It is optional when P= the spindle speed before cycle or the default spindle speed).
C	The direction for milling each groove (It is optional when C=3) 0: milling in the same direction with the spindle rotation; 1: milling in the reversed direction with the spindle rotation; 2: milling in G02 direction; 3: milling in G03 direction
D	Machining type (It is optional when D=1 ). 1: rough machining; 2: finish machining
V	Tool radius.

### Parameter graph



### Milling direction

Before entering the cycle mode, you need to use the command to enable spindle rotation. The system will calculate the reasonable milling direction based on the spindle rotation direction (M03/M04) and the command. See the table below:

Milling Direction (Parameter C)	Execute M03/M04 before the cycle	
	M03 spindle CW	M03 spindle CW
0: same direction	G03	G02
1: reversed direction	G02	G03

2: in G02 direction	G02	G02
3: in G03 direction	G03	G03
Left blank	G03	G03

### Operation procedure

1. Select a random start point from which the tool may move to each groove without any collision.

2. **Rough machining (D=1):**

Go to the center of the long side of the groove with G00(reserve the finishing allowance for the groove margin). The tool feeds downward with the depth specified by **Q**, and then conducts milling from the margin to the center for the upper part of the groove in the milling direction specified by **C**. Then backing to the same start position, the tool conducts milling from the groove surface to the groove bottom (reserve the finishing allowance).

**Finish machining (D=2):**

Go to the center of the long side of the groove with G00. (reserve the finishing allowance for the groove margin). The tool feeds downward with the depth specified by **H**, and then conducts milling from the center to the defined margin for the groove surface in the milling direction specified by **C**. After that, the tool goes back to the same point, moves to the surface for milling the finishing allowance, from the surface to the bottom in the direction specified by **C**

3. After machining, exit the tool to the initial plane or the reference plane with the command G98 or G99, and then the cycle ends.

1. For the information about alarms, see section 12.1.26.
2. The maximum feed depth for rough and finish machining is specified by the parameter **Q** or **H** respectively. If the groove depth is not divisible by **Q** or **H**, the final cut depth will be less than **Q** or **H**.
3. The values of I, E, O, Q, and H should be non-negatives. If the specified value is a negative value, the system will ignore the negative symbol.
4. The parameter **C** specifies the milling direction, like G182.

### Attention

**Example**

to enable spindle rotation before entering the cycle mode.

Conduct milling for the groove with the following specifications:

Circle center: X50 Y50; radius: 100 mm; depth: 50 mm; finishing allowance on the groove bottom and margin: 2 mm and 1.5 mm respectively; feed depth for rough machining: 4 mm; tool radius: 5 mm

*G54 X0 Y0 Z40*

*G17 G90*

*T10*

*M06*

*M03 S650*

*G99 G185 R0 Z-50 X50 Y50 I100 F300 Q4 E1.5 O2 V5D1*; rough machining

*X50 Y50 I100 P800 H1.5 D2*; finish machining

*M30*

5. You need to use the command



### 12.1.23 Face Milling Cycle (G186)

#### Description

This cycle can be used to conduct milling for any rectangular end face. The cycle for rough machining (perform multi-step reaming from surface to finishing allowance) and finish machining (finish the end face) is different.

#### Format


(G98/G99)G186R\_Z\_N\_W\_X\_Y\_I\_A\_F\_Q\_J\_O\_H\_K\_U\_P\_C\_D\_V\_

Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the groove bottom for absolute programming, or the incremental value from the groove bottom to the reference point R for incremental programming.
N	The first axis length of the workpiece.
W	The second axis length of the workpiece.
X, Y	The start position. The first axis coordinate of the current plane for absolute programming, or the incremental value to the current point during incremental programming.
I	The safety margin in the milling direction (It is optional when I= tool radius).
A	The angle formed by the long side of the end face and the first positive axis (It is optional when A=0 ).
F	Milling speed during rough machining.
Q	The maximum feed depth for each time during rough machining (It is optional when Q= <i>groove depth-finishing allowance of the groove bottom</i> ).
J	The milling width during rough machining (It is optional when J= <i>tool radius</i> x 80%).
O	The finishing allowance of the workpiece bottom (It is optional when O=0).
H	The maximum feed depth during finish machining (It is optional when H=Q).
K	The cutting width during rough machining (It is optional when K= <i>tool radius</i> x 80%).


U	The milling speed for finish machining (It is optional when $U=F$ ).
P	The spindle speed for finish machining (It is optional when $P = \text{the spindle speed before cycle or the default spindle speed}$ ).
C	The direction for milling each groove (It is optional when $C=3$ ) 0: milling in the same direction with the spindle rotation; 1: milling in the reversed direction with the spindle rotation; 2: milling in G02 direction; 3: milling in G03 direction
D	Machining type (It is optional and $D=1$ by default) • 1: rough machining • 2: finish machining
V	The tool radius.

- **C=0, D=1, bidirectional machining along the X axis**


### Basic description




- 
- 
- **C=1, D=1, bidirectional machining along the Y axis**



- **C=2, D=1, unidirectional machining along the X axis**



- **C=3, D=1, unidirectional machining along the Y axis**



Note: The figures above show the milling cycle (rough machining) only for the end face of the G17 plane. The cycle for G18/G19 is similar, and

that for the finish and comprehensive machining (D=2) is also similar.

### Attention

1. The values of N, W, I, O, Q, J, H and K should be non-negatives. If the specified value is a negative value, the system will ignore the negative symbol.
2. For the feed width (specified by J/K) or the feed depth (specified by Q/H), the final cut will be less than the feed width or the feed depth if the feed rate is not divisible by them.
3. Before executing the cycle, use the command to enable the spindle rotation.
4. For the information about alarms, see section 12.1.26.

### Example

end face, with the following end dimension and relative parameters:

Start plane: 10 mm; reference plane: 2 mm, only rough machining, each milling width: 10 mm; each feed depth: 6 mm; total milling depth: 11 mm; milling start point (100, 100); end face dimension: 60 mm x 40 mm; safety margin in the milling direction: 5 mm; bidirectional milling along the X axis; feed rate on the surface: 500 mm/min; tool radius: 5 mm.

*%1018*

*N10 G54 X0 Y0 Z20*

*N20 G17 G90*

*N30 T10*

*N40 M06*

*N50 M03 S650*

*N60 G00 X0 Y0 Z20*

*N70 G99G186 Z-11 R0 N60 W40 X100 Y100 I5 F500 Q6 J10 V5*


*N80 M30*

Conduct milling for a rectangular

### 12.1.24 Rectangular Boss Cycle (G188)

#### Description

This cycle is used to conduct machining for rectangular boss of arbitrary size on a plane. The rectangular boss may have rounded corners. You may select roughing, finishing or comprehensive machining as required.




#### Format

(G98/G99)G188R\_Z\_N\_W\_X\_Y\_J\_K\_I\_A\_F\_Q\_E\_O\_H\_U\_P\_C\_D\_V\_


Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the boss bottom for absolute programming, or the incremental value from the boss bottom to the reference point R for incremental programming.
N	The length of the rectangular boss.
W	The width of the rectangular boss.
X	The center of the rectangular boss. The first axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
Y	The center of the rectangular boss. The second axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
J	The length of the rough rectangular boss.

K	The width of the rough rectangular boss.
I	The radius of the rounded corner in the rectangular boss (It is optional when $I=W/2$ ).
A	The angle formed by the long side of the rectangular boss and the first positive axis (It is optional when $A=0$ ).
F	The milling speed for rough machining.
Q	The maximum feed depth for each rough machining (It is optional when $Q = \text{groove depth} - \text{finishing allowance at the groove bottom}$ ).
E	The finishing allowance at the boss margin (It is optional when $E=0$ ).
O	The finishing allowance at the boss bottom (It is optional when $O=0$ ).
H	The maximum feed depth for finish machining (It is optional when $H=Q$ ).
U	The feed speed for finish machining (It is optional when $U=F$ ).
P	The spindle speed for finish machining (It is optional when $P = \text{the spindle speed before cycle or the default spindle speed}$ ).
C	The milling direction for the boss (It is optional when $C=3$ ). 0: milling in the same direction with the spindle rotation; 1: milling in the reversed direction with the spindle rotation; 2: milling in G02 direction; 3: milling in G03 direction
D	Machining type (It is optional and $D=1$ by default). 1: rough machining; 2: finish machining
V	Tool radius.

### Parameter graph




### Semicircle path for entering and existing



To ensure the tool smoothly moves into the workpiece, the cycle automatically adds a semicircle path when entering and exiting the workpiece. The semicircle radius is determined by the cycle parameters, and the semicircle direction is opposite to the milling direction. For example, if the milling direction is specified by G2, then the added semicircle is in the direction of G3.

### Dimension of rough boss



For the machining of workpiece with prior casting, the rough size of rectangular boss, which is symmetrical to the size of the boss with the center(X,Y), may be taken into account.

### Milling direction

Before entering the cycle mode, you need to use the command to enable spindle rotation. The system will calculate the reasonable milling direction based on the spindle rotation direction (M03/M04) and the commands. See the table below:

Milling Direction	Execute M03/M04 before the cycle
-------------------	----------------------------------

(Parameter C)	M03 spindle CW	M03 spindle CW		
0: same direction	G03	G02		
		1: reversed direction	G02	G03
		2: in G02 direction	G02	G02
		3: in G03 direction	G03	G03
		Left blank	G03	G03

### Operation procedure

1. Selecting a start point, which must be to the right of the boss in the first positive axis direction of the plane. You need to consider the automatically added semicircle during the cycle.

#### 2. **Rough machining (D=1):**

Go to the reference plane over the long side of the boss with G00, feed downward with the specified depth, and then in the milling direction, enter the workpiece contour through a semicircle path to conduct milling from the surface to the finishing allowance of the margin, and exit the workpiece contour through a semicircle path in the opposite direction. Use G00 to rapidly move to the start point, and then conduct milling from the groove surface to the finishing allowance of the bottom.

#### **Finish machining (D=2):**

Go to the reference plane over the long side of the boss with G00, feed downward with the specified depth, and then in the milling direction, enter the workpiece contour through a semicircle path to machine the finishing allowance of margin. After that, exit the workpiece contour through a semicircle path in the opposite direction. Use G00 to rapidly move to the start point, feed downward again to machine the finishing allowance of the bottom.

3. After completing the machining, exit the tool to the initial point or the reference point based on the current modal G98 or G99, and then the cycle ends.

### Attention

1. For the information about alarms, see section 12.1.26.
2. The values of W, J, K, I, O, Q and H should be non-negatives. If the specified value is a negative value, the system will ignore the negative symbol.




3. For the maximum feed depth for rough and finish machining (specified by **Q** and **H** respectively), if the feed rate is not divisible, the final cut will be less than **Q** or **H**.
4. Before executing the cycle, use the command to enable the spindle rotation.
5. If the specified width is greater than the length, the system will automatically exchange them and rotate to the expected position.

### Example

Conduct milling for the boss as shown in the figure below:

Dimension: 60 mm x 40 mm; rough dimension: 80 mm x 50 mm; tool radius: 3 mm



*%1019*

*G17 G54 G90*

*T10*

*M06*

*M03 S650*


*G98 G188 R2Z-17.5N60W40X80Y60J80K50I15A10F200Q11E2O1V3*

*M30*

## 12.1.25 Circular Boss Cycle (G189)

### Description

The cycle is used to conduct machining for circular boss with arbitrary size.




### Format

**(G98/G99)G189R\_Z\_X\_Y\_I\_J\_F\_Q\_E\_O\_H\_U\_P\_C\_D\_V\_**

Parameter	Description
R	The coordinate value of the reference point R for absolute programming, or the distance from reference point R to the initial plane for incremental programming.
Z	The coordinate value of the boss bottom for absolute programming, or the incremental value from the boss bottom to the reference point R for incremental programming.
X	The center of the rectangular boss. The first axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
Y	The center of the rectangular boss. The second axis coordinate of the current plane for absolute programming, and the incremental value to the start point for incremental programming.
I	The radius of the circular boss.
J	The radius of the rough circular boss.
F	The milling speed for rough machining.

Q	The maximum feed depth for each rough machining (It is optional when $Q = \text{groove depth} - \text{finishing allowance at the groove bottom}$ ).
E	The finishing allowance at the boss margin (It is optional when $E=0$ ).
O	The finishing allowance of the boss bottom (It is optional when $O=0$ ).
H	The maximum feed depth for finish machining (It is optional when $H=Q$ ).
U	The feed speed for finish machining (It is optional when $U=F$ ).
P	The spindle speed for finish machining (It is optional when $P = \text{the spindle speed before cycle or the default spindle speed}$ ).
C	The milling direction for the grooves (It is optional when $C=3$ ). 0: milling in the same direction with the spindle rotation; 1: milling in the reversed direction with the spindle rotation; 2: milling in G02 direction; 3: milling in G03 direction
D	Machining type (It is optional when $D=1$ ) 1: rough machining; 2: finish machining
V	Tool radius.

### Semicircle path for entering and existing



Similar as G188, to ensure the tool smoothly moves into the workpiece, the cycle automatically adds a semicircle path when entering and exiting the workpiece. The semicircle radius is automatically determined by the cycle. The direction of the semicircle is opposite to that of milling.

**Dimension of rough boss**

Similar as G188, you may set the dimension of the rough boss, with the center (X, Y).

**Milling direction**

Before entering the cycle mode, you need to use the command to enable spindle rotation. The system will calculate the reasonable milling direction based on the spindle rotation direction (M03/M04) and the commands. See the table below:

<b>Milling Direction (Parameter C)</b>	<b>Execute M03/M04 before the cycle</b>	
	<b>M03 spindle CW</b>	<b>M04 Spindle CCW</b>
0: same direction	G03	G02
1: reversed direction	G02	G03
2: in G02 direction	G02	G02
3: in G03 direction	G03	G03
Left blank	G03	G03

**Operation procedure**

1. Select a start point, which must be to the right of the boss in the first positive axis direction of the plane. You need to consider the automatically added semicircle during the cycle.
2. **Rough machining (D=1):**

Go to the reference plane over the long side of the boss with G00, feed downward with the specified depth, and then in the milling direction, enter the workpiece contour through a semicircle path to conduct milling from the surface to the finishing allowance of the margin, and exit the workpiece contour through a semicircle path in the opposite direction. Use G00 to rapidly move to the start point, and then conduct milling from the groove surface to the finishing allowance of the bottom.

**Finish machining (D=2):**

Go to the reference plane over the long side of the boss with G00, feed downward with the specified depth, and then in the milling direction, enter the workpiece contour through a semicircle path to machine the finishing allowance of margin. After that, exit the workpiece contour through a semicircle path in the opposite direction. Use G00 to rapidly move to the start point, feed downward again to machine the finishing allowance of the bottom.

3. After **completing** the machining, exits the tool to the initial point or the reference point based on the current modal G98 or G99, and then the cycle ends.


### Attention

1. For the information about alarms, see section 12.1.26.
2. The values of J, K, I, E, O, Q and H should be non-negatives. If the specified value is a negative value, the system will ignore the negative symbol.
3. For the maximum feed depth for rough and finish machining (specified by **Q** and **H** respectively), if the feed rate is not divisible by them, the final cut will be less than **Q** or **H**.
4. Before executing the cycle, use the command to enable the spindle rotation.
5. If the specified width is greater than the length, the system will automatically exchange them and rotate to the expected position.

### Example

Conduct milling for the boss as shown in the figure below:

Rough boss radius: 55 mm; each feed depth: 10 mm; tool radius: 5 mm



*%I020*

*G17 G54 G90*

*T10*

*M06*

*M03 S650*

*G98G189 R2Z-20X60Y70I25J27.5F200Q10E1O1V5*

*M30*

### 12.1.26 Alarm Information for Milling Cycle

During fixed cycle, if the system detects an error, an alarm will be reported, and the current cycle execution will be stopped. After you modify the program, the system will proceed to run the ongoing cycle.

This section describes the alarms that may be reported during the milling cycle, and provides alarm analysis and suggestions, based on which you may modify the program.

Alarm No.	Alarm Text	Source	Reasons and Suggestions
800	"MILLING CYCLE: TOOL OFFSET NUMBER NOT DEFINED."	G181 G182 G183 G184 G185 G186 G188 G189	The tool radius <b>V</b> is not specified before executing the cycle.
801	"MILLING CYCLE: REFERENCE PLANE NOT DEFINED."	G181 G182 G183 G184 G185 G186 G188 G189	This alarm is reported if <b>R</b> is not specified in the program and the cycle cannot detect the modal <b>R</b> value. This parameter should be specified as it is required when the groove depth is defined in the incremental value or the tool exits to the R plane after the cycle is completed.
802	"MILLING CYCLE: POSITION OF BOTTOM OF GROOVE NOT DEFINED."	G181 G182 G183 G184 G185 G186 G188 G189	The groove bottom position must be specified; otherwise, the groove depth cannot be defined.
803	"MILLING CYCLE: NUMBER OF GROOVE IS SET TO ZERO."	G181 G182 G183	This alarm is reported when the groove number is set to <b>0</b> . The number of grooves should be an integer greater than <b>0</b> .

804	"MILLING CYCLE: GROOVE LENGTH DEFINED TOO SMALL."	G182	For the groove with user-defined width, the length should be greater than the width; otherwise, this alarm is reported.
805	"M-CYC: TOOL RADIUS TOO MUCH."	G181 G182 G183 G184 G185 G186 G188 G189	This alarm is reported when the tool radius is greater than the defined groove length. You may select a milling tool with relative smaller radius for the milling.
806	"MILLING CYCLE: CENTER POSITION OF ARC MADE OF GROOVES."	G181 G182 G183	This alarm is reported if the arc center is not specified in the program and no related modal position is detected by the cycle.
807	"M-CYC: AR MADE OF GV NOT DEFINED."	G181 G182 G183	If there is no modal arc radius value, the radius should be specified in this line; otherwise, this alarm is reported.
808	"M-CYC: INTERFER BTWN GROOVE"	G181 G182 G183	Because of the angle formed by the tool radius and the groove, there may be interference among the machined grooves, which may affect the groove contour shape. The system conducts the interference detection before the cycle and provides prompts for you.
809	"M-CYC: GV NO.&DEF OF AI CONFLICTS"	G181 G182 G183	This alarm is reported when the groove number or the angle between grooves is defined improperly, e.g. <i>groove number x the angle between grooves &gt; 360 degrees</i> .
810	"The maximum feed depth for each time is over large."	G181 G182 G183 G184 G185 G186 G188 G189	This alarm is reported when the maximum feed depth for each time ( <b>Q</b> ) is greater than the groove depth. You may decrease the value of <b>Q</b> .

811	"M-CYC: ROTATE SPDL BEF CYC RUN."	G181 G182 G183 G184 G185 G186 G188 G189	This alarm is reported when the spindle does not rotate before the cycle. The spindle status is detected before the cycle is executed.
812	"CG OR BOSS CP NOT DEFINED."	G184 G185 G188 G189	This alarm is reported when the center of the circular groove or boss is not specified.
813	"M-CYC: CG OR BOSS R NOT DEFINED."	G185 G189	This alarm is reported when the radius of the circular groove or boss is not specified.
814	"M-CYC: F.ALLOW OF MARGIN MUCH."	G182 G183 G184 G185 G188 G189	The reserved finishing allowance for the margin is too large to complete. You may decrease the finishing allowance.
815	"M-CYC: F.ALLOW OF BOTTOM MUCH."	G182 G183 G184 G185 G186 G188 G189	The reserved finishing allowance for the bottom is too large to complete. You may decrease the finishing allowance.
816	"M-CYC: MAX F.DEF OF FINISH MUCH."	G182 G183 G184 G185 G186 G188 G189	For finish machining, this alarm is reported if the maximum feed depth for each time ( <b>H</b> ) is greater than the groove depth. You may decrease the value of <b>H</b> .



817	"M-CYC: DIR MILLING ERROR."	G182 G183 G184 G185 G186 G188 G189	This alarm is reported if the defined milling direction is not supported by the system, that is the value specified for <b>C</b> is not within the allowed range ( <b>0, 1, 2, 3</b> ).
818	"M-CYC: DEF OF MACHING TYPE ERROR."	G182 G183 G184 G185 G186 G188 G189	This alarm is reported if a milling type not supported by the system is defined, that is the value specified for <b>D</b> is not within the allowed range ( <b>1, 2</b> ).
819	"M-CYC: W.SIZE NOT DEFINED."	G186	For G186, the dimension of the end face should be specified for the workpiece to be machined, e.g. length and width; otherwise, this alarm is reported.
820	"M-CYC: ST PT OF MIL NOT DEFINED."	G186	For G186, the start point for the milling should be specified, generally the lower left corner of the workpiece on the machining plane; otherwise, this alarm is reported.
821	"M-CYC: SAFETY LMT TOO SMALL."	G186	For G186, the safety margin should be specified for a good milling effect. Its value cannot be lower than the radius of the milling tool.
822	"M-CYC: WID OF RM TOO MUCH."	G186	For G186, the milling width for rough machining cannot be greater than the tool diameter.
823	"M-CYC: WID OF RM TOO MUCH."	G186	For G186, the milling width for finish machining cannot be greater than the tool diameter.
824	"M-CYC: WP SIZE ON BOSS NOT DEF."	G188 G189	For G189 and G188, the workpiece dimension should be defined; otherwise, this alarm is reported.

826	"M-CYC: GV/BOSS LEN/WID NOT DEF."	G181 G182 G183 G184 G188	This alarm is reported if the groove length or width is not specified in this line or the related modal value of the groove length cannot be detected.
829	"M-CYC: CR OF REC.GV/B OSS MUCH."	G184 G188	For 184 or 188, the rounded corner can be defined, but the arc radius cannot be greater than <i>long side</i> / 2; otherwise, this alarm is reported.
830	"M-CYC: WP SIZE ON BOSS<MA C SIZE."	G188 G189	For G189 and G188, the rough boss dimension should be greater than the contour dimension; otherwise, this alarm is reported.
873	"M-CYC: TOOL RAD CANNOT BE 0."	G181 G182 G183 G184 G185 G186 G188 G189	The parameter <b>V</b> indicates the compensation number in the tool compensation table. The value entered in the compensation number is the tool radius. This value cannot be zero; otherwise, this alarm is reported.
874	"The finishing allowances is not defined for the finishing."	G182 G183 G184 G185 G186 G188 G189	This alarm is reported when the finishing allowances of groove wall and groove bottom are not defined simultaneously or both are specified as 0 during finish machining.

## 12.2 Simple Cycle for Turning Machines (T)

For turning machines, there are five simple cycles. See the table below:

G Code	Functions
G80	Inner (outer) diameter cutting cycle
G81	End-face cutting cycle
G82	Thread cutting cycle
G74	End-face deep-hole drilling cycle
G75	Outer diameter grooving cycle

The cycle is to use a G code program block to complete the machining of multiple blocks, to simplify the programs.

### Attention

1. The cycle described in this section can only be used for turning machines.
2. The commands G83, G87, G84 and G88 have no positioning function. To conduct positioning, you need to execute G01 or G00 outside the fixed cycle.

### 12.2.1 Inner (Outer) Diameter Cutting Cycle (G80)


This cycle can be used for inner (outer) diameter cutting of cylindrical and conical surfaces.

#### Cylindrical surface cutting

**G80 X\_<sub>U</sub> Z\_<sub>W</sub> F\_**

Parameter	Description
X/U Z/W	The cutting end point C at the workpiece coordinate system for absolute value programming; The relative distance from the cutting end point C to the cycle start point A for the incremental value programming. Use U and W to express them in the blueprint and the direction of path 1 and 2 determine whether it is a positive or a negative value.
F	Feed speed (indicates to move at the speed specified by F) (mm/min)


The tool moves along the path A→B→C→D→A. See the figure below:



**G80 X\_/\_U\_/\_Z\_/\_W\_/\_I\_/\_F\_/\_****Conical surface cutting**


Parameter	Description
X/U Z/W	The cutting end point C at the workpiece coordinate system for absolute value programming; The relative distance from the cutting end point C to the cycle start point A for the incremental value programming. Use U and W to express them in the blueprint and the direction of path 1 and 2 determine whether it is a positive or a negative value.
I	The radius difference between the cutting start point B and the end point C. Either in the absolute value programming or in the incremental value programming, the sign (+ or -) of the difference value determines whether the value of I is positive or negative.
F	Feed speed (indicates to move at the speed specified by F) (mm/min)

The tool moves along the path A→B→C→D→A. See the figure below:



Conduct machining for the workpiece as shown in the figure below: use G80 to conduct rough and finish machining for simple cylindrical parts.

### Example 1



%3320

N1 T0101

N2 M03 S460

N3 G00 X90 Z20

N4 X40 Z3

N5 G80 X31 Z-50 F100


N6 G80 X30 Z-50 F80

N7 G00 X90 Z20

N8 M30

### Example 2:

Conduct machining for the workpiece as shown in the figure below: use G80 to conduct rough or finish machining for simple conical parts.



*%3321*

*N1 T0101*

*N2 G00 X100Z40 M03 S460*

*N3 G00 X40 Z5*

*N4 G80 X31 Z-50 I-2.2 F100*

*N5 G00 X100 Z40*

*N6 T0202*

*N7 G00 X40 Z5*

*N8 G80 X30 Z-50 I-2.2 F80*

*N9 G00 X100 Z40*

*N10 M05*

*N11 M30*

### 12.2.2 End-face cutting cycle (G81)


This cycle can be used for end face cutting and conical face cutting.

#### End face cutting

#### G81 X\_/U\_Z\_/W\_F\_

Parameter	Description
X/U Z/W	The cutting end point C at the workpiece coordinate system for the absolute value programming; The relative distance from the cutting end point C to the cycle start point A for the incremental value programming. Use U and W to express them in the blueprint and the direction of path 1 and 2 determines whether it is a positive or a negative value.
F	Feed speed (indicates to move at the speed specified by F) (mm/min)

The tool moves along the path A→B→C→D→A. See the figure below:



#### Conical face cutting


#### G81 X\_/U\_Z\_/W\_K\_F\_

Parameter	Description
X /U Z/W	The cutting end point C at the workpiece coordinate system for absolute value programming; The relative distance from the cutting end point C to the cycle start point A for the incremental value programming. Use U and W to express them in the blueprint and the direction of path 1 and 2 determines whether it is a positive or a negative




	value.	K	The relative distance from the cutting start point B to the end point C along the Z axis.
		F	Feed speed (indicates to move at the speed specified by F) (mm/min)

The cutting process is along the path A→B→C→D→A. See the figure below:



### Example

Conduct machining for the workpiece as shown in the figure below: use G81 programming; The dotted lines indicate the workpiece.



%3323

N1 T0101; Establish the coordinate system, and choose tool 1

N2 G00 X60 Z45; Move to the cycle start point

N3 M03 S460; Rotate the spindle in the clockwise direction

N4 G81 X25 Z31.5 K-3.5 F100;  
Conduct the first cycle with tool depth 2 mm

N5 X25 Z29.5 K-3.5; Each tool depth is 2 mm.

N6 X25 Z27.5 K-3.5; Conduct each cutting at the start point; 5 mm away from the outer circle of workpiece; the value of K is -3.5.

N7 X25 Z25.5 K-3.5; Conduct the fourth cycle with tool depth 2 mm

N8 M05; Stop the spindle

N9 M30; End the main program and reset.

### 12.2.3 Thread Cutting Cycle (G82)


This cycle can be used for machining straight thread or conical thread.

#### Straight thread cutting cycle

**G82 X\_/U\_Z\_/W\_R\_E\_C\_P\_F\_**

Parameter	Description
X /U Z/W	The thread end point C at the workpiece coordinate system for absolute value programming; The relative distance from the thread end point C to the cycle start point A for the incremental value programming. Use U and W to express them in the blueprint and the direction of path 1 and 2 determines whether it is a positive or a negative value.
R E	The retreat of tailstock for thread cutting. <b>R</b> and <b>E</b> are vectors. <b>R</b> indicates the retreat along the Z axis direction, and <b>E</b> indicates the retreat along the X axis direction. A positive value indicates the retreat towards the positive X/Z direction, while a negative value indicates the retreat towards the negative X/Z direction. R and E can be left blank, which indicates that there is no tailstock retreat function.
C	The number of threads. The value <b>0</b> or <b>1</b> indicates single thread cutting.
P	During the single thread cutting, it indicates the spindle rotation angle between the spindle reference pulse and the starting point of the cutting (default value <b>0</b> ); During multi-thread cutting, it indicates the spindle rotation angle between the cutting start points of the adjacent thread.
F	Metric thread lead (mm/r)

The tool moves along the path A→B→C→D→A. See the figure below:




### Conical thread cutting cycle

**G82 X\_/U\_Z\_/W\_I\_R\_E\_C\_P\_F\_**

Parameter	Description
X /U Z/W	The thread end point C at the workpiece coordinate system for absolute value programming; The relative distance from the thread end point C to the cycle start point A for the incremental value programming. Use U, W to express them in the blueprint and the direction of path 1 and 2 determines whether it is a positive or a negative value.
I	The difference of radius between thread starting point B and the thread end C. Either in the absolute value programming or in the incremental value programming, the sign (+ or -) of the difference value determines whether the value of I is positive or negative.
R E	The retreat of tailstock for thread cutting. R and E are vectors. R indicates the retreat along the Z axis direction, and E indicates the retreat along the X axis direction. R and E can be left blank, which indicates that there is no tailstock retreat function.
C	The number of threads. The value 0 or 1 indicates single thread cutting.

P	During the single thread cutting, it indicates the spindle rotation angle between the spindle reference pulse and the starting point of the cutting (default value 0); During multi-thread cutting, it indicates the spindle rotation angle between the cutting start points of the adjacent thread.
F	Metric thread lead (mm/r)

The tool moves along the path  $A \rightarrow B \rightarrow C \rightarrow D \rightarrow A$ .




#### Attention

1. If the retreat function is required, the symbol of the **R** or **E** value ("+" / "-") should be coordinated with the thread cutting direction. Otherwise, it may damage the threads. In addition, you can specify only the **R** value without specifying **E**, but if **E** is specified, **R** must be specified.
2. Similar as G32 thread cutting, in the feed hold state, this cycle can stop the movement only after all operations specified by this cycle are completed.

**Example**

Conduct machining for the workpiece shown in the figure below with G82 programming. The blank shape has been worded.



%3324

*N1 G54 G00 X35 Z104;* Select coordinate system G54, to the cycle start point

*N2 M03 S300;* Rotate spindle in the CW direction at 300 r/min

*N3 G82 X29.2 Z18.5 C2 P180 F3;* The first cycle thread cutting with depth 0.8 mm

*N4 X28.6 Z18.5 C2 P180 F3;* The second cycle thread cutting, with depth 0.4 mm


*N5 X28.2 Z18.5 C2 P180 F3;* The third cycle thread cutting with depth 0.4 mm

*N6 X28.04 Z18.5 C2 P180 F3;* The forth cycle thread cutting with depth 0.16 mm

*N7 M30;* Stop spindle, end the main program, and reset

### 12.2.4 End-Face Deep-Hole Drilling Cycle (G74)

This cycle is used to conduct end-face deep-hole drilling. See the figure below:



#### Format


**G74 X\_/U\_Z\_/W\_ Q(ΔK)\_R(e)\_ I(i)\_P(p)\_**

Parameter	Description
X/U	For the absolute value programming, this value is the coordinates of the end point at the hole bottom along the X axis in the workpiece coordinate system; for the incremental value programming this value is the relative distance from the end point at the hole bottom to the start point of the cycle. Use U to express it in the blueprint. This value is optional.
Z/W	For the absolute value programming, this value is the coordinates of the end point at the hole bottom along the Z axis in the workpiece coordinate system; for the incremental value programming this value is the relative distance from the end point at the hole bottom to the start point of the cycle. Use W to express it in the blueprint.
R	The retract amount along the Z axis. This value must be a positive value, and is optional.
Q	The feed depth which must be positive.

I	The feed width for wide-hole drilling. This value must be a positive value, and is optional.
P	The retract amount along the X axis. When <b>I</b> is specified, <b>P</b> must be a positive value. When <b>I</b> is not specified, <b>P</b> may be a positive or a negative value. This parameter is optional.

**Example**

Conduct end-face deep hole drilling cycle with G74.



*%I234*

*T0101*

*M03S500*

*G01 X0 Z10F2000*


*G74 X-10Z-60R1Q5I3P1*

*M30*



### 12.2.5 Outer Diameter Grooving Cycle (G75)

This cycle is used to conduct grooving for the outer diameter of the workpiece. See the figure below:



## Format


**G75X\_/U\_Z\_/W\_ Q( $\Delta$ K)\_R(e)\_ I(i)\_P(p)\_**

Parameter	Description
X/U	For the absolute value programming, this value is the coordinates of the end point at the hole bottom along the X axis in the workpiece coordinate system; for the incremental value programming this value is the relative distance from the end point at the hole bottom to the start point of the cycle. Use U to express it in the blueprint.
Z/W	For the absolute value programming, this value is the coordinates of the end point at the hole bottom along the Z axis in the workpiece coordinate system; for the incremental value programming this value is the relative distance from the end point at the hole bottom to the start point of the cycle. Use W to express it in the blueprint. This value is optional.
R	The retract amount along the X axis. This value must be a positive value, and is optional.
Q	The feed depth which must be positive.

I	The groove width. This value must be a positive value, and is optional.
P	The retract amount along the Z axis. When <b>I</b> is specified, <b>P</b> must be a positive value. When <b>I</b> is not specified, <b>P</b> may be a positive or negative value. It is optional.

### Example

Conduct outer diameter grooving cycle with G75.



*%I234*

*T0101*

*M03S500*

*G01 X50 Z50F2000*

*G75 X10Z60R1Q5I3P2*

*M30*

## 12.3 Fixed Cycle for Drilling of Turning Machines (T)

**Commands of fixed cycle for drilling of turning machines**

G Code	Description
G83	Axial drilling cycle
G87	Radial drilling cycle
G84	Axial rigid tapping cycle
G88	Radial rigid tapping cycle

**Attention**

The commands in this section have no positioning function. To conduct positioning, you need to specify G01 or G00 outside the fixed cycle.

### 12.3.1 Axial Drilling Cycle (G83)/Radial Drilling Cycle (G87)


This cycle is used for the high-speed deep-hole drilling, with the cutting feed speed for drilling, specified distance for tool exit, and periodically repeat until the hole bottom. The chips is discharged out of the hole during tool exit.

#### Format


**G87X(U)\_R\_Q\_K\_P\_F\_H\_**

Parameter	Description
X/Z	Hole bottom coordinates.
R	The distance from the initial plane to the R plane.
Q	The cutting depth for each time.
P	The duration when the tool remains at the hole bottom.
F	Feed speed.
K	Tool exit distance.
H1	Exit with the specified distance K.
H2	Exit to the R point.
H3	Directly drilling to the hole bottom.


- H1 Mode**



- **G83Z(W)\_R\_Q\_K\_P\_F\_H\_**
- **H2 mode**



- **H3 mode**



**Example**

```

%1111

g54x0z50

g98g83z-10r10q5k2p1000f200h1
g99g83z-10r10q5k2p1000f200h1
g0x0z50

g98g83z-10r10q5k2p1000f200h2
g99g83z-10r10q5k2p1000f200h2
g0x0z50

g98g83z-10r10q5k2p1000f200h3
g99g83z-10r10q5k2p1000f200h3
m30

%1111

g54z0x50

g98g87x-10r10q5k2p1000f200h1
g99g87x-10r10q5k2p1000f200h1
g0z0x50

g98g87x-10r10q5k2p1000f200h2
g99g87x-10r10q5k2p1000f200h2
g0z0x50

g98g87x-10r10q5k2p1000f200h3
g99g87x-10r10q5k2p1000f200h3
m30

```

**Attention**

When  $H=1$ , the tool exits with the distance specified by **K**. When the tapping is in the H1 and H2 mode, the cutting depth **Q** and retract amount **K** must be specified.

### 12.3.2 Axial Rigid Tapping Cycle (G84)/Radial Rigid Tapping Cycle (G88)

This cycle is used for tapping. In this cycle, the spindle rotates in the counter clockwise direction when it reaches the hole bottom.

#### Format 1


**G84 Z(W)\_R\_P\_Q\_E\_J\_K\_F\_H\_**

Parameter	Description
Z	Hole bottom coordinates.
R	The distance from the initial plane to the R plane.
P	The duration when the tool remains at the hole bottom.
F	Feed speed.
Q	Cutting depth.
K	Retract amount
E1	Clockwise tapping.
E2	Counter clockwise tapping
J1	Tapping with the first spindle C.
J2	Tapping with the second spindle A.
H1	Exit with the distance specified by <b>K</b> .
H2	Back to the point R.
H3	Directly back to the hole bottom.

#### Format 2

**G88X(U)\_R\_E\_Q\_K\_H\_P\_F\_**(Tapping with the second spindle A only)

Parameter	Description
E1	Clockwise tapping.
E2	Counter clockwise tapping
Q	Cutting depth.
K	Retract amount
H1	Exit with the distance specified by <b>K</b> .
H2	Back to the point R.
H3	Directly back to the hole bottom.

**Example**

*M3 S1=1000; Rotate No. 1 spindle*

*G0X50Z50*

*M5*

*G84Z-10R20P1000F1000H1*

*M33 S2=1000; Rotate No. 2 spindle*

*G4P1000*

*M55*

*G84Z-10R20P1000F1H2*

*G88X-10R20P1000F1*

*M30*



## 12.4 Compound Cycle for Turning Machines (T)

---

This fixed cycle simplifies programming by using the finishing shape data to describe the roughing tool path. This system provides four combined cycle:

G71: Inner (outer) diameter roughing compound cycle

G72: End-face roughing compound cycle

G73: Closed cutting compound cycle

G76: Thread cutting compound cycle

Through this instruction, you need to specify only the finishing path and roughing cutting depth, the system will automatically calculate the roughing path and the cutting count.

### Attention

This cycle is used only for turning machines.

For G71, G72, and G73 compound cycle, pay attention to the following items:

1. The program block specified by **P** should have the commands of G00 or G01 in group 01; otherwise, an alarm will be reported.
2. In the MDI mode, the compound cycle command cannot be executed.
3. In the compound cycle G71, G72 and G73, the blocks of which sequence number is specified by **P** or **Q** should not have M98 subprogram calling or M99 subprogram returning command.
4. In the compound cycle G71, G72 and G73, tool compensation cannot be executed for the blocks of which sequence number is specified by **P** or **Q**.

### 12.4.1 Inner (Outer) Diameter Roughing Compound Cycle (G71)

This cycle can be divided into inner (outer) diameter roughing compound cycle with groove and without groove.


Inner (outer) diameter roughing compound cycle without groove

**G71 U( $\Delta d$ ) R(r) P(ns) Q(nf) X( $\Delta x$ ) Z( $\Delta z$ ) F(f) S(s) T(t);**

Parameter	Description
U	Cutting depth (each cutting amount). The symbol ("+" "-") is not specified with the value. The direction is determined by the vector AA'.
R	Each retract amount.
P	The first program block sequence number for finish machining (AA' in the figure below).
Q	The last program block sequence number for finish machining (B'B in the figure below).
X	Finishing allowance in the X axis direction.
Z	Finishing allowance in the Z axis direction.
F S T	During roughing, the F, S and T in G71 are valid, while in finishing, the F, S and T between the <b>ns</b> program block and <b>nf</b> program block are valid.


#### Description

This cycle is used for the roughing as shown in the figure below, and the tool returns to the cycle start point. The finishing path A→A'→B'→B is executed based on the command order.



**XZ symbol ("+" / "-")**


In the cutting cycle G71, the cutting feed direction is parallel to the Z axis. The symbol of X ( $\Delta U$ ) and Z ( $\Delta W$ ) is as shown below, where "+" indicates a positive direction along the axis, "-" indicates the negative direction along the axis.

**Attention**

1. In the last program block of the finishing path with Q, there must be X axial movements.
2. In outer diameter roughing compound cycle G71, the cycle start point must be the highest point, and in the inner diameter of the roughing compound cycle, it must be the lowest point.

**Example 1**

Use outer diameter roughing compound cycle to create a machining program for the workpiece shown as below: cycle start point: A (46, 3); cutting depth 1.5 mm (radius); retract amount: 1 mm; finishing allowance along the X axis: 0.4 mm; finishing allowance along the Z axis: 0.1 mm. The dotted lines indicate the workpiece.



%3325

T0101; Define coordinate system, and select No. 1 tool.

N1 G00 X80 Z80; Go to the program start point

N2 M03 S400; Spindle rotates at 400r/min

N3 G01 X46 Z3 F100; The tool goes to the cycle start point.

N4 G71 U1.5 R1 P5 Q14 X0.4 Z0.1; Roughing amount: 1.5 mm; finishing amount: X0.4 mm, Z0.1 mm

N5 G00 X0; Start finishing contour , go to the extended line of chamfer

N6 G01 X10 Z-2; Conduct finishing for chamfer of  $2 \times 45$  degrees

N7 Z-20; Conduct finishing for  $\Phi 10$  outer circle

N8 G02 U10 W-5 R5; Conduct finishing for R5 arc

N9 G01 W-10; Conduct finishing for  $\Phi 20$  outer circle

N10 G03 U14 W-7 R7; Conduct finishing for R7 arc

N11 G01 Z-52; Conduct finishing for  $\Phi 34$  outer circle

N12 U10 W-10; Conduct finishing for outer cone

N13 W-20; Conduct finishing for  $\Phi 44$  outer circle

N14 U1; End finishing

N15 X50; Exit the machined face


N16 G00 X80 Z80; Back to the tool exchange position

N17 M05; Stop spindle

*N18 M30 ; End the main program and reset*

### Example 2

Use inner diameter roughing compound cycle to create a machining program for the workpiece shown as below: cycle start point: A (6, 5); cutting depth: 1.5 mm (radius); retract amount: 1 mm; finishing allowance along the X axis: 0.4 mm; finishing allowance along the Z axis: 0.1mm. The dotted lines indicate the workpiece.



*%3326*

*N1 T0101;* Select No.1 tool, and define the coordinate system

*N2 G00 X80 Z80;* Go to the program start point or tool exchange position.

*N3 M03 S400;* Rotate Spindle in the clockwise direction at 400r/min

*N4 X6 Z5;* Go to the cycle start point

*G71U1R1P8Q16X-0.4Z0.1 F100;* Start roughing

*N5 G00 X80 Z80;* After roughing, go to the tool exchange position

*N6 T0202;* Change to No.2 tool, and define the coordinate system

*N7 G00 G41X6 Z5;* Add tool nose arc radius compensation to No.2 tool

*N8 G00 X44;* Start finishing , go to the outer circle of Φ44

*N9 G01 Z-20 F80;* Conduct finishing for the outer circle of Φ44

*N10 U-10 W-10;* Conduct finishing for the outer cone

*N11 W-10*; Conduct finishing for the outer circle of  $\Phi 34$

*N12 G03 U-14 W-7 R7*; Conduct finishing for the arc of R7

*N13 G01 W-10*; Conduct finishing for the outer circle of  $\Phi 20$

*N14 G02 U-10 W-5 R5*; Conduct finishing for the arc of R5

*N15 G01 Z-80*; Conduct finishing for the outer circle of  $\Phi 10$

*N16 U-4 W-2*; Conduct finishing for  $2 \times 45^\circ$  chamfer, and end the finishing

*N17 G40 X4*; Exit the machined face, and cancel the tool arc radius compensation

*N18 G00 Z80*; Exit the inner hole of the workpiece

*N19 X80*; Return to the program start point or the tool exchange position

*N20 M30*; Stop spindle, end the main program, and reset

### Inner (outer) diameter roughing compound cycle with groove


#### Format

**G71 U( $\Delta d$ ) R(r) P(ns) Q(nf) E(e) F(f) S(s) T(t);**

Parameter	Description
U	Cutting depth (each cutting amount). The symbol ("+"/"-") is not specified with the value. The direction is determined by the vector AA'.
R	Each retract amount.
P	The first program block sequence number for finishing path (AA' in the figure below).
Q	The last program block sequence number for finishing path (B'B in the figure below).
E	The finishing allowance, which indicates the distance along the X axis; It is positive for outer diameter cutting and negative for inner diameter cutting.
F S T	During roughing, the F, S, and T in G71 are valid, while in finishing, the F, S, and T between the <b>ns</b> program block and <b>nf</b> program block are valid.

#### Description


This cycle is used for the roughing as shown in the figure below. The finishing path is  $A \rightarrow A' \rightarrow B' \rightarrow B$ .

**Attention**

1. G71 must have **ns** and **nf** of **P/Q**, which should correspond to the start and end number of the finishing path; otherwise, the cycle cannot be executed.
2. The program block of **ns** must be **G00/G01**. In other words, the action from **A** to **A'** must be a straight line or point positioning movement.
3. In the program blocks from **ns** to **nf**, no subprogram (4.03) should be included.

**Example**

Use outer diameter roughing compound cycle with groove to create a machining program for the workpiece shown as below: the dotted lines indicate the workpiece.



%3327

N1 T0101; Select No. 1 tool and define coordinate system

N2 G00 X80 Z100; Go to the program start point or tool exchange position

M03 S400; Rotate spindle in the clockwise direction at 400 r/min

N3 G00 X42 Z3; The tool goes to the cycle start point.

N4 G71 U1 R1 P8 Q19 E0.3 F100; Conduct rough cutting cycle with groove.

N5 G00 X80 Z100; After roughing, go to the tool exchange position

N6 T0202; Select No.2 tool, and define the coordinate system

N7 G00 G42 X42 Z3; Add tool nose arc radius compensation to No.2 tool

N8 G00 X10; Conduct finishing, go to the extended line of chamfer

N9 G01 X20 Z-2 F80; Conduct finishing for  $2 \times 45^\circ$  chamfer

N10 Z-8; Conduct finishing for  $\Phi 20$  outer circle

N11 G02 X28 Z-12 R4; Conduct finishing for R4 arc

N12 G01 Z-17; Conduct finishing for  $\Phi 28$  outer circle

N13 U-10 W-5; Conduct finishing for under-cut cone



*N14 W-8*; Conduct finishing for  $\Phi 18$  outer circular groove

*N15 U8.66 W-2.5*; Conduct finishing for upper-cut cone

*N16 Z-37.5*; Conduct finishing for  $\Phi 26.66$  outer circle

*N17 G02 X30.66 W-14 R10*; Conduct finishing for R10 under-cut arc

*N18 G01 W-10*; Conduct finishing for  $\Phi 30.66$  outer circle

*N19 X40*; Exit the machined face, and end the finishing

*N20 G00 G40 X80 Z100*; Cancel the radius compensation, and back to the tool exchange position

*N21 M30*; Stop spindle, end the main program, and reset

### 12.4.2 End-Face Roughing Compound Cycle (G72)

This cycle is similar as G71. The difference is that the cutting of G72 is parallel to the X axis.


#### Format

**G72 W( $\Delta d$ ) R(r) P(ns) Q(nf) X( $\Delta x$ ) Z( $\Delta z$ ) F(f) S(s) T(t);**

Parameter	Description
W	Cutting depth (each cutting amount). The sign (positive or negative) is not specified with the value. The direction is determined by the vector AA'.
R	Each retract amount.
P	The first program block sequence number for finishing path (AA' in the figure below).
Q	The last program block sequence number for finishing path (BB' in the figure below).
X	Finishing allowance in the X axis direction.
Z	Finishing allowance in the Z axis direction.
F S T	During roughing, the F, S, and T in G72 are valid, while in finishing, the F, S, and T between the <b>ns</b> program block and <b>nf</b> program block are valid.


#### Description

This cycle is used for the roughing and finishing as shown in the figure below. The finishing path is  $A \rightarrow A' \rightarrow B' \rightarrow B$ .



In the cutting cycle of G72, the cutting feed direction is parallel to the X axis, and the sign of  $X(\Delta U)$  and  $Z(\Delta W)$  is shown in the figure below. The sign "+" indicates the movement along the positive direction of the axis while "-" indicates the movement along the negative direction of the axis.

### Symbol of XZ value ("+" / "-" )




### Attention

1. The G72 command should have the address specified by **P** or **Q**; otherwise, this cycle cannot be executed.
2. The **ns** program should include G00/G01 commands, to execute the action from A to A'. In addition, this program block should not have the commands for the movement along the X axis.
3. The program blocks from **ns** to **nf** may include G02/G03 commands, but cannot include subprograms.

### Example 1

Create a machining program for the workpiece shown as below: cycle start point: A (80, 1); cutting depth 1.2 mm; tool exit quantity: 1 mm; finishing allowance along the X axis: 0.2 mm; finishing allowance along the Z axis: 0.5 mm. The dotted lines indicate the workpiece.



N1 T0101; Select No. 1 tool and define coordinate system

N2 G00 X80 Z80; Go to the program start point

N3 M03 S400; Rotate spindle in the clockwise direction at 400r/min.

N4 X80 Z1; Go to the cycle start point

N5 G72W1.2R1P8Q17X0.2Z0.5F100; Conduct roughing for the external end face

N6 G00 X100 Z80; Go to the tool exchange position after roughing.

N7 G42 X80 Z1; Add tool nose arc radius compensation

N8 G00 Z-53; Start finishing , go to the extended line of the cone

N9 G01 X54 Z-40 F80; Conduct finishing for the cone.

N10 Z-30; Conduct finishing for  $\Phi 54$  outer circle

N11 G02 U-8 W4 R4; Conduct finishing for R4 arc

N12 G01 X30; Conduct finishing for Z26 end face

N13 Z-15; Conduct finishing for  $\Phi 30$  outer circle

N14 U-16; Conduct finishing for Z15 end face

N15 G03 U-4 W2 R2; Conduct finishing for R2 arc

N16 G01 Z-2; Conduct finishing for  $\Phi 10$  outer circle

N17 U-6 W3; Conduct finishing for  $2 \times 45^\circ$  chamfer, complete finishing


N18 G00 X50; Exit the machined face

N19 G40 X100 Z80; Cancel the radius compensation and back to the program start point

N20 M30; Stop spindle, end the main program, and reset

**Example 2**

Create a machining program for the workpiece shown as below: cycle start point: A (6, 3); cutting depth: 1.2 mm; tool exit quantity: 1 mm; finishing allowance along the X axis: 0.2 mm; finishing allowance along the Z axis: 0.5 mm. The dotted lines indicate the workpiece.



%3329

N1 T0101; Define coordinate system

N2 G00 X100 Z80; Go to the start point

N3 M03 S400; Rotate spindle in the clockwise direction at 400r/min

N4 G00 X6 Z3; Go to the cycle start point

N5 G72W1.2R1P6Q16X-0.2Z0.5F100; Inner end face roughing process

N6 G00 Z-61; Conduct finishing , go to the extended line of chamfer

N7 G01 U6 W3 F80; Conduct finishing for the chamfer  $2 \times 45^\circ$

N8 W10; Conduct finishing for the outer circle of  $\Phi 10$

---

<i>N9 G03 U4 W2 R2;</i> Conduct finishing for the arc of R2	for the outer circle of $\Phi 54$
<i>N10 G01 X30;</i> Conduct finishing for Z45 end face	<i>N15 U20 W10 ;</i> Conduct finishing for the cone
<i>N11 Z-34 ;</i> Conduct finishing for the outer circle of $\Phi 30$	<i>N16 Z3;</i> Conduct finishing for the outer circle of $\Phi 74$ , complete finishing
<i>N12 X46;</i> Conduct finishing for Z34 end face	
<i>N13 G02 U8 W4 R4;</i> Conduct finishing for the arc of R4	<i>N17 G00 X100 Z80;</i> Back to the tool exchange position
<i>N14 G01 Z-20 ;</i> Conduct finishing	<i>N18 M30 ;</i> Stop spindle, end the main program, and reset

### 12.4.3 Closed Cutting Compound Cycle (G73)

This cycle can be used to cut workpiece with fixed graphics. It can be used to effectively cut cast molding, forging molding or rough workpieces.


#### Without groove

**G73 U( $\Delta I$ ) W( $\Delta K$ ) R(r) P(ns) Q(nf) X( $\Delta x$ ) Z( $\Delta z$ ) F(f) S(s) T(t)**

Parameter	Description
U	Total finishing allowance in the X axis direction.
W	Total finishing allowance in the Z axis direction.
R	Rough cutting count.
P	The first program block sequence number for finishing path (AA' in the figure below).
Q	The last program block sequence number for finishing path (BB' in the figure below).
X	Finishing allowance in the X axis direction.
Z	Finishing allowance in the Z axis direction.
F S T	During roughing, the F, S, and T in G73 are valid, while during finishing, the F, S, and T between the <b>ns</b> program block and <b>nf</b> program block are valid.

#### Description

instruction is a closed loop shown in the figure below. The tool feeds gradually and cuts the workpiece to the final shape step by step. The finishing path is  $A \rightarrow A' \rightarrow B' \rightarrow B$ . See the figure below:




The tool path specified by the

**Attention**

1.  $\Delta I$  and  $\Delta K$  indicates the total cutting amount during roughing. If the roughing number is  $r$ , then each cutting amount in the X and Z direction is  $\Delta I/r$  and  $\Delta K/r$  respectively.
2. When executing this cycle based on the **P** and **Q** commands in G73, pay attention to the symbols ("+" or "-") of  $\Delta x$ ,  $\Delta z$ ,  $\Delta I$  and  $\Delta K$ .

**Example**

Create a machining program for the workpiece shown as below: cutting start point: A (60, 5); roughing allowance along the X and Z axis: 3 mm and 0.9 mm respectively; roughing count: 3. The finishing allowance along the X and Z axis: 0.6 mm and 0.1 mm respectively. The dotted lines indicate the workpiece.



%3330

N1 T010; Select No. 1 tool and define coordinate system

N2 G00 X80 Z80; Go to the program start point

N3 M03 S400; Rotate spindle in the clockwise direction at 400r/min

N4 G00 X60 Z5; Go to the cycle start point

N5 G73 U3 W0.9 R3 P6 Q13 X0.6 Z0.1 F120; Conduct machining with closed rough cutting cycle

N6 G00 X0 Z3; Start finishing, go to the extended line of chamfer

N7 G01 U10 Z-2 F80; Conduct finishing for 2×45° chamfer

N8 Z-20; Conduct finishing for the outer circle of Φ10

N9 G02 U10 W-5 R5; Conduct finishing for the arc of R5

N10 G01 Z-35; Conduct finishing for the outer circle of Φ20



*N11 G03 U14 W-7 R7;* Conduct finishing for the arc of R7

*N12 G01 Z-52;* Conduct finishing for the outer circle of  $\Phi 34$

*N13 U10 W-10;* Conduct finishing for the cone

*N14 U10;* Exit the machined face, complete finishing contour

*N15 G00 X80 Z80;* Back to the program start point

*N16 M30;* Stop spindle, end the main program, and reset

### 12.4.4 Thread Cutting Compound Cycle (G76)

#### Format


**G76 C(c) R(r) E(e) A(a) X(x) Z(z) I(i)**

**K(k) U(d) V( $\Delta$ min) Q( $\Delta$ d) P(p) F**


Parameter	Description
C	Exact cutting count (1-99), modal value.
R	The retreat of tailstock along the Z axis during threading, modal value.
E	The retreat of tailstock along the X axis during threading; modal value.
A	The tool nose angle (two digits), modal value. The value must be greater than <b>10</b> degrees and less than <b>80</b> degrees.
X Z	The coordinates of the valid thread end point C for absolute value programming; The relative distance from the valid thread end point C to the cycle start point A for the incremental value programming. ( the G91 command for incremental programming, and the G90 command for absolute value programming).
I	The radius difference between the ends of the thread. If $i = 0$ , it indicates a straight thread (cylindrical thread) cutting mode.
K	Thread height. This value is specified by the radius value in the X axis direction.
U	The finishing allowance (radius value).
V	The minimum cutting depth (radius value); when the $n^{\text{th}}$ cutting depth $\Delta d\sqrt{n} - \Delta d\sqrt{n-1}$ is less than <b><math>\Delta</math>min</b> , the cutting depth is set to <b><math>\Delta</math>min</b> .
Q	The first cutting depth (radius value)
P	The spindle rotation angle between the the spindle reference pulse and the cutting start point.
F	Thread lead (same as G32); F indicates Metric.

#### Description

The thread cutting fixed cycle G76 can be used for the machining path shown as below:



The unilateral cutting and related parameters are shown as below:




### Attention

1. When executing the cycle with the X(x) and Z(z) commands in G76, pay attention to the sign ("+" or "-") of **u** and **w** (determined by the direction of the tool path AC and CD) during incremental programming.
2. G76 can be used for unilateral cutting, reducing the force of the tool nose. The first cutting depth is  $\Delta d$ ; the total  $n^{\text{th}}$  cutting depth is  $\Delta d\sqrt{n}$ ; The depth of cut for each cycle is  $\Delta d(\sqrt{n} - \sqrt{n-1})$ .
3. In the unilateral cutting figure, the cutting speed from B to C is specified by the thread cutting speed, while other paths are all defined by the feed speed.

### Example

Use the thread cutting compound cycle command G76 to create a program for the thread machining of ZM60×2. The dimension of the

workpiece is shown as below. The size in the bracket is derived from the threading standard. ( $\tan 1.79^\circ = 0.03125$ )



%3331

N1 T0101; Select No. 1 tool and define coordinate system

N2 G00 X100 Z100; Go to the program start point or tool exchange position

N3 M03 S400; Rotate spindle in the clockwise direction at 400r/min

N4 G00 X90 Z4; Go to the simple cycle start point

N5 G80 X61.125 Z-30 I-1.063 F80; Conduct machining outer surface of the conical thread

N6 G00 X100 Z100 M05; Go to the program start point or tool exchange position

N7 T0202; Select No. 2 tool and define coordinate system

N8 M03 S300; Rotate spindle in the clockwise direction at 300r/min

N9 G00 X90 Z4; Go to the thread cycle start point

N10 G76C2R-3E1.3A60X58.15Z-24I-0.875K1.299U0.1V0.1Q0.45F2

N11 G00 X100 Z100; Return to the program start point or tool exchange position

N12 M05; Stop spindle

N13 M30; End the main program, and reset

## 12.5 Special Cases in Fixed Cycle

For milling machines, use G80 to cancel the fixed cycle. For turning machines, use G00/G01/G02 to cancel the fixed cycle. After the fixed cycle statement, all statements are identified by the system as a fixed cycle before the fixed cycle is canceled.


Wrong programming	Correct programming
%1111	%1111
T0101	T0101
G0X50Z20	G0X50Z20
X32Z0	X32Z0
G80X30Z-30	G80X30Z-30
M98P12; Call %12 in the fixed cycle	G01
M30	M98P12; call %12 of the current program
%12	M30
G0X10Z10	%12
X30Z30	G0X10Z10
M99	X30Z30
	M99

Currently, the fixed cycle cannot be used with rotation, mirroring, scaling, and G91 simultaneously.

## 13 User Macro Program

---

User macro program is similar to a high-level language programming method, which allows users to use variables, arithmetic, logical operations and conditional transfer. This function makes it simpler to create the same machining program than the traditional ones. Users may create general macro program for the same machining operation, e.g. the machining of the bolt hole circle shown as below:



Create a macro program for the bolt hole circle machining shown in the figure above, and store it in the CNC. This way, you can call this program to machine the bolt hole circle at any time by simply entering the bolt hole properties such as the number of holes and deviation angle. It is like a bolt hole circle function is added to the CNC.

### 13.1 Variables

### 13.2 Operation Instructions

### 13.3 Macro Statement

### 13.4 Macro Program Calling

### 13.5 User Sub-Programs

## 13.1 Variables

---

In a macro program, you may use variables for parameters of preparation function commands and axial movement distance, e.g. **G00 X[#43]**, where **#43** is a variable. You can assign to it before calling it.

### Attention

In macro program, you cannot directly use the variable name. Variables is specified with the variable symbol (#) and the variable number following the symbol.

### Variables

According to the variable numbers, variables can be divided into local variables, global variables, and system variables. Different variables have different usages. In addition, the access properties of different variables are different; some variables are read-only.

### Constant

A number of constants have been defined for users in the system, which are read-only.

PI: circular constant  $\Pi$

TRUE: indicates the condition is true.

FALSE: indicates the condition is false.

### Attention

When using the constant **PI**, users need to specially handle the end condition of the program because of its calculation error; otherwise, exceptions may occur.

### Local variables

Local variables are variables used within the macro program. That means a local variable (e.g. **#i**) called from a macro program A at one time is different from that at another time. Therefore, during multi-layer calling, the system may improperly use in macro B the local variables being used in macro A when calling macro B from A, resulting in damage to the value.

Variables from **#0** to **#49** are local variables, of which properties are read and write.

The system provides six layers of nested local variables, of which properties are read-only.

- #200-#249: local variables of layer 0
- #250-#299: local variables of layer 1
- #300-#349: local variables of layer 2
- #350-#399: local variables of layer 3
- #400-#449: local variables of layer 4
- #450-#499: local variables of layer 5

### Global variables

variables can be generally used for the main program calling subprograms, or used among subprograms and macro programs, while the values remain unchanged. That means a global variable (e.g. #i) used in one macro program and others is the same. In addition, the public variable #i out of a macro can be used in other macros.

Variables from #50 to #199 are global variables, of which properties are read and write.

Different from local variables, global

### System variables

System variables are fixed variables in the system. Its properties are read-only, write-only and read & write, depending on the properties of each system.

### Undefined variables

The default value for the variables undefined in the system is 0.

Example:

*%I234*

*G54*

*G01 X10Y10*

*X[#1]Y30*; Coordinate value of the workpiece coordinate system (0, 30)

*M30*



**Variables related to channels**

Variable No.	Properties	Description
Channel variables Channel 00: (00000-03999)		
#0 to #49	R/W	Current local variables
#50 to #199		Reserved
#200 to #249	R	Local variables of layer 0
#250 to 299	R	Local variables of layer 1
#300 to #349	R	Local variables of layer 2
#350 to #399	R	Local variables of layer 3
#400 to #449	R	Local variables of layer 4
#450 to #499	R	Local variables of layer 5
#1000 to #1008	R	Machine position of the current channel axis (9-axis)
#1009	R	Diameter programming for turning machines
#1010 to #1018	R	Programmed machine position of the current channel axis (9-axis)
#1019		Reserved

#1020 to #1028	R	Programmed workpiece position of the current channel axis (9-axis)
#1029		Reserved
#1030 to #1038	R	Workpiece origin of the current channel axis (9-axis)
#1039	R	Coordinate system
#1040 to #1048	R/W	G54 origin of the current channel axis (9-axis)
#1049	R	G54 axis mask
#1050 to #1058	R/W	G55 origin of the current channel axis (9-axis)
#1059	R	G55 axis mask
#1060 to #1068	R/W	G56 origin of the current channel axis (9-axis)
#1069	R	G56 axis mask
#1070 to #1078	R/W	G57 origin of the current channel axis

		(9-axis)
#1079	R	G57 axis mask
#1080 to #1088	R/W	G58 origin of the current channel axis (9-axis)
#1089	R	G58 axis mask
#1090 to #1098	R/W	G59 origin of the current channel axis (9-axis)
#1099	R	G59 axis mask

#1100 to #1108	R	G92 origin of the current channel axis (9-axis)
#1109	R	G92 axis mask
#1110 to #1118	R	Breakpoint of the current channel axis (9-axis)
#1119	R	Breakpoint axis labels
#1120 to #1149	R/W	Fixed cycle modal variables
#1150 to #1189	R	G code 0-39 modal
#1190	R	User-defined input
#1191	R	User-defined output
#1192 to #1199		Reserved
#1200 to #1209	R	AD input
#1210 to #1219	R	DA output
#1220	R	M3/4/5
#1221	R	G94 F value
#1222	R	Tapping F value
#1223 to #1226	R	Tapping spindle rotation speed
#1227	R	Valid radius compensation No. D
#1228	R	Valid length compensation No.H
#1229	R	cmd_feed
#1300 to #1308	R	Relative origin of the current channel axis (9-axis)
#1309		Reserved
#1310 to 1318	R	Programmed machine position of the current channel axis (9-axis)
#1319		Reserved
#1320 to #1328	R	G28 midpoint
#1329	R	G28 axis mask
#1330 to #1338	R	G52 origin
#1339		Reserved
#1340 to #1349	R	G31 measure machine command position
#1350 to #1359		Reserved
#1360 to #1369	R	G31 measure actual machine position
#1370 to #1399		Reserved
#1400 to #1408	R/W	G54 offset
#1409		Reserved
#1410 to #1418	R/W	G55 offset
#1419		Reserved
#1420 to #1428	R/W	G56 offset
#1429		Reserved
#1430 to #1438	R/W	G57 offset

#1439		Reserved
#1440~#1448	R/W	G58 offset
#1449		Reserved
#1450~#1458	R/W	G59 offset
#1459~#3999		Reserved

**Attention**

The variables corresponding to the origins and offsets of the current channel workpiece coordinate system G54~G59 are read and write, and can be saved after power off.

**User-defined variables**

User-defined variables: 500 to 999 50000 to 54999		
#500 to #999	R/W	Global variables
#50000 to #54999	R/W	Global variables

**Attention**

When the machine user parameter **010091"#500~#999USER MACRO ENABLED"** is **1**, the user-defined variables **#500** to **#999** are valid. User-defined variables are saved after power off.

**Variables related to tool**

Tool data: #70000 to #89999 Each tool uses 200 numbers. There is a total of 100 tools, with a total of 20000 numbers. Coding range corresponding to No. 0 tool: 000 to 199 Coding range corresponding to No. 1 tool: 200 to 399 Coding range corresponding to No. 99 tool: 18000-19999		
#70005	R	The direction of the turning tool nose.
#70006	R/W	The length of the milling tool or the X offset of the turning tool.
#70007	R	The Y offset of the turning tool.
#70008	R	The Z offset of the turning tool.
#70009		Reserved
#70010		Reserved
#70011	R/W	The radius of the milling tool or the radius of the turning tool nose.
#70012~#70028		Reserved
#70029	R/W	The length wear of the milling tool or the Z offset wear of the turning tool.
#70030		The Y offset wear of the turning tool.

#70034	R/W	The radius wear of the milling tool or the X offset wear of the turning tool.
#70035- #70100		Reserved
#70101	R	Tool life monitoring types
#70104	R	Maximum cutting time
#70105	R	Alarm cutting time
#70106	R	Actual cutting time
#70107	R	Maximum cutting count
#70108	R	Alarm cutting count
#70109	R	Actual cutting count

**Attention**

The properties of the variables corresponding to the tool radius compensation value, length offset, and wear values are read and write, which can be save after power off.

## 13.2 Operation Instructions

In the macro statement, you may flexibly use arithmetic operators and functions to meet complex programming requirements. See the figure below:

Operation Type	Operation Instructions	Description
Arithmetic operation	$\#i = \#i + \#j$	Addition, $\#i$ plus $\#j$
	$\#i = \#i - \#j$	Subtraction, $\#i$ minus $\#j$
	$\#i = \#i * \#j$	Multiplication, $\#i$ times $\#j$
	$\#i = \#i / \#j$	Division, $\#i$ divided by $\#j$
Condition operation	$\#i \text{ EQ } \#j$	Equal to ( $=$ )
	$\#i \text{ NE } \#j$	Not equal to ( $\neq$ )
	$\#i \text{ GT } \#j$	Greater than ( $>$ )
	$\#i \text{ GE } \#j$	Greater than and equal to ( $\geq$ )
	$\#i \text{ LT } \#j$	Less than ( $<$ )
	$\#i \text{ LE } \#j$	Less than and equal to ( $\leq$ )
Logical operation	$\#i = \#i \& \#j$	Logical operation "And"
	$\#i = \#i   \#j$	Logical operation "Or"
	$\#i = \sim \#i$	Logical operation "Not"
Functions	$\#i = \text{SIN}[\#i]$	Sine (unit: radian)
	$\#i = \text{ASIN}[\#i]$	Anti-sine
	$\#i = \text{COS}[\#i]$	Cos (unit: radian)
	$\#i = \text{ACOS}[\#i]$	Anti-cos
	$\#i = \text{TAN}[\#i]$	Tangent (unit: radian)
	$\#i = \text{ATAN}[\#i]$	Anti-tangent
	$\#i = \text{ABS}[\#i]$	Absolute value
	$\#i = \text{INT}[\#i]$	Integer (round down)
	$\#i = \text{SIGN}[\#i]$	Obtain sign
	$\#i = \text{SQRT}[\#i]$	Square root
	$\#i = \text{POW}[\#i]$	Power
	$\#i = \text{LOG}[\#i]$	logarithm
	$\#i = \text{PTM}[\#i]$	Pulse time modulation (mm)
	$\#i = \text{PTD}[\#i]$	Pulse time degree
	$\#i = \text{RECIP}[\#i]$	Reciprocal
	$\#i = \text{EXP}[\#i]$	Index based on e (2.718)
	$\#i = \text{ROUND}[\#i]$	Round
	$\#i = \text{FIX}[\#i]$	Round down
	$\#i = \text{FUP}[\#i]$	Round up

**Example**

The program below is used to obtain the sum of 1 to 10:

*O9500*

*#1=0*; The initial value of the subtrahend

*#2=1*; The initial value of the addend

*N1 IF[#2 LE 10]*; The addend cannot exceed **10**; otherwise, it goes to the *N2* after *ENDIF*.

*#1 =#1 + #2*; Subtraction operation

*#2 =#2 + 1*; The next addend

*ENDIF*; Move to *N1*

*N2 M30*; End program

## 13.3 Macro Statement

### Expression

Those calculation formulas with symbols like "+", "-", "\*", "/", "[", "]", and SIN are known as expression. See the examples as below:

1. -#1
2. SIN[#1+#2]\*COS[[#1+#2]/#3]

Attention:

1. The symbol "[" indicates a higher priority than "+", "-", "\*", and "/". E.g. when conducting operation for [[#1+#2]/#3], firstly calculate the [#1+#2], then calculate /#3.
2. For the expression, to ensure the calculation accuracy, it is recommended to use the symbol "[ ]", e.g. [-#2]. It is not recommended to write like -[#2].

### Assignment statement

Assignment means to transfer the value of a constant or an expression to a macro variable. This statement is called an assignment statement. See the example below:

#2 = 175 / SQRT[2] \* COS[55\*PI/180]

#3 = 124.0

### Condition statements

Two types of condition statement are supported in this system:

IF [condition expression];                      **Type 1**

.....

ENDIF

IF [condition expression];                      **Type 2**

.....



ELSE

.....

ENDIF

For the condition expression of the *IF* statement, you may use a simple or complex expression. See the examples below:

When **#1** is equal to **#2**, **0** is assigned to **#3**.

IF [#1 EQ #2]

#3 = 0

ENDIF

When **#1** is equal to **#2**, and **#3** is equal to **#4**, **0** is assigned to **#3**.

IF [#1 EQ #2] AND [#3 EQ #4]

#3 = 0

ENDIF

When **#1** is equal to **#2**, or **#3** is equal to **#4**, **0** is assigned to **#3**. Otherwise, **1** is assigned to **#3**.

IF [#1 EQ #2] OR [#3 EQ #4]

#3 = 0

ELSE

#3 = 1

ENDIF

### Cycle statement

Specify a condition expression after WHILE. When the specified condition expression is satisfied, execute the programs between WHILE to ENDW. When the specified condition expression is not satisfied, exit the WHILE cycle, and execute the program line after ENDW.

#### Calling format:

WHILE [condition expression]

.....

ENDW

### Infinite cycle

When the WHILE condition expression is defined as always true, an infinite cycle can be realized:

```
WHILE [TRUE]; or WHILE [1]
```

```
.....
```

```
ENDW
```

### **GOTO statement**

```
GOTO _
```

Use **GOTO** to move to the specified label.

GOTO must be followed by numbers. E.g. **GOTO 4** indicates to move to the **N4** program block (N4 must be defined at the header of the program block).

### **Nest**

For the IF and WHILE statement, the system allows nested statements that follow a certain of restrictive rules.

For IF statement, only up to six layers of nested statements are allowed; if over six, an error will be reported.

For WHILE statement, only up to six layers of nested statements are allowed; if over six, an error will be reported.

The system supports combined IF and WHILE statements, but the matching relationship of IF-ENDIF and WHILE-ENDW must be satisfied. For the usage as described below, the system will report an error.

```
IF [condition expression 1]
```


```
WHILE [condition expression 2]
```

```
ENDIF
```

```
ENDW
```

### **Example**

Edit ellipse machining program  
(elliptic expression:  $X=a \times \cos \alpha$ ;  $Y=b \times \sin \alpha$ ).



*%0001*

*#0=5; Define tool radius R*

*#1=20; Define a*

*#2=10; Define b*

*#3=0; Define the initial value of the stepping angle. unit: degree*

*N1 G92 X0 Y0 Z10*

*N2 G00 X[2\*#0+#1] Y[2\*#0+#2]*

*N3 G01 Z0*

*N4 G41 X[#1] D01*

*N5 WHILE #3 GE [-360]*

*N6 G01 X[#1\*COS[#3\*PI/180]] Y[#2\*SIN[#3\*PI/180]]*

*N7 #3=#3-5*

*ENDW*

*G01 G91 Y[-2\*#0]*

*G90 G00 Z10*

*G40 X0 Y0*

*M30*

## 13.4 Calling Macro Programs

There are three modes to call macro programs:

1. Non-modal call: G65
2. G-code call: fixed cycle
3. Call subprograms with M codes

### 13.4.1 Rules for Defining Arguments

#### Rules for defining arguments

When users call the macro, the system will automatically copy the argument (A - Z) in the current program to the local variables (#0 to #25) of the current layer in the corresponding user macro, and copy the workpiece coordinate system absolute position of the current channel axis (XYZABCUVW) to the local variables (#30 to #38) of the current channels.

Macro Variables	Argument Name	Macro Variables	Argument Name	Macro Variables	Argument Name
#0	A	#1	B	#2	C
#3	D	#4	E	#5	F
#6	G	#7	H	#8	I
#9	J	#10	K	#11	L
#12	M	#13	N	#14	O
#15	P	#16	Q	#17	R
#18	S	#19	Blank	#20	U
#21	V	#22	W	#23	X
#24	Y	#25	Z	#26	Reserved
#27	Reserved	#28	Reserved	#29	Reserved
#30	X position	#31	Y position	#32	Z position
#33	A position	#34	B position	#35	C position
#36	U position	#37	V position	#38	W position

#### Example

*%1234; Main program*

*G92 X0 Y0 Z50*

*G91 G01 Z10 F400*

*M98 P111*

*G4X1*

*%111*

*G01x10y10z10*

...

*M99*

#### Verification of macro definition

Format: **AR[# variable number]**

Returned value:

**0**: The variable is not defined.

**90**: The variable is defined as the absolute mode G90.

**91**: The variable is defined as the incremental mode G91.

Note: Use the system macro AR[] to determine whether the macro variable is defined, and whether it is defined as the incremental or absolute mode.

#### Example

*%1234*

*G92X0Y0Z0*

*M98P9990X20Y30Z40*

*M30*

*%9990*

*IF [AR[#23] EQ 0] OR [AR[#24] EQ 0] OR [AR[#25] EQ 0];* if X or Y or Z is not defined, then return

*M99*

*ENDIF*

*G91;* create macro program with the incremental mode

*IF AR[#23] EQ 90;* if the X value is the absolute mode G90

*#23=#23-#30;* change the X value to the incremental mode; **#30** is the absolute coordinate of X

*ENDIF*

.....

*M99*

### 13.4.2 Non-Modal Call (G65)

When G65 is specified, the defined user macro program following the parameter P is called. At the same time, the arguments and variables required by the user macro program are transferred to the user macro program.

#### Format

**G65 P\_ L\_ [argument address word]**

Parameter	Description
P	The number of the program to be called.
L	Call repeats.
<b>Argument address word</b>	The data that users need to transfer to the macro program.

#### Attention

1. G65 is a non-modal command. You need to specify G65 in the current line when calling macro programs.
2. Subprograms must be in the same file.

#### Example

```
%0032

G54G0X100Z100

G65P100L5X50Z-30F1000

G00X50Z10

M30

%100

G01X[#23]Z[#25]F[#5]

G81X[#23]Z[#25]

G0X100Z50

M30
```

### 13.4.3 Call Macro Program with G Codes

to call macro programs, you may call macro programs with G codes. Currently, only the G codes in the

fixed cycle can be used to call macro programs. For details, see relevant sections related to turning and milling operations.

In addition to use non-modal (G65)

### Function

Use G codes to call the user-defined subprograms in the fixed cycle.

### Format

**G\_**

Parameter	Description
G	The subprogram number called in the USERDEF.CYC (Arabic numerals).

### Example

Add a fixed cycle 1001 in USERDEF.CYC

*%1001;*

*G01 X10 Y10 Z10*

*G80*

*M99*

*Main program*

*%1244*

*G92X0Y0Z50*

*G91G01X10F400*

*G1001 (call user-defined fixed cycle)*

*G4X1*

*M30*

## 13.4.4 Call Macro Program with M Commands

### Format

**M98 P\_**



Parameter	Description		program	
P	The subprogram number to be called in the current			

### Description

For the macro program calling with M commands, refer to the relevant

information (M98) in the auxiliary function section. When executing M98, the system will find the subprogram number to be called. If the subprogram is not found, an error will be reported.

### Format

M\_

Parameter	Description
M	The input value of the user-defined parameter.

### Description

Use a M command to call a user-defined subprogram.

The table below describes the M parameter settings corresponding to the subprograms. The user-defined parameters (010360-010373) correspond to the subprograms (%1007-%1020) in USERDEF.CYC.

Parameter List	Parameter No.	Parameter Name corresponding to the	Parameter Value	Effective Mode
Machine user parameters	010360	M command corresponding to the fixed cycle G1007	13	Save
	010367	M command corresponding to the fixed cycle G1007	0	Save
	010361	M command corresponding to the fixed cycle G1014	0	Save
	010368	M command corresponding to the fixed cycle G1008	0	Save
	010362	M command corresponding to the fixed cycle G1015	0	Save
	010369	M command corresponding to the fixed cycle G1009	0	Save
	010363	M command corresponding to the fixed cycle G1016	0	Save
	010370	M command corresponding to the fixed cycle G1010	0	Save
	010364	M command corresponding to the fixed cycle G1017	0	Save
	010371	M command corresponding to the fixed cycle G1011	0	Save
	010365	M command corresponding to the fixed cycle G1018	0	Save
	010372	M command corresponding to the fixed cycle G1012	0	Save
		fixed cycle G1019		
	010373	M command corresponding to the fixed cycle G1020	0	Save

Set the M command parameter (010360) corresponding to the fixed cycle G1007 to 13, then you may use M13 to call the %1007 program in USERDEF.CYC.

%1007; add user-defined subprogram 1007 to USERDEF.CYC

G0Z5

Z-50

G80

#### Example

M99

%1234; main program

G54

G1X0Y0Z0

M13; use M13 to call the 1007 subprogram

*X10Y10*

*X20Y30*

*Y0*

*X0*

*M30*


#### Attention

1. Currently, the fixed cycle cannot be used with rotation/mirroring/scaling/G91 simultaneously.
2. When using M commands to call subprograms, you need to add G80 before M99 when the program ends.

### 13.4.5 Macro Program Cases

#### Case 1 (milling)

Use spher mill to machine the R5 fillet surface shown in the figure below:



*%0001* (The cutter location is the ball center)

*G92 X-30 Y-30 Z25*

*#0=5* (Fillet radius)

*#1=4* (Spher mill radius)

*#2=180* (The initial value of the stepping angle  $\gamma$ . Unit: degree)

*WHILE #2 GT 90*

*G01 Z[25+[#0+#1]\*SIN[#2\*PI/180]]* (Calculate Z axis height)

*#101=ABS[[#0+#1]\*COS[#2\*PI/180]]-#0* (Calculate radius offset)

*G01 G41 X-20 D01*

*Y14*

*G02 X-14 Y20 R6*

*G01 X14*

*G02 X20 Y14 R6*

*G01 Y-14*

*G02 X14 Y-20 R6*

*G01 X-14*

*G02 X-20 Y-14 R6*

*G01 X-30*

*G40 Y-30*


*#2=#2-10*

*ENDW*

*M30*

### Case 1 (turning)

Use macro program to create a program for the parabola within interval A[0, 8]. See the figure below:



*%3401*

*N1 T0101*

*N2 G37*

*N3 #10=0; A coordinate*

*N4 M03 S600*

*N5 WHILE #10 LE 8*

*N6 #11=#10\*#10/2*

*N7 G90 G01 X[#10] Z[-#11] F500*

*N8 #10=#10+0.08*

*N9 ENDW*

*N10 G00 Z0 M05*

*N11 G00 X0*

*N12 M30*

### 13.4.6 Subprogram Classification

#### Internal subprogram

If the called program and the main program are in the same file, then the called program is an internal subprogram.

#### Example

G code file name: O\_test; %111: an internal subprogram, which is in the same file with the main program %1001, and is called by G98 in the main program.

*%1001; main program*

*G92 X0 Y0 Z50*

*G91 G01 Z10 F400*

*M98 P111; call subprogram 111*

*G4X1*

*M30*

*%111; subprogram*

*G01x10y10z10*

*...*

*G80*

*M99*

#### External subprogram

If the called program is in another file, it is an external subprogram.

The external subprogram file name must start with letter "O".

#### Example

G code file name: O\_test; subprogram file name: O123

#### Main program

*%1001*

*G92 X0 Y0 Z50*

*G91 G01 Z10 F400*

*M98 P123; call subprogram O123*

*G4X1*

*M30*

### **Subprogram O123**

*%1234;*

*G01x10y10z10*

*...*

*G80*

*M99*

### **Fixed cycle**

There are two kinds of fixed cycles. One is the general fixed cycle, mainly used for turning, milling and drilling; the other is the user fixed cycle, which is created by yourself according to your requirements.

For detailed information about general fixed cycle, see section 12.

For user-defined fixed cycle (USERDEF.CYC), you may add subprograms to this file as required, and may directly call them in the main program.

Open the user-defined fixed cycle file "USERDEF.CYC", find the content as below, and add subprograms after it, e.g. add 1010:

The fixed cycle below is a user-defined fixed cycle:

User-defined fixed cycle ranging from **G1000** to **Gxxxx** by tp  
2010.12.27

User-defined fixed cycle G1090

*%1010*

*G01X10Y10*

*M99*

## **14 Spindle Functions**

---

---

This chapter includes the following sections:

### **14.1 Constant Linear Speed Cutting Control**

### **14.2 C/S Axis Change Function**



## 14.1 Constant Linear Speed Cutting Control (T) (G96, G97)

Specifies the circumferential speed (relative speed between the tool and the workpiece) after S. With respect to the tool position change, rotate the spindle at specified circumferential speed all the time.

### Format

constant linear speed control

**G46** X\_ P\_ ; limit spindle speed

**G97** S\_ ; cancel the spindle constant linear speed control

Parameter	Description
P	In G96 command: It specifies the axis for the constant linear speed control. The axis specified by <b>0</b> is determined by the system axis parameter. The values <b>1</b> , <b>2</b> , and <b>3</b> indicate the X, Y and Z axis respectively. In G46 command: It specifies the maximum spindle speed (r/min) limitation when the constant linear speed is defined by G46.
S	Define the constant linear speed in G96 (mm/min or inch/min). The defined spindle speed (r/min) after the constant linear speed is canceled in G97.
X	The minimum spindle speed (r/min) limitation when the constant linear speed is defined.

**G96** P\_ S\_ ; enable the spindle

### Description


which can be canceled by each other.

- G46 is valid only when the constant linear speed function is valid.
- Only when the spindle can automatically change speed (e.g.: servo spindle, frequency spindle), can the constant linear speed function be used.
- During the constant linear speed control, when the spindle speed exceeds the maximum spindle speed, it will be limited at the maximum speed.

- G96/G97 are modal commands

### Attention

G96 must be followed by G46, to limit the maximum and minimum spindle speed.

**Example**

%3318

N1 T0101; Select No. 1 tool and define coordinate system

N2 G00 X40 Z5; Go to the start point

N3 M03 S460; Rotates spindle at 460r/min

N4 G96 P0 S80; The constant linear speed is valid, with the speed of 80m/min).

N5 G46 X400 P900; Limit the spindle speed range: 400-900 r/min

N6 G00 X0; The tool goes to the center, and the spindle speed increases until the maximum speed 900r/min.

N7 G01 Z0 F60; Close to the workpiece

N8 G03 U24 W-24 R15; Conduct machining for the arc of R15

N9 G02 X26 Z-31 R5; Conduct machining for the arc of R5

N10 G01 Z-40; Conduct machining for the outer circle of Φ26

N11 X40 Z5; Back to the tool setting location

N12 G97 S300; Cancel the constant linear speed function, and rotate the spindle at the speed of 300r/min

N13 M30; Stop spindle, end the main program, and reset

## 14.2 C/S Axis Switching Function (CTOS/STOC)

In complex applications, such as rigid tapping function, the spindle need to be used as a rotation axis in addition to a spindle. In this case, the C/S axis switching function is available.

### Format

**STOC/G108 IP;**

**CTOS/G109 IP;**

Parameter	Description
IP	<p>IP can be defined as A/B/C. The number following it indicates the channel spindle number, which ranges from <b>0</b> to <b>3</b>.</p> <p>When <b>IP</b> is not specified after STOC, No. 0 spindle will be switched to the C axis by default.</p> <p>When <b>IP</b> is not specified after CTOS, the C axis will be switched to No.0 spindle by default.</p>

### Attention

1. In the same G code, it is not recommended to frequently use the STOC/CTOS macro commands
2. When the spindle is switched to the C axis, the unit of the C axis is deg/min.
3. It is not allowed to use the random line function to jump among lines between STOC and CTOS, or jump from other line to a line between STOC and CTOS.
4. The random line function does not support the C axis of STOC.

### Example

*%900* Program name

*G54*

*M03S600*

*STOC;* Switch the spindle to the C axis

*G28 C0;* The C axis returns to the origin.

*G1 C45 F2000*

...

*CTOS*; Switch the C axis to the spindle*M03S600**M30***Attention**

M30 cannot restore the status of the C/S axis.

## 14.3 Spindle Synchronization (G116, G117)

During dual spindle synchronization, one spindle is the master axis, and the other is the slave axis. The reference spindle for synchronization is called the master axis, while the axis moves with the master axis is called the slave axis. During polygon machining, the tool axis is the master axis, and the workpiece axis is the slave axis.

**Format****G116 J\_/K\_ P\_/Q\_ R\_;** establish synchronization**G117;** cancel synchronization

Parameter	Description
J	The logical axis number of the master axis.
K	The logical axis number of the slave axis.
P	The rotation speed ration of the master axis, ranging from <b>1</b> to <b>1000</b> .
Q	The rotation speed ration of the slave axis, ranging from <b>-1000</b> to <b>1000</b> and cannot be <b>0</b> . When Q is a positive value, the rotation direction of the slave axis is the same as that of the master axis. When Q is a negative value, the rotation direction of the slave axis is opposite to that of the master axis.
R	Phase angle (0 to 360)

**Example***T0101**G0 X100 Z20**M3 S1000*

*G116 J5 K1 P1 Q2 R0*; Establish synchronization. No.5 logical axis is the master axis and No.1 logical axis is the slave axis.

*G04 X2*

*G01 X20 F100*; Conduct tool feed for cutting

*G0 X100*; Exit the tool

*G117*; Cancel synchronization

*M5*

*M30*

#### **Attention**

1. The spindle synchronization commands (G116/G117) cannot be used with other commands simultaneously in one line.
2. During synchronization, you can not specify the metric conversion commands (G20, G21).
3. The Emergency Stop and Reset command can automatically cancel the synchronization.
4. During synchronization, you cannot control the slave axis with commands. Only the rotational speed and direction of the master axis can be specified. But you may specify movement commands for other axis through the programming.

## 15 Programmable Data Input

---

---

You can dynamically modify system data in the program via programmable data input.

1. Change the origin of the workpiece coordinate system
2. Change the origin of the extended workpiece coordinate system

## 15.1 Programmable Data Input (G10, G11)

You can dynamically modify system data in the program with G10/G11. The modified system data takes effect immediately.

### Format

Function	G Code
G54-G59: the origin of the workpiece coordinate system	G10 L2 Pp IP_
G54.X: the origin of the extended workpiece coordinate system	G10 L20 Pp IP_
System parameter output	G10 L53 PpRr
Cancel user-defined input	G11
Milling tool geometry compensation value H input	G10 L10 PpRr
Milling tool geometry compensation value D input	G10 L12 PpRr
Turning tool compensation value input	G10 L14 Pp X_ Z_ R_ Q_ Y_ J_ K_

### Description

G10 is a modal command, which enables the programmable data input mode until it is canceled by G11.

### G54-G59 origin of the workpiece coordinate system

#### G10 L2 Pp IP\_

Parameter	Description
Pp	Specify the workpiece origin offset in the relative workpiece coordinate systems from 1 to 6: <ul style="list-style-type: none"> <li>1 indicates the G54 workpiece coordinate system</li> <li>2 indicates the G55 workpiece coordinate system</li> <li>3 indicates the G56 workpiece coordinate system</li> <li>4 indicates the G57 workpiece coordinate system</li> <li>5 indicates the G58 workpiece coordinate system</li> <li>6 indicates the G59 workpiece coordinate system</li> </ul>
IP	The workpiece origin offset of each axis for absolute commands. Added to the workpiece origin offset of each axis for incremental commands.

### Example 1

```
%0002
```



*G54*; Initial value of *G54*

*G01X100Y100Z100*

*G10L2P1X100Y100Z50*; Change the origin of the *G54* workpiece coordinate system to (100, 100, 50)

*G11*

*G01X20Y20Z20*; The command value of the machine coordinate system is (120, 120, 70).

*M30*

**G54.X origin of the extended workpiece coordinate system**

**G10 L20 Pp IP\_**

Parameter	Description
Pp	Set the code <b>p</b> for the workpiece coordinate system of the workpiece origin offset: <b>1-60</b> , corresponding to the X value in the <i>G54.X</i> coordinate system.
IP	The workpiece origin offset of each axis for absolute commands. Added to the workpiece origin offset of each axis for incremental commands.

**Example 2**

*%0002*

*G54.1*

*G01X100Y100Z100*

*G10L20P1X100Y100Z50*; Change the origin of the *G54.1* workpiece coordinate system to (100, 100, 50)

*G11*

*G01X20Y20Z20*

*M30*

**Attention**

In the turning system and in the diameter programming mode, the X value specified by *G10* is the radius value.

**System parameter output**

Output the system parameter to the current channel variables specified

by Rr: #0 to #49

### G10 L53 Pp Rr

Parameter	Description
Pp	Index of parameter ID
Rr	Variable address (0 to 49)

### Cancel user-defined input

### G11

### Example 3

Use machine user parameters from **P40** to **P48**

Parameter number **010340** to **010348**

As the parameter P ranges from **500000** to **-500000**, you may use it if the error range is wide.

*G54*

*G01X0Y0Z0*

*G10L53P010340R1*

*G10L53P010341R2*

*G10L53P010342R3*

*G10L53P010343R4*

*G10L53P010344R5*

*G10L53P010345R6*

*G10L53P010346R7*

*G10L53P010347R8*

*G10L53P010348R9*

*G11*

*G01X[#1/1000]Y[#2/1000]Z[#3/1000]*

*G01X[#4/1000]Y[#5/1000]Z[#6/1000]*

*G01X[#7/1000]Y[#8/1000]Z[#9/1000]*

*M30*

**Milling tool geometry compensation value H input****G10 L10 Pp Rr;**

Parameter	Description
Pp	Tool offset number
Rr	Tool compensation data

**Milling tool geometry compensation value D input****G10 L12 Pp Rr;**

Parameter	Description
Pp	Tool offset number
Rr	Tool compensation data

**Turning tool compensation input****G10 L14 Pp X\_ Z\_ R\_ Q\_ Y\_ J\_ K\_;**

Parameter	Description
Pp	Tool offset number
X	Tool compensation data X
Z	Tool compensation data Z
R	Tool nose compensation R
Q	Imaginary too nose direction
Y	Tool compensation data Y
J	Tool radial wear J
K	Tool axial wear K

## **16 Axis Control Functions**

---

---

This chapter includes the following sections:

**16.1 Cycle Function of the Rotation Axis**

**16.2 Reference of the Grating Ruler with Distance-Code**

## 16.1 Cycle Function of the Rotation Axis

### Overview

The rotation axis cycle function can be used to prevent the overflow of the rotation axis coordinate value.

You may enable the rotation axis cycle function by setting relevant parameters.

Take the C axis as an example, you need to set the parameter **AXIS TYPE (104001)** of axis 4 to **3** in the coordinate axis parameters, and set the parameter **FEEDBACK POS CYCLE ENABLED (505014)** of the corresponding device to **1** in the device interface parameters.

### Description

For incremental commands, the movement amount is the command value.

For absolute command, you may set the parameter **R-AXIS SHORT PATH SELECTION EN (104082)** of the corresponding axis to **1** in the coordinate axis parameters, and set the rotation direction of the rotation axis to the direction of the short path from the start point to the end point.

### Example

G90 C0 N1 G90 C-150.0 N2 G90 C540.0 N3 G90 C-620.0 N4 G91 C380.0 N5 G91 C-840.0	Sequence No.	Actual Movement	Absolute Coordinates after Movement
	N1	-150	210
	N2	-30	180
	N3	-80	100
	N4	380	120
	N5	-840	0

### Attention

For some machines with rotation axis (such as working tables), due to the mechanical structure, the rotation axis can rotate only in one direction during movement. In this case, it is not recommended to use the absolute command but the incremental command programming to avoid the opposite direction of rotation caused by programming errors.


## 16.2 Reference of Grating Ruler with Distance-Code

## Overview

Using a linear measuring system with distance-coded reference point symbols, you do not need to install a deceleration switch on the machine for returning to the reference point, and the machine can return to a fixed machine reference point. It makes the operation much faster and easier in the actual use.

## Principle


The principle for the linear measuring system with distance-coded reference point symbols is to adopt a standard linear grid line and a channel with distance-coded reference point symbols which is parallel to the linear grid line. The distance between two reference point symbols in the same group is the same, but the distance between the adjacent reference point symbols of two different groups is variable. Each segment distance plus a fixed value, then the CNC axis can determine the absolute position according to the distance. See the figure below (example: LS486C):



For example, the machine moves from point A to point C through the middle point B. If the system detects 10.02, it will know which reference point the axis is at. Similarly, when the machine moves from point B to point D through the middle point C and the distance from the point C to point D is 10.04, the system will know which reference point the axis is at. Therefore, if the axis moves more than two reference points (20 mm), the system will be able to get the absolute position of the machine.

## Parameter settings

Take the X-axis as an example to illustrate the parameter settings for linear grating ruler with distance code:



### 1. Setting reference returning mode

Set the parameter **REF POINT RETURN MODE (100010)** of the axis 0 in coordinate axis parameters to **4** when the feedback from the distance-code is in the same direction of reference returning; otherwise set it to **5**.

### 2. Setting distance between distance-coded reference points

Set the parameter **DISTANCE CODE REF SPACE(mm) (100018)** of the axis 0 in coordinate axis parameters. This parameter indicates the distance between two adjacent distance-coded reference points in the incremental measuring system. As shown in the figure above, the distance between two distance-coded reference points is set to **20**.

### 3. Setting distance-code offset

Set the parameter **DISTANCE CODE DEVIATION(mm) (100019)** of the axis 0 in coordinate axis parameters. This parameter indicates the incremental interval between distance-coded reference points in the incremental measurement system. As shown in the figure above, it indicates the incremental value **0.02** from **10.02** to **10.04**. Therefore, the distance-code offset is set to **0.02**.

### 4. Setting reference point zero

After the distance code is returned to the zero point, return a defined point to the zero point, and set this point to the machine zero. Then set the coordinate value after the current point is returned to zero for **REF POINT POS(mm) (100017)** of the coordinate axis 0. This point will be used as the machine origin to define coordinate system when you return a point to the zero point next time.

## 17 Other Functions

---

---

This chapter includes the following sections:

**17.1 Stop Read-ahead (G08)**

**17.2 Redefine Rotation Axis Angle Resolution (G115)**

**17.3 Axis Release (G101)**

**17.4 Command Channel Loader (G103) and Running (G103.1)**

**17.5 Channel Synchronization (G104)**

**17.6 Alarms (G110)**



## 17.1 Stop Read -ahead (G08)

---

During program execution, the system stops interpreting the subsequent lines after encountering this command. Only after the previously interpreted commands are completed, the system proceeds to interpret. This command is also used for real-time coordinate reading and state judgment.

### Format

**G08** ; specify this command in a separate program line.

### Example

*%0003*

*G54*

*G01 X10 Y10 Z10*

*G08*; stop interpretation

*G01 X100Y100Z100*

*G01 X30*

*M30*

## 17.2 Redefine Rotary Axis Angle Resolution (G115)

### Format

G115 IP\_

Parameter	Description
IP	Set the reciprocal value for the rotary axis resolution. When it is set to <b>0</b> , the system restores the default angle resolution. It must be greater than <b>0</b> .

### Description

Modify the rotary axis resolution. The default value is **1/100000** degree. There should be greater angle increments in one instruction during rigid tapping. Therefore, you need to decrease the angle resolution to an appropriate degree, to make sure that the equivalent length will not exceed the limit.

### Attention

1. This command must be specified in a separate row.
2. One command can be used to modify only one rotary axis instruction.
3. The specified axis must be a rotary axis.
4. The newly defined angle resolution must be divisible by the standard one.

### Example

*%I234*

*STOC*

*G54*

*G90 C0*

*G115 C 1000*; change the C axis resolution to 1/1000 degree.

*G01 C3000*

*G115 C0*; restore the C axis resolution to the default 1/100000 degree.

*CTOS*

## 17.3 Axis Release (G101) and Axis Obtaining (G102)

### Format

#### G101 IP\_

Parameter	Description
IP	Set the axis to be released. Options: X/Y/Z/A/B/C/U/V/W/S0/S1/S2/S3

#### G102 IP\_

Parameter	Description
IP	Set the axis to be obtained. Options: X/Y/Z/A/B/C/U/V/W/S0/S1/S2/S3

### Description

G101 is used to release the axis by the channel. The address word following G101 can be any numbers, but it is recommended to specify it as 0.

G102 is used to obtain the axis by the channel. The address word following G102 must be a logical axis number.

### Attention

1. Generally, the same logical axis can belong to only one channel at the same time.
2. After a channel obtains an axis, you need to set the G5X origin of the axis. If it cannot be specified on the settings interface, you may use G10 to specify it.
3. Axis release or obtaining cannot be executed during axis movement.

**Example**

How is drilling executed in the X/Y axis direction on the milling machines? In the example as below, assuming that in the channel configuration, the logical axis number of the X axis is **0**, the logical axis number of the Y axis is **1**, and the logical axis number of the Z axis is **2**:

*%1111*

*G54*

*G101 Y0 Z0*; Release the Y axis and Z axis

*G102 Y2 Z1*; Exchange the logical axis numbers of the Y axis and Z axis

Start drilling:

*G0X0Y0Z60*

*M3S700*

*G99G73X20Y25R5P2Q-3K2Z-32F80*

*G0X0Y0Z60*

*M30*

## 17.4 Command Channel Loader (G1030) and Running (G103.1)

### Format

**G103** P="*program name*" Q={*channel number*,...}

Parameter	Description
P	The name of the program to be loaded.
Q	The number of the channel where the program will be loaded. Separate multiple channels with a comma symbol (,).

**G103.1** Q={*channel number*,...}

Parameter	Description
Q	The number of the channel where the program will run. Separate multiple channels with a comma symbol (,).

### Description

When G103.1 is executed, the channel where the program will be loaded must be in the auto mode.

When G103 is executed, the channel where the program will be loaded should not have selection programs.

These two commands are generally used for multi-channels.

### Example

Assuming that there is a dual-channel machine, channel 1 makes channel 2 load and run program O01.

*%1*

*N1 G54*

*N2 G103 P="O01" Q={2}*

*N3 G103.1 Q={2}*

*.....;*

*M30*

When channel 1 completes the line N3, channel 2 starts to run O01.

## 17.5 Channel Synchronization (G104)

### Format

**G104 P\_ Q={*channel number*,}**

Parameter	Description
Q	The number of the channel to be synchronized. Separate multiple channels with a comma symbol (,).
P	Signal value, ranging from <b>0</b> to <b>40</b> .

### Description

G104 is generally used for the process synchronization of multiple channels.

### Example

Assuming there is a dual-channel milling machine, and the X axis is the public axis, with the following configuration:

	Logical Axis No. of Channel 0	Logical Axis No. of Channel 1
X axis	0	---
Y axis	1	3
Z axis	2	4

Programs of Channel 1	Programs of Channel 2
%1 N1G54X0Y0Z0 N2G02X10Y10R20 N3G1X0Y0Z0 N4G101 X0; release X axis N5G104 P1 Q={1,2}; synchronization statement 1 N6G104 P2 Q={1,2}; synchronization statement 2 N7G102 X0 N8G0X100 N9M30	%2 N1G104 P1 Q={1,2}; synchronization statement 1 N2G102 X0; obtain X axis N3G54X0Y0Z0 N4G02X10Y10R20 N5G0X0Y0Z0 N6G101 X0; release X axis N7G104 P2 Q={1,2}; synchronization statement 2 N8M30

As listed in the table above, channel 1 and 2 load their own programs

and start the cycle.

1. Channel 1 executes N1 to N4, and channel 2 waits at N1.
2. Channel 1 executes N5, and channel 2 can execute downward.
3. Channel 1 waits at N6, and channel 2 executes N2 to N6.
4. Channel 2 executes N7, and channel 1 can execute downward.
5. Channel 2 executes N8, and channel 1 proceeds to execute N7 to N9.

## 17.6 Alarms (G110)

### Format

G110 P\_

Parameter	Description
P	Alarm code, which must be a negative value.

### Attention

User-defined alarm codes: **-8000** to **-9999**

You may write alarm information as required, which will be saved in **USR\_SYNTAX.TXT** (all uppercase). The format is as below:

-8000 milling cycle: The tool is not defined.

-8001 milling cycle: The reference plane is not defined.

.....

.....

Write the following statement in the G codes:

G110 P-8000; when the system executes this line, an alarm indicating the tool is not defined will be reported.



